



**Manifestación de Impacto Ambiental en la  
modalidad regional (MIA-R): “Proyecto  
Integral de Extracción Ichalkil-Pokoch”**

**ANEXO A**

**Información adicional**

## ***ANEXO A***

### ***Información Adicional***

## TABLA DE CONTENIDO

a.	<i>El REGULADO deberá ingresar a esta AGENCIA, la publicación del extracto del PROYECTO, la cual deberá hacerse en un diario de amplia circulación, conforme a lo establecido en el artículo 34 párrafo tercero fracción I de la Ley General del Equilibrio y la Protección al Ambiente (LGEEPA).....</i>	1
b.	<i>Ingresar la información específica de los dos pozos delimitadores con los que pretende iniciar actividades en los polígonos Pokoch e Ichalkil. Dicha información consiste entre otra, en el nombre de los pozos delimitadores, características, ubicación mediante coordenadas geográficas o UTM (especificando zona y datum), presiones y caudales esperados (BPD y MMPCD).....</i>	2
c.	<i>Definir la cantidad de pozos a perforar para la etapa de explotación de los Campos Ichalkil y Pokoch, debiendo ser consistente con la información incluida en la MIA-R.....</i>	3
d.	<i>Señalar el criterio mediante el cual delimitó el SAR del PROYECTO.....</i>	4
e.	<i>Señalar cuales fueron los daños ambientales identificados en la LBA, con la finalidad de tener un diagnóstico completo del SAR.....</i>	6
1.1.	<i>Registro y descripción de daños ambientales .....</i>	6
1.1.1	<i>Identificación de los daños ambientales .....</i>	6
1.1.2	<i>Valor del daño ambiental .....</i>	7
1.1.3	<i>Descripción de los daños ambientales .....</i>	10
1.1.4	<i>Conclusiones.....</i>	19
1.2.	<i>Registro y descripción de daños preexistentes (pasivos ambientales) .....</i>	20
1.2.1	<i>Infraestructura petrolera existente .....</i>	20
1.2.2	<i>Inspección de la infraestructura petrolera existente .....</i>	23
1.2.3	<i>Información de las condiciones ambientales históricas .....</i>	26
1.2.4	<i>Resultados de la presente evaluación ambiental .....</i>	28
1.2.5	<i>Conclusión.....</i>	30
f.	<i>El REGULADO deberá justificar técnicamente el por qué únicamente tomó un escenario calificado como Riesgo Medio para la simulación del análisis de consecuencias y no en la totalidad de los escenarios identificados como Riesgo Medio (5 escenarios para el nodo 1 y 4 escenarios para el nodo 2); en su caso actualizar el análisis de consecuencias.....</i>	32
g.	<i>REGULADO deberá realizar la justificación técnica de suponer un derrame de 6,259 BPD y porque se acotó la duración del derrame a 15 días. Lo anterior deberá ser sustentado y/o ajustado con la finalidad de tener la certeza que se está simulando el Peor Escenario sin subestimar o sobreestimar el riesgo en caso de derrame de hidrocarburo. ....</i>	35
h.	<i>El REGULADO deberá ingresar información de soporte respecto al uso del modelo tridimensional GEMS y COSIM, con la finalidad de evidenciar los datos que se ingresaron a dichos modelos de simulación y los resultados obtenidos para los mismos /memoria numérica.....</i>	38
i.	<i>El REGULADO deberá ingresar planos a escala adecuada donde se observen los sitios probables de deposición de crudo en la costa en tres temporadas climáticas del año distintas (secas, frentes fríos y lluvias). Aunado a lo anterior, deberá realizar el análisis y discusión de las posibles sitios vulnerables a impactar (arrecifes de coral, áreas naturales protegidas, vegetación de manglar, entre otros). ....</i>	40
j.	<i>El REGULADO deberá realizar el análisis de consecuencias de la dispersión de los gases inflamables, la evaluación de la radiación térmica derivada de posibles eventos de dardo de fuego (jet fire),</i>	

*churco de fuego (pool fire) así como la sobrepresión debido a la posibilidad de una explosión, identificando en cada uno de estos las zonas de alto riesgo y amortiguamiento.....* 48

k. *El REGULADO deberá identificar y proponer medidas de contención y mitigación específicas para el escenario de derrame de hidrocarburo en el agua, considerando los parámetros de dispersión y las simulaciones de derrames realizadas.....* 50

a.

*El REGULADO deberá ingresar a esta AGENCIA, la publicación del extracto del PROYECTO, la cual deberá hacerse en un diario de amplia circulación, conforme a lo establecido en el artículo 34 párrafo tercero fracción I de la Ley General del Equilibrio y la Protección al Ambiente (LGEPA).*

La publicación del extracto del proyecto se realizó el día 7 de octubre de 2016, en la editorial Campeche Hoy. Se anexa publicación original en el Anexo 1.

**campechehoy.mx** 7 de Octubre de 2016 | LA ISLA | 5

# Protexa provoca caos vehicular

LA EMPRESA PROPIEDAD DE LA FAMILIA LOBO MORALES, SE APROPIÓ DE LAS CALLES Y PUSO A SERVICIO A LAS CORPORACIONES POLICIAZAS.

**CD. DEL CARMEN**  
AGUSTÍN FERRER  
CAMPECHE HOY

**P**anador "bifásico" gas y aceite, de la carretera Carmen Puerto Real al Puerto Industrial, la petrolera Protexa dispuso de un madero operativo que incluyó a trabajadores de la Comisión Federal de Electricidad (CFE) y la policía municipal.

Deteniendo el tráfico pasada la medianoche de ayer, y usando como medio de transporte a la compañía Acción Logística Integral (ALI), Protexa transportó con lentitud dicho tanque.

Quienes arribaban a la ciudad debían esperar los lentes movimientos que hacia la compañía ALI, contratada para trasladar el tanque propiedad de Protexa.

Bajaban y subían las cuchillas de los postes de la CFE cuando la altura del tanque pegaba en líneas de alta tensión, que por segundos provocaba la suspensión de energía eléctrica.

El amplio convoy era custodiado por dos patrullas enviadas por el titular de la corporación Jonny Alberto Morales León, que prefirió atender el tráfico que ocasionó Protexa que cuidar a la población.

Una mujer policía corría de un lado a otro auxiliando en la vialidad, todo para obedecer las indicaciones de su "jefe".

Protexa para evitar que resultara involucrada en estas peligrosas maniobras, tapó los logos de sus unidades pesadas.

Sin embargo, las decenas de obreros que custodiaron la pesada carga, tratan overoles de la compañía regiomontana.

**Jorge Fuerte irresponsable**

**CD. DEL CARMEN**  
AGUSTÍN FERRER  
CAMPECHE HOY

Rectificando que Jorge Fuerte Mancera es el titular del Colegio Gardner, algunos habitantes del fraccionamiento Héroes de Nacozari, pidieron al funcionario educativo que se disculpe con la comunidad, por atentar contra el medio ambiente.

Después de que hace dos días, Jorge Fuerte –aunque ayer por una omisión se dijo que su nombre era René– introdujo su lujoso carro a un predio que es conservado por vecinos, estos pidieron que el director del colegio explique su mal proceder.

**DOBLE MORAL**



Jorge Fuerte Mancera, director del Gardner debe pedir una disculpa pública a la comunidad

**AVISO DE EVALUACIÓN DE IMPACTO AMBIENTAL**

Con la finalidad de garantizar el derecho a la información y de la participación ciudadana y en cumplimiento al Artículo 34 párrafo 3º, fracción I de la Ley General del Equilibrio Ecológico y Protección al Ambiente, FIELDWOOD ENERGY, informa acerca de la siguiente obra, que se pretende realizar en la provincia petrolera Cuenca del Sureste y cuya Manifestación de Impacto Ambiental en Modalidad Regional (MIA R), se encuentra en procedimiento de evaluación por parte de la Agencia de Seguridad Energía y Ambiente (ASEA). Nombre de la persona moral responsable del Proyecto:

**FIELDWOOD ENERGY ESP MÉXICO, S. DE R.L. DE C.V.**

Nombre y descripción del proyecto:

El "Proyecto Integral de Extracción Ichábil-Pokoch" fue asignado mediante contrato CNI-R01-L02-A4/2015 y consiste en evaluar el potencial petrolero de los Campos Ichábil y Pokoch. El proyecto comprende la perforación de pozos, la instalación de plataformas de explotación de diferentes tipos y dimensiones, así como la instalación de ductos para el transporte de la producción. El Proyecto se divide contractualmente en dos Etapas: La Etapa de Evaluación con una duración de 2 años en la cual se perforan dos pozos y se reevalúa la información existente de los campos y la Etapa de Desarrollo inicia en enero de 2018 y termina en enero de 2041.

**Ubicación y referencias a los ecosistemas existentes y su condición al momento del estudio:**

El Proyecto se llevará a cabo en la provincia petrolera Cuenca del Sureste, con un área de 58 km<sup>2</sup>, ubicados frente a las costas del estado de Campeche en la Zona Económica Exclusiva (ZEE) del Golfo de México, a una distancia aproximada de 40 km de las costas, partiendo del vértice más cercano en línea recta a costa que corresponde al campo Ichábil. Debido a la extensión del área de estudio, la misma cuenta con muchas especies de flora y fauna, desde plantas hasta mamíferos marinos, pasando por comunidades benthicas, corales puros y tortugas marinas. El desarrollo del Proyecto se prevé que no altere a la calidad de los puertos de Dos Bocas o Isla del Carmen, ya que las actividades actuales en los mismos hacen que los buques del proyecto realicen operaciones adicionales marginales.

**Principales efectos ambientales que se pueden generar y sus medidas de mitigación:**

De acuerdo a la evaluación descrita en la MIA R, debido a las características del "Proyecto Integral de Extracción Ichábil-Pokoch", no se generarán impactos directos, acumulativos, sínérgicos o residuales significativos en el entorno físico y biológico. Adicionalmente, se considerarán beneficios económicos favorables al país por la posible apertura del sector de hidrocarburos en sus aguas del Golfo de México, ya que se genera la posibilidad de crear nuevos empleos lo cual ayudará a mejorar las condiciones de la población, así como generar nuevas oportunidades de desarrollo en los diferentes aspectos. A pesar de que de en ninguna etapa del Proyecto se esperan impactos moderados o significativos, se tendrán medidas de manejo ambiental, orientadas a prevenir, mitigar y compensar la huella ecológica del Proyecto, tales como: medidas de conservación de la calidad del aire, medidas para el control de ruido y manejo de residuos sólidos y líquidos.



El tanque que sería llevado al Puerto Industrial provocó caos en el tránsito, sin embargo, fue custodiado por la policía municipal.



Se volvió lento el tráfico vehicular sobre la Isla de Trío, y todos debían esperar que se movieran las unidades al servicio de Protexa.

b.

Ingresar la información específica de los dos pozos delimitadores con los que pretende iniciar actividades en los polígonos Pokoch e Ichalkil. Dicha información consiste entre otra, en el nombre de los pozos delimitadores, características, ubicación mediante coordenadas geográficas o UTM (especificando zona y datum), presiones y caudales esperados (BPD y MMPCD).

En la Tabla 1, se resume información referente a los dos pozos delimitadores, incluido el tipo, las coordenadas superiores y objetivo, la formación geológica objetivo, que dado su ubicación puede ser Jurásico SK o Cretácico Medio, presión de fondo de pozo y caudales esperados tanto de crudo como de gas.

**Tabla 1** *Información relativa a los pozos delimitadores*

Pozos de evaluación	Tipo	Coord Sup (x,y)	Coord Obj (x,y)	Pruebas	Form. Obj	Prof (m vbnm)	PWF (psi)	Qo esperado BPD	Qg esperado MMPCD
Pokoch 1DL		Coordinadas protegidas articulo 113 fraccion I de la LGTAIP y 110 fraccion I de la LFTAIP				4650	1750	1900	2.81
						5400	6700	1300	2.66
Ichalkil 2DL						5300	4500	1500	2.08
						4780	4200	1300	0.71

**Fuente:** Documento del Plan de Evaluación aprobado por la CNH del Área contractual 4 Campos Ichalkil y Pokoch.

**Notas:** Coord Sup = Coordenada Superficie; Coord Obj = Coordenada Objetivo; Form. Obj = Formación Objetivo; mvbnm = Metros Verticales Bajo Nivel del Mar; PWF = Presión de Fondo Fluyendo de Pozo; psi = Libras sobre Pulgada Cuadrada; Qo = Gasto de Aceite; BPD = Barriles por Día; Qg = Gasto de Gas; MMPCD = Millones de Pies Cúbicos por Día.

c. *Definir la cantidad de pozos a perforar para la etapa de explotación de los Campos Ichalkil y Pokoch, debiendo ser consistente con la información incluida en la MIA-R.*

La estimación actual es perforar **24 pozos** para la explotación de los campos, incluyendo los dos pozos del Período de Evaluación, con la siguiente distribución:

- **19 pozos** en el campo Ichalkil y
- Un máximo de **5 pozos** en el campo Pokoch.

d.

*Señalar el criterio mediante el cual delimitó el SAR del PROYECTO.*

Como se mencionó en el Capítulo 4 de la MIA Regional del proyecto denominado “Proyecto Integral de Extracción Ichalkil-Pokoch” entregado a la ASEA el 03 de octubre de 2016, dado que el SAR de un Proyecto es importante como un marco de referencia en el cual se analiza y evalúa el desempeño ambiental a través de sus distintas etapas, en particular de las formas en que puede incidir sobre los distintos factores que lo componen, y considerando que el sistema se define como “el espacio finito definido con base en las interacciones entre los medios abiótico, biótico y socioeconómico de la región donde se pretende establecer el proyecto, generalmente formado por uno o varios ecosistemas, y dentro del cual se aplicará un análisis para determinar los impactos, restricciones y potenciales medidas ambientales y de aprovechamiento”, se realizó la delimitación del SAR con base en los siguientes criterios:


- Que los impactos ambientales se producen por la alteración de las estructuras y de los procesos ecológicos, económicos o sociales de un ambiente determinado;
- Que se consideraron aquellas áreas que pudieran ser afectadas fuera del sitio del Proyecto, y pudieran sufrir impactos ambientales por el desarrollo del mismo.

Considerando la delimitación establecida por el Programa de Ordenamiento Ecológico Marino y Regional del Golfo de México y Mar Caribe (POEMRGFMC) publicado en el DOF el 24 de noviembre de 2012, así como con base en la homogeneidad de la batimetría, el Sistema Ambiental Regional está enmarcado por la:

- Unidad de Gestión Ambiental (UGA 188) - el Proyecto se encuentra inmerso dentro de este UGA, y comprende los límites sur, norte, este y oeste del SAR;

La superficie ocupada por el SAR es de 561,496.675 Ha y es compatible con la realización de actividades del sector hidrocarburos. La Figura 1 muestra el SAR del Proyecto.

**Figura 1** Delimitación del SAR del Proyecto - UGA 188.



Fuente: ERM, 2016

e. Señalar cuales fueron las daños ambientales identificados en la LBA, con la finalidad de tener un diagnóstico completo del SAR.

## 1.1. Registro y descripción de daños ambientales

En esta sección se presentan los componentes y factores ambientales que han sido identificados como afectados por alguna actividad antropogénica pasada o presente, haciendo énfasis en los derivados de la industria de petróleo y gas.

### 1.1.1 Identificación de los daños ambientales

Los daños ambientales se han dividido de acuerdo a la causa que originó esas afectaciones, y posteriormente se catalogaron de acuerdo al factor que están alterando. Se identificaron cinco causas principales de daños ambientales, las cuales son:

1. Descarga de aguas continentales,
2. Industria petrolera: actividades relacionadas directamente con la industria hidrocarburífera sin incluir actividades de investigación,
3. Actividades antropogénicas: son aquellas que pueden o no estar derivadas de la industria petrolera,
4. Presencia de desechos marinos, y
5. Sobreexplotación de los recursos pesqueros.

Los factores alterados que se identificaron fueron los siguientes:

#### Medio abiótico:

- Columna de agua,
- Sedimentos.

#### Medio biótico:

- Fitoplancton,
- Macrobenitos,
- Ictiofauna,
- Mamíferos marinos, y
- Tortugas marinas.

### 1.1.2

#### *Valor del daño ambiental*

Habiendo identificado los daños o impactos ambientales se valorizó cada uno de ellos de acuerdo a su magnitud e incidencia.

La magnitud será la cantidad y calidad del factor modificado en relación con el área de estudio.

La incidencia se refiere a la severidad, la cual es el grado y forma de la alteración; la cual está definida por la intensidad y por una serie de atributos de tipo cualitativo que caracterizan dicha alteración.

El signo del efecto alude al carácter beneficioso (expresado como +), perjudicial (expresado como -) o difícil de calificar sin mayores estudios (expresado como x), de cada una de las acciones que van a actuar sobre los distintos factores considerados.

- Intensidad (It), grado de incidencia de la alteración.
- Extensión o escala (Ex), área de influencia del efecto en relación con el entorno considerado.
- Inmediatez (In), dependencia directa de una acción o indirecta a través de un efecto.
- Acumulación (Ac), incremento continuo de la gravedad cuando se prolonga la acción que lo genera.
- Sinergia (Si), reforzamiento de efectos simples, se produce cuando la coexistencia de varios efectos simples produce un efecto superior a su suma simple.
- Momento (Mo), lapso de tiempo que transcurre entre la acción y la aparición del efecto.
- Persistencia (Pe), tiempo de permanencia del efecto.
- Regularidad (Rg), manifestación de forma regular, predecible, por tanto, o impredecible.
- Reversibilidad (Re) o posibilidad de ser asimilado por el medio, de tal manera que éste, por sí solo, es capaz de recuperar las condiciones iniciales una vez producido el efecto.
- Recuperabilidad (Rc), posibilidad de recuperación mediante intervención externa
- Continuidad (Co), manifestación de forma constante en el tiempo.
- Periodicidad (Pr), manifestación de forma cíclica o recurrente en el tiempo.

Para determinar el índice de incidencia primero se caracterizan los atributos de manera formal, asignando un código o valor numérico a cada atributo, acotado entre un valor máximo para la más desfavorable (3) y uno mínimo para la más favorable (1), tal como se observa en la Tabla 2.

La expresión de incidencia consiste en la suma ponderada de los códigos de cada atributo, considerando la siguiente expresión:

$$\text{Incidencia (I)} = \text{It} + \text{Ex} + \text{In} + \text{Ac} + \text{Si} + \text{Mo} + \text{Pe} + \text{Rg} + \text{Re} + \text{Rc} + \text{Co} + \text{Pr}$$

En la Tabla 2 se asigna el código (valor) a cada atributo de los daños ambientales:

**Tabla 2** *Determinación de códigos de atributos de daños ambientales*

Atributo	Características de los atributos	Código
Signo del efecto	Benéfico	+
	Perjudicial	-
	Difícil de calificar sin estudiar	x
Intensidad (It)	Baja	1
	Media	2
	Alta	3
Extensión (Ex)	Puntual	1
	Parcial	2
	Extenso	3
Inmediatez (In)	Indirecto	1
	Directo	3
Acumulación (Ac)	Simple	1
	Acumulativo	3
Sinergia (Si)	Leve	1
	Media	2
	Fuerte	3
Momento (Mo)	Largo plazo	1
	Medio	2
	Corto	3
Persistencia (Pe)	Temporal	1
	Permanente	3
Regularidad (Rg)	Regular	1
	Predecible	2
	Impredecible	3
Reversibilidad (Re)	A corto plazo	1
	A medio plazo	2
	A largo plazo o no reversible	3
Recuperabilidad (Ro)	Fácil	1
	Media	2
	Difícil	3
Continuidad (Co)	Discontinuo	1
	Continuo	3
Periodicidad (Pr)	Irregular	1
	Periódico	3

Fuente: ASEA 2015.

Posterior a la valoración de los atributos, se calcula el índice de incidencia, estandarizando la misma en un rango de 0 a 1, utilizando la siguiente expresión:

$$\text{Índice de Incidencia} = (\text{I} - \text{I}_{\text{mínima}}) / (\text{I}_{\text{máxima}} - \text{I}_{\text{mínima}})$$

Siendo:

$I$  = El valor de la incidencia obtenido por un impacto o daño

$I_{\text{máxima}}$  = El valor de la expresión en el caso de que los atributos se manifestarán con el mayor valor.

$I_{\text{mínima}}$  = El valor de la expresión en el caso de que los atributos se manifestarán con el menor valor.

La evaluación de daños ambientales culmina con la asignación de categorías, de acuerdo a la significancia que estos representen para los factores ambientales, previos a la valoración cualitativa de cada atributo (ver Tabla 3).

**Tabla 3** *Categoría de significancia de daños ambientales*

Categoría	Interpretación	Intervalo de valores	
No relevante	Alteraciones de muy bajo impacto a componentes y factores que no comprometen la integridad de los mismos.	Menor a	0.34
Moderadamente relevante	Se afectan componentes y factores sin poner en riesgo los procesos o estructuras de los ecosistemas de los que forman parte.	0.34	0.66
Relevante	Se pueden generar alteraciones en los componentes y factores que afectaron el funcionamiento o estructura de los ecosistemas.	Mayor a	0.66

Fuente: ASEA 2015.

Habiendo establecido lo anterior se construyó la matriz donde se presentan los resultados de la valorización de los impactos ambientales (ver *Tabla* ). Cada daño está relacionado a un código el cual fue construido utilizando las primeras letras de cada origen del daño, seguido por el componente al que afecta y factor; lo anterior con el fin de ubicarlo en la matriz y en la descripción.

Ejemplo:

Daño ambiental: ACD Disminución en la calidad del agua como consecuencia de la descarga de aguas continentales

A= Abiótico

C= Columna de agua

D= Descarga de aguas continentales

1.1.3

*Descripción de los daños ambientales*

De acuerdo al origen, al daño y a la categoría del impacto se presenta a continuación la descripción de aquellos daños que resultaron con categoría Moderadamente Relevante (ver Tabla 4 y Figura 2).

**Tabla 4 Cálculo del índice de incidencia y categorización de los daños ambientales en el Área Contractual 4**

Origen del daño	Factor	Código	Daño ambiental						Categoría							
			Columna de agua	ACD	Disminución en la calidad del agua como consecuencia de la descarga de aguas continentales	-	1	1	1	2	3	18	0.33	No relevante		
Descarga de aguas continentales	Fitoplancton	FFD	Variaciones en la abundancia de poblaciones de fitopláncton en la línea costera por descargas de aguas continentales	-	1	1	1	2	1	1	3	1	1	16	0.17	No relevante
	Bentos	FBD	Variaciones en la población de bentos por descargas de aguas continentales	-	1	1	1	2	1	1	2	1	3	17	0.29	No relevante
	Ictiofauna	FBD	Variaciones en las poblaciones de ictiofauna por descargas de aguas continentales	-	1	1	1	2	1	1	2	1	3	17	0.29	No relevante
	Emanaciones naturales de hidrocarburos	ACC	Disminución en la calidad de agua de mar derivado de las emanaciones naturales de hidrocarburos (chapopoteras)	-	1	1	1	2	1	1	2	1	3	17	0.29	No relevante
Sedimentos	SCC	Contaminación de los sedimentos por emanaciones naturales de hidrocarburos (chapopoteras)	-	1	1	1	2	1	1	1	3	3	17	0.29	No relevante	

Origen del daño	Factor	Código	Daño ambiental	Categoría												
				Indice	Periodicidad	Continuidad	Recurrida	Reversibilidad	Molmetro	Dimergia	Accumulación	Immediatuz	Extensión	Intensidad		
	Bentos	FBC	Variaciones en la población de bentos por emanaciones naturales de hidrocarburos (chapopoteras)	-	1	1	1	1	1	1	1	17	0.29			
	Ictiofauna	FBC	Variaciones en las poblaciones de ictiofauna por emanaciones naturales de hidrocarburos (chapopoteras)	-	1	1	1	1	1	1	1	17	0.29			
	Columna de agua	ACP	Disminución en la calidad de agua de mar derivado de la industria petrolera	-	2	2	3	2	1	2	3	2	1	3	26	0.53
	Sedimentos	SCP	Contaminación de los sedimentos por actividades petroleras	-	2	2	3	3	2	3	3	2	1	1	26	0.63
Industria petrolera	Fitoplankton	FFP	Variaciones en la abundancia de poblaciones de fitoplancton por actividades petroleras	-	1	2	1	2	1	1	3	1	1	1	17	0.21
	Aves	FAP	Interferencia en la migración de las aves por infraestructura petrolera	-	1	1	1	1	1	1	3	2	1	1	17	0.21
	Ictiofauna	PEP	Variaciones en las poblaciones de ictiofauna por actividades petroleras	-	2	2	3	1	1	1	2	2	1	1	19	0.29
Actividades antropogénicas	Columna de agua	ACA	Disminución en la calidad del agua de mar por el vertido de lastre	-	2	2	3	3	2	2	3	2	1	3	27	0.63

Origen del daño	Factor	Código	Daño ambiental	Categoría							
				Indice	Periodicidad	Continuidad	Recuperabilidad	Reversibilidad	Movimiento	Acumulación	Sinergia
	Ictioplancton	FIA	Mortalidad de organismos de ictioplancton por el tráfico marítimo	-	1	1	2	2	1	3	1
	Tortugas marinas	FRA	Cambio en la distribución espacial de tortugas marinas derivado del tráfico marítimo, pesca ilegal e incidental.	-	1	1	3	1	1	1	1
	Sedimento	SCA	Re-suspensión de sedimentos por actividades antropogénicas	-	2	2	1	2	2	1	1
	Fitopláncton	FFA	Variaciones en la abundancia de poblaciones de fitopláncton por el movimiento sedimento	-	1	1	1	2	2	1	3
	Zoopláncton	FZA	Variaciones en la abundancia de poblaciones de zooplancton por actividades antropogénicas	-	1	1	1	2	1	1	3
	Ictiofauna	FNA	Cambio en la distribución espacial de la ictiofauna por el aumento de ruido derivado de actividades antropogénicas	-	1	2	1	3	2	1	1
	Mamíferos marinos	FMA	Cambio en la distribución espacial de los mamíferos marinos por el aumento de ruido derivado de actividades antropogénicas	-	2	2	3	1	2	1	2

Origen del daño	Factor	Código	Daño ambiental	Categoría															
				Intensidad (+/-)	Extensión	Acumulación	Interacción	Simergia	Molmetro	Resistencia	Regulación	Reversibilidad	Recuperabilidad	Continuidad	Periodicidad	Incidencia	Índice		
	Mamíferos marinos	MMA	Cambio en el comportamiento de los mamíferos marinos por el aumento de ruido derivado de actividades antropogénicas	-	1	1	3	1	1	1	1	1	1	3	3	18	0.33	No relevante	
	Tortugas marinas	RTA	Cambio en el comportamiento de las tortugas marinas por el aumento de ruido derivado de actividades antropogénicas	-	1	1	3	1	1	1	1	1	1	3	3	18	0.33	No relevante	
Desechos marinos	Tortugas marinas	FTB	Mortalidad de tortugas marinas por ingestión de desechos marinos	-	2	1	3	1	1	2	2	3	1	1	2	1	20	0.33	No relevante
	Ictiofauna	FNB	Mortalidad de la ictiofauna por ingestión de desechos marinos	-	1	1	3	1	1	2	2	3	1	1	2	1	19	0.29	No relevante
Sobreexplotación del recurso pesquero	Ictiofauna y crustáceos	FNE	Variaciones en las poblaciones de ictiofauna y crustáceos por sobreexplotación del recurso pesquero	-	1	1	1	1	1	1	1	3	1	1	1	1	14	0.14	No relevante

Fuente: ERM 2016




Figura 2 Mapa de daños ambientales identificados en el Área Contractual 4

### 1.1.3.1

#### *Daños ambientales y sociales originados por la industria petrolera*

- Las actividades petroleras como la exploración, explotación, desarrollo, refinación y petroquímica, así como los accidentes derivados de estas, provocan la presencia de sustancias como HAPs, BTEX, COV o HC, las cuales contaminan la columna de agua y son tóxicos para los organismos que viven en ella (Villanueva S. y Botello A., 1992).
- Adicionalmente a la infraestructura en tierra, PEMEX en la Manifestación de Impacto Ambiental, Modalidad Regional “Proyecto Integral Crudo Ligero Marino Fase 3” determinó que en el área del Proyecto Integral CLM-F3 (localizado en el Área Contractual 4 y zonas aledañas) hay presencia de sustancias contaminantes, como plaguicidas, metales pesados, hidrocarburos y metales traza.

No obstante, no se reportaron niveles detectables de HAPs o BTEX en las muestras analizadas; sin embargo, se registró en dos muestras colectadas en el campo Pokoch presencia de HTP-FM y FP excediendo los criterios de la UNESCO. Por lo que los efectos relacionados fueron clasificados entre moderadamente relevantes a no relevantes.

#### Afectaciones particulares:

#### *ACP Disminución en la calidad de agua de mar derivado de la industria petrolera*

La infraestructura antes descrita y las actividades que se llevan a cabo en ella contribuyen a la contaminación del agua de mar afectando negativamente la flora y fauna que habitan en esa zona. Sin embargo, en los muestreos realizados dentro del Área Contractual 4, específicamente en el campo Pokoch, solo se detectó la presencia de hidrocarburos de Fracción Media y Pesada en dos puntos, y en concentraciones que exceden el criterio de la UNESCO. Con relación a la presencia de metales pesados, únicamente se registró hierro, excediendo el criterio de comparación SQuRTs de la NOAA, además de detectarse la presencia de metales como el zinc, cromo, vanadio y bario; estos últimos sin exceder ningún criterio internacional de comparación. La presencia de hidrocarburos (FP y FM), así como de los metales mencionados, evidenciaría orígenes antrópicos del daño y posiblemente parte de este habría sido generado por la industria petrolera, dada la naturaleza de los contaminantes y la relación que tienen con sus actividades. Este efecto es, por tanto,

caracterizado como moderadamente relevante para el medio abiótico (físico-químico).

#### ***SCP Contaminación de los sedimentos marinos por actividades petroleras***

Los resultados de las muestras de sedimento obtenidas en el Área Contractual 4 no mostraron HAP y sólo una muestra resultó impactada con HTP-FP, la cual pertenece al campo Ichalkil. Para el resto de las muestras no hubo detecciones por arriba de los límites de cuantificación del laboratorio. Por el contrario, algunos metales presentaron excedencias, tales como el cadmio, níquel y bario, los cuales superaron los criterios establecidos en la SQuRTs de la NOAA tanto para Pokoch como para Ichalkil. La dinámica de las corrientes marinas en esta región así como la remoción rápida y permanente de los contaminantes en el sedimento fueron aspectos considerados para la valorización de los atributos usados para este daño, otorgándole la categoría de moderadamente relevante. Cabe señalar que, de acuerdo a la modelación de corrientes realizada para esta línea base, se registró un comportamiento primordialmente redundante sin corrientes hacia la costa y con mayoría de periodos en el año donde las corrientes se encuentran en dirección hacia el noreste. Esto favorece la incorporación de los contaminantes provenientes del río hacia el Golfo, extendiendo la pluma de descarga de los mismos y, por ende, el arrastre de sus contaminantes.

##### **1.1.3.2**

#### ***Daños ambientales y sociales derivados de actividades antropogénicas***

##### ***ACA Disminución en la calidad del agua de mar por el vertido de agua de lastre***

Coatzacoalcos es uno de los puertos y rutas petroleras más importantes del país por lo que se produce una gran cantidad tráfico de embarcaciones mayores. Estas embarcaciones liberan lastre a la columna de agua, el cual comúnmente contiene hidrocarburos así como flora y fauna exóticas aportando contaminantes al ambiente marino (Guerrero Hernández, 2014). El Convenio Internacional para prevenir la Contaminación de los Buques MARPOL 73/78 permite el vertimiento de lastre cuando: la cantidad vertida no supere un 1/15 000 parte de la capacidad total de carga del petrolero, cuando la misma no exceda 60 l/milla navegada y que el vertimiento no se lleve a cabo en menos de 50 millas náuticas de la costa más cercana.

A pesar de las medidas preventivas, es posible la introducción de especies potencialmente invasoras a nivel de estadios planctónicos, además que los patrones de circulación del Golfo pueden facilitar colonización de especies foráneas. Carlton y Rukelshaus (1997) mencionan que, aún se desconocen muchas especies de fitoplancton marino y de otros grupos de invertebrados marinos, así como su distribución geográfica. Se considera que existe una gran cantidad de especies cosmopolitas, pero este hecho puede estar relacionado con la transferencia temprana de especies debido al transporte de barcos transoceánicos (citado de la Estrategia Nacional sobre Especies Invasoras en México, 2010).

Debido a su extenso litoral, México cuenta con 90 puertos, de los cuales más de la mitad (64%) tiene tráfico internacional en cantidades importantes, con más de 6 000 arribos por año (CGMP, 1999). Con base en el tamaño de los buques se ha calculado que alrededor de  $50 \times 10^6$  m<sup>3</sup> de agua proveniente de Australia, Filipinas, Medio Oriente y Europa se descargan anualmente en costas mexicanas (Okolodkov *et al.*, 2007 citado en Especies Acuáticas Invasoras en México, 2014).

Entre las especies que sobresalen por los estragos causados en el continente americano se encuentra el pez león (*Pterois volitans* y *P. miles*), voraces depredadores que han diezmado numerosas poblaciones de peces e invertebrados en los arrecifes y manglares del Golfo, varias de ellas de importancia comercial (meros, huachinangos, entre otros), además de ser venenosos, resultando peligrosos para diferentes especies, incluyendo la humana (Morris y Whitfield, 2009 citado en Especies Acuáticas Invasoras en México, 2014).

De acuerdo a los resultados de línea base del componente fitoplancton, se registró la presencia de dinoflagelados del género *Ceratium* y, sobre todo, *Gymnodinium*, asociados a la ocurrencia de eventos de "marea roja" o Floraciones Algales Nocivas, y en su mayoría no determinados taxonómicamente hasta el nivel de especie. Teniendo en cuenta que *Ceratium dens* (o *Neoceratium dens*) y *Gymnodinium catenatum* son microalgas consideradas potencialmente invasivas en aguas mexicanas, y que habrían ingresado debido al vertido de agua de lastre, se categorizará a este daño ambiental como moderadamente relevante en función al principio precautorio<sup>1</sup>, y a que el tráfico marítimo en el Golfo es una actividad

---

<sup>1</sup> **Principio Precautorio.**- La esencia de la precaución consiste en que, frente a la amenaza de un daño ambiental, debe actuarse para tomar control o disminuir tal riesgo, incluso existiendo incertidumbre

permanente, por lo cual el vertido de agua de lastre hacia la columna de agua también lo es.

#### 1.1.4 Conclusiones

Con base en los datos e información revisada anteriormente se puede dar un orden de Componentes Ambientales afectados, principalmente al día de hoy, como se indica en la Tabla 5.

**Tabla 5 Componente ambiental por incidencia**

Componente Ambiental por incidencia	Actividades que afectan al componente ambiental
Columna de Agua	Descargas de aguas continentales Actividades de la industria petrolera Actividades antropogénicas Emanaciones naturales de hidrocarburos
Ictiofauna	Descarga de aguas continentales Actividades de la industria petrolera Actividades antropogénicas Sobreexplotación de recursos pesqueros Emanaciones naturales de hidrocarburos
Bentos	Descarga de aguas continentales Sobreexplotación de recursos pesqueros Emanaciones naturales de hidrocarburos
Tortugas marinas	Actividades Antropogénicas
Mamíferos marinos	Actividades Antropogénicas
Sedimentos	Actividades de la industria petrolera Emanaciones naturales de hidrocarburos

Fuente: ERM, 2016

De acuerdo al análisis realizado, se puede concluir que el Componente Ambiental mayormente afectado en este momento y que requiere mayor atención en cuanto a medidas de mitigación es la columna de agua, seguido del sedimento marino, la cual se ve afectada principalmente por cuatro actividades que actualmente se realizan en la zona. Finalmente, es necesario considerar que el bentos, las tortugas y los mamíferos marinos, así como la ictiofauna, presentan evidencias de haber recibido

---

científica en cuanto a los efectos de la actividad en cuestión (Principios del Derecho Ambiental Internacional, Declaración de Río, 1992).

impactos por las actividades mencionadas en el pasado, por lo que conviene tener en cuenta dichos hallazgos, en la etapa de la aplicación de medidas.

La actividad de la industria petrolera de acuerdo a la valoración de los daños ambientales realizada, causa en su mayoría daños moderadamente relevantes que son necesarios tomar en cuenta.

## 1.2. Registro y descripción de daños preeexistentes (pasivos ambientales)

De acuerdo con el CONTRATO PARA LA EXPLORACIÓN Y EXTRACCIÓN DE HIDROCARBUROS BAJO LA MODALIDAD DE PRODUCCIÓN COMPARTIDA, licitación CNH-R01-L02-A4/2015, cláusula 3.4 artículos d) y f):

- (d) El Contratista deberá iniciar los estudios que permitan la identificación, caracterización y predicción de los pasivos ambientales mediante la contratación de un tercero acreditado por la Entidad Mexicana de Acreditación, previa autorización de la CNH, con la finalidad de establecer la línea de base ambiental antes del inicio de las Actividades Petroleras. El Estado vigilará que el contratista o asignatario que estuviera a cargo del Área Contractual con anterioridad a la Fecha Efectiva asuma los gastos relacionados con la liquidación, limpieza y remediación de los pasivos ambientales preeistentes;
- (f) Al término de la Etapa de Transición de Arranque, el Contratista asumirá total responsabilidad sobre el Área Contractual y sobre los Pozos y Materiales que en ella se encuentren, salvo por aquellos pasivos que hayan sido identificados.

En cumplimiento a lo anterior, en esta sección se presenta una descripción de la infraestructura preeexistente en el Área Contractual 4, así como los resultados de las inspecciones visuales a esa infraestructura, lo cual tuvo como resultado la determinación de daños preeistentes los cuales fueron aprobados por la Comisión Nacional de Hidrocarburos, según se describe a continuación.

### 1.2.1 *Infraestructura petrolera existente*

Según la información proporcionada por la CNH a Fieldwood se conoce la existencia de tres pozos exploratorios perforados con anterioridad en el Área Contractual 4, los cuales se denominan Ichalkil-1, Ichalkil-1 DL y Pokoch-1, y cuya ubicación geográfica se presenta en la Tabla 6.

**Tabla 6 Localización de pozos de exploración existentes en el Área Contractual 4**

Pozo preexistente	Coordenadas UTM (15Q)	
	X	Y
Ichalkil-1		
Ichalkil-1 DL		
Pokoch-1		

Fuente: CNH 2015

Los pozos Ichalkil-1 y Pokoch-1 empezaron a ser explorados en el año 2004, e Ichalkil-1DL en el 2009. Posteriormente, llegaron a la etapa de abandono a las profundidades de 5 010 m para Ichalkil-1, 5 805 m para Ichalkil-1DL y 5 031 m para Pokoch-1.

Cabe mencionar que se tiene además la presencia de cuatro pozos de exploración en las inmediaciones de los campos Ichalkil y Pokoch, cuya operación actual se encuentra a cargo de PEMEX y su producto es transportado hacia la zona costera través de un sistema de oleoductos y oleogasoductos (ver Tabla 7).

**Tabla 7 Localización de pozos de exploración cercanos a los campos del Área Contractual 4**

Pozo de exploración	Coordenadas UTM (15Q)	
	X	Y
Uech TB		
Jaatsul-1		
Pich		
ChucA		

Fuente: CNH 2015


Las características generales de los ductos existentes se resumen en la Tabla 8, mientras que en la Figura 3 *Ubicación de la infraestructura petrolera existente en el Área Contractual 4 y sus inmediaciones*

se muestra la infraestructura petrolera existente en el Área Contractual 4 y sus inmediaciones.

**Tabla 8 Localización de ductos cercanos a los campos del Área Contractual 4**

Nombre	Origen	Destino	Servicio	Longitud (m)
Oleoducto 36 INT L064 GNE- Dos Bocas	GNE	Dos Bocas	Oleoducto	132772.98
Oleoducto 36 Akal C - Dos Bocas	Akal C	Dos Bocas	Oleoducto	161325.47
Oleoducto 36 Pol A - Rebombeo	Pol A	Rebombeo	Oleoducto	50755.009
Oleogasoducto 36 Enlace - Pol A	Enlace	Pol A	Oleogasoducto	56315.61
Oleoducto 36 Akal J Enlace - Dos Bocas L2	Akal J Enlace	Dos Bocas L2	Oleoducto	160500.43

Fuente: CNH 2015



Fuente: Secretaría de Marina, Carta Náutica 840

**Figura 3** Ubicación de la infraestructura petrolera existente en el Área Contractual 4 y sus inmediaciones

#### 1.2.2 Inspección de la infraestructura petrolera existente

A fin de determinar la presencia de daños preexistentes en los campos del Área Contractual 4 se realizó una inspección visual detallada<sup>2</sup> de la integridad de la infraestructura actualmente instalada en dichas locaciones, específicamente de los sistemas de Suspensión Mud Line (MLS) de los pozos Ichalkil-1, Ichalkil-1DL y Pokoch-1. Los hallazgos de la referida evaluación se resumen en la Tabla 9.

<sup>2</sup> La inspección fue realizada el día 23 de junio de 2016 por la empresa Diavaz Offshore en el marco de los lineamientos estándar técnico (Integridad de Pozo para la Fase Operacional).

**Tabla 9 Resumen de hallazgos de la inspección de los sistemas MLS de los pozos Ichalkil-1, Ichalkil-1DL y Pokoch-1**

Pozo	Hallazgos
Ichalkil-1	Ausencia de fluidos tanto en las fundaciones del pozo como en el espejo de agua
	Área de cementación de 1 m de radio y a 50 cm por debajo del nivel del lecho marino
	Capuchón del pozo de 36" en su lugar y con cuatro tornillos opresores de 1" de diámetro y 12 cm de longitud
	Emanan burbujas de gas del cabezal del pozo de manera intermitente cada 20 segundos
Ichalkil-1DL	Ausencia de fluidos tanto en las fundaciones del pozo como en el espejo de agua
	Área de cementación de 150 cm de radio y a 22 cm por debajo del nivel del lecho marino
	Capuchón del pozo de 36" en su lugar y solo con tres tornillos opresores de 1" de diámetro y 20 cm de longitud. Faltaría el cuarto tornillo
Pokoch-1	El capuchón del pozo de 36" se encuentra fuera de lugar y apoyado sobre un neumático. Ausencia de fluidos tanto en las fundaciones del pozo como en el espejo de agua
	Área de cementación de 57 cm de radio y a 45 cm por debajo del nivel del lecho marino
	Emanan continuamente burbujas de gas del cabezal del pozo

Fuente: Reportes de Inspección Diavaz Offshore, 2016

Asimismo, en la Tabla 10 se presentan los criterios empleados para examinar la integridad de los MLS.

**Tabla 10 Criterios empleados para la inspección de los MLS de los pozos Ichalkil-1, Ichalkil 1-DL y Pokoch-1**

Criterio de inspección	Pozos		
	Ichalkil-1	Ichalkil-1DL	Pokoch-1
Condición general del equipo de suspensión de tuberías (Buena / Regular / Deficiente)	Buena	Regular. El capuchón del pozo no se encuentra en su posición, y los tornillos opresores no están en su lugar	Regular. Falta uno de los cuatro tornillos opresores del cabezal del pozo
Alguna protección alrededor del pozo (Sí / No)	No	No	No
Evidencia de daño físico en el equipo (barreras, jaulas de protección o deflectores de arrastre)	Ninguna	Ninguna	Ninguna
Evidencia de daño o impacto mecánico (Sí / No)	No	No	No
Naturaleza del daño mecánico (cortes, hendiduras, agrietamientos, abolladuras)	Ninguna	Ninguna	Ninguna
Condición de corrosión, erosión o desgaste (Sin daño, Leve / Moderada / Severa)	Sin daño	Sin daño	Leve corrosión en el capuchón del pozo
Filtraciones o emanación de burbujas desde el cabezal del pozo (Si / No)	Sí. Burbujeo cada 20 segundos a la altura de uno de los tornillos opresores, por debajo del sello del capuchón del pozo	No	Sí. Emanación continua de burbujas desde el cabezal del pozo

*Fuente: Reportes de Inspección Diavaz Offshore, 2016*

Cabe destacar que los hallazgos relativos a las emanaciones de burbujas de gas detectadas en los pozos Ichalkil-1 y Pokoch-1, así como también la remoción del capuchón y de los tornillos de opresión reportada en este último, califican como daños preexistentes.

Se enfatiza que la Comisión Nacional de Hidrocarburos notificó a Fieldwood Energy la aprobación de estos daños preexistentes por medio del oficio No. 220.1777/2016 de fecha 26 de agosto de 2016. Esos daños preexistentes fueron incluidos en el informe de la Línea Base Ambiental entregada a esa Comisión y a la ASEA. En escrito del Fieldwood Energy del 5 de julio de 2016 (ver Anexo 2).

#### 1.2.3 *Información de las condiciones ambientales históricas*

La intensificación de las actividades de transporte de petróleo, las descargas y el lavado de buques-tanque, constituyen la mayor fuente de contaminación derivada de la industria del petróleo en los ambientes costeros del Golfo de México (Botello *et al.*, 1992). Existe evidencia de elevados índices de presencia de hidrocarburos en mar abierto en la región del Golfo y el mar Caribe, donde áreas localizadas mayormente en la Sonda de Campeche rebasan los límites permisibles de concentración de hidrocarburos de  $0.03 \mu\text{g L}^{-1}$  de la US EPA (1988) y  $0.20 \mu\text{g L}^{-1}$  (Unión Europea). El estado de Campeche ocupa el primer lugar en las concentraciones de hidrocarburos dispersos en aguas costeras y marinas con un promedio de  $48 \mu\text{g L}^{-1}$ , seguido por el mar Caribe con  $15 \mu\text{g L}^{-1}$  (Ponce y Botello, 2005).

La contaminación que ingresa a las lagunas, ríos, estuarios y al mar del Golfo de México proviene principalmente del procesamiento de alimentos, de la refinación del azúcar, la explotación petroquímica, y de las aguas residuales agrícolas y domésticas (Rosas *et al.*, 1983). La zona marina al sur del Golfo recibe importantes aportes fluviales de los ríos González, Grijalva, San Pedro - San Pablo, Champotón, Lerma y de las bocas de la Laguna de Términos. Asimismo, las actividades petrolera y pesquera, y el tráfico marítimo, modifican las concentraciones de sedimentos y metales traza en el ambiente marino (Vázquez Gutiérrez *et al.*, 1999). Muchos de los programas de seguimiento ecológico se han llevado a cabo en las zonas cercanas a las refinerías de petróleo a fin de evaluar el impacto que estas tienen sobre el medio ambiente. La mayoría de los estudios han analizado el impacto en el medio marino o de estuario, especialmente de refinerías que descargan en las zonas intermareales (CINVESTAV, 2013).

En las aguas congénitas vertidas desde las zonas petroleras, se encontró que varios metales podrían estar presentes en concentraciones mucho más elevadas que en el agua de mar circundante (1 000 veces o más). Los metales más frecuentemente detectados en concentraciones elevadas en el agua congénita son bario, hierro, manganeso y zinc. Cuando se descargan en aguas superficiales ricas en sulfato y bien oxigenadas, el hierro y el manganeso disueltos pueden precipitar como óxidos y, por tanto, instalarse fuera de la columna de agua y acumularse en los sedimentos alrededor de la descarga. Dependiendo del régimen de corrientes del sitio de interés, estos óxidos metálicos podrían dispersarse en un área grande, elevando sus concentraciones en los sedimentos del fondo marino (Yeung *et al.*, 2011).

Asimismo, el diagnóstico ambiental del Golfo de México en cuanto a hidrocarburos es regular, de acuerdo al estado que tenía antes de 1981. Sin embargo, si se considera el valor de fondo propuesto en el 2004, su estado sería bueno ya que no se rebasan los límites establecidos por la Legislación europea.

Del monitoreo de calidad de aire realizado en el año 2013 por el CINVESTAV, y en cuanto a los niveles de gases contaminantes y de efecto invernadero en zonas cercanas al Área Contractual 4, se encontró que de acuerdo a la normatividad nacional vigente se rebasan los límites máximos de los parámetros Dióxido de Azufre (NOM-022-SSA1-1993), Dióxido de Nitrógeno (NOM-023-SSA1-1993) y Ozono (NOM-020-SSA1-1993). Además, se evidenció que las concentraciones más altas de Monóxido de Carbono (CO) fueron reportadas en el área de plataformas al noroeste de Ciudad del Carmen (Campeche), cerca de los campos del Área Contractual 4. Por otro lado, al analizarse las emisiones a la atmósfera desde la costa, se encontró que estas no superaron los límites máximos permisibles de la Legislación nacional vigente (CINVESTAV, 2013).

La concentración promedio de Dióxido de Carbono (CO<sub>2</sub>) en el área de estudio fue de 280.12 ppm, con un valor máximo reportado de 329.10 ppm, donde las concentraciones más elevadas se presentaron en el área de plataformas con niveles superiores a 300 ppm. Cabe mencionar que dichos valores se encuentran por debajo del límite sugerido por la Comunidad Económica Europea (CEE) y diversas ONGs de 350 ppm (CINVESTAV, 2013).

Asimismo, la concentración promedio en la zona de partículas suspendidas totales (PSTs) y de partículas menores a 10 micrómetros (PM<sub>10</sub>) se encontraron por debajo de los límites establecidos en la NOM-025-SSA1-1993 (CINVESTAV, 2013).

Las concentraciones promedio de metales en la atmósfera (Ba, Cd, Cr, Cu, Fe, Ni y V) presentaron valores muy bajos, los cuales cumplieron con los límites aplicables para ambiente laboral de acuerdo a la NOM-010-STPS-1999. Y para el caso del plomo, se observó que los niveles detectados en toda el área de estudio estuvieron por debajo del límite establecido en la NOM-026-SSA1-1993 (CINVESTAV, 2013).

Por lo anterior, se concluye que no existiría mayor afectación de la calidad del aire en la zona del Área Contractual 4, ya que casi todos los parámetros (con excepción de SO<sub>2</sub>, NO<sub>2</sub> y O<sub>2</sub>) se encuentran muy por debajo de los límites máximos establecidos en las normas oficiales de referencia.

#### 1.2.4 *Resultados de la presente evaluación ambiental*

Durante la colecta de muestras realizada en el marco de la presente evaluación ambiental, no hubo hallazgos de evidencias visuales (sobrenadantes de hidrocarburos, manchas de grasa) ni olfativas de afectación por hidrocarburos en el agua ni en el sedimento marino. Los resultados de los análisis de laboratorio se resumen a continuación:

##### *A nivel de calidad de sedimento marino:*

###### **Hidrocarburos:**

Solo una muestra proveniente del campo Pokoch presentó excedencia en el criterio de comparación de la UNESCO para la fracción pesada de HTP; sin embargo, en ninguna de las muestras restantes se detectó hidrocarburos por encima del nivel de cuantificación del método analítico de laboratorio.

###### **Metales:**

Cadmio: Se excedió el criterio de comparación SQuiRTs de la NOAA en todas las estaciones de muestreo, detectándose concentraciones entre 1.11 y 1.63 mg/kg (TEL= 0.68 mg/kg). El valor más alto fue registrado en la locación PC1 del campo Pokoch (1.86 mg/kg).

Níquel: Se excedieron ambos niveles establecidos en los criterios de comparación de SQuiRTs de la NOAA en todas las estaciones de muestreo, detectándose

concentraciones entre 60.59 y 75.55 mg/kg (TEL= 15.90 mg/kg, PEL= 42.80 mg/kg), con el valor más alto en la locación D3 ubicada al suroeste del campo Ichalkil.

Bario: Se excedió el límite del TEL (130.10 mg/kg) establecido en el criterio de comparación SQuRTs de la NOAA en las estaciones de muestreo IC1 y D4, con valores de 316.07 y 221.96 mg/kg respectivamente. Cabe mencionar que en todas las demás muestras se detectaron concentraciones de este metal aunque por debajo de la normativa de referencia.

Otros metales detectados, pero en concentraciones por debajo de los valores guía de referencia o que no tienen criterio de comparación, fueron: hierro, zinc, plomo, cobre, vanadio, bario, litio, manganeso y molibdeno.

*A nivel de calidad de agua de mar:*

**Hidrocarburos:**

Se detectaron dos muestras dentro del campo Pokoch con excedencias de HTP - Fracción Pesada de los valores guía de referencia de la UNESCO; sin embargo, en las muestras restantes no se detectaron hidrocarburos por encima del nivel de cuantificación de los métodos analíticos, tanto para HTP como para HPA.

**Metales:**

Hierro: Se detectó por encima de los criterios de comparación de la UNESCO en la muestra P2-S ubicada en el campo Pokoch. Para las muestras restantes no hubo detecciones que superaran el límite de cuantificación del laboratorio.

Cobre: Se detectó por encima de los criterios de comparación de SQuRTs de la NOAA en la muestra Dupli-1-agua correspondiente al campo Ichalkil. Para las muestras restantes no hubo detecciones que superaran el límite de cuantificación del laboratorio.

Otros metales detectados por encima del límite de cuantificación del laboratorio fueron: zinc, cromo, vanadio y bario, pero por debajo de los criterios de comparación. El resto de los metales no fueron detectados por encima del límite de cuantificación en las muestras de agua.

Sólidos Suspendidos Totales (SST): La concentración de SST se detectó entre 140 y 304 mg/L a nivel superficial, 138 y 230 mg/L a nivel medio y entre 118 y 224 mg/L a nivel de fondo. No se identificó una tendencia específica entre los puntos de muestreo.

Clorofila a: Se detectó en la mayoría de los puntos de muestreo en todos los niveles por encima de las concentraciones típicas reportadas para el sur del Golfo de México de 0.00004 mg/L lo cual nos indica una biomasa fitoplanctonica elevada en dichos puntos.

#### 1.2.5 *Conclusión*

La ASEA establece que “Daño Ambiental significa, la pérdida, cambio, deterioro, menoscabo, afectación o modificación adversa y mensurable de los ecosistemas y de los elementos y recursos naturales que los comprenden, incluyendo de manera enunciativa más no limitativa sus hábitats, el agua, el suelo, el subsuelo, la flora y la fauna, así como de las condiciones químicas, físicas o biológicas de dichos ecosistemas, elementos y recursos naturales, de las relaciones de interacción que se dan entre estos, así como de los servicios ambientales que proporcionan, derivada de hechos de la naturaleza o actividades humanas”. Además, indica que “Pasivo Ambiental, significa, sin importar su causa u origen, aquellos sitios contaminados por la liberación de materiales o residuos peligrosos, que no fueron remediados oportunamente para impedir la dispersión de contaminantes, y cualesquier otros Daños Ambientales, presentes en el Área Contractual antes del inicio de la Fecha Efectiva”.

De acuerdo con la información bibliográfica, el Área Contractual 4 se ha visto afectada en mayor o menor grado por actividades antropogénicas como la extracción de hidrocarburos, pesca, tráfico marino, diversas industrias y desechos urbanos, entre las principales, que se han llevado a cabo históricamente en la zona costera y marina, impactando por tanto los ecosistemas acuáticos desde tiempos previos a la instalación de los pozos Ichalkil-1, Ichalkil-1DL y Pokoch-1.

Del mismo modo, los niveles de concentración en el sedimento de HTP-Fracción Pesada y de ciertos metales como cadmio, níquel y bario, obedecerían a los procesos geoquímicos propios del Golfo, incluyendo la existencia de emanaciones naturales de hidrocarburos (o chapopoteras) cercanas al Área Contractual 4; y también tendrían relación con los aportes de origen antrópico a través del aforo de los ríos o

de las actividades propias de la industria del petróleo, en especial la probable descarga incidental de cortes y lodos de perforación. Las concentraciones detectadas durante la presente evaluación, superan los valores guía de referencia y podrían representar un riesgo para el ecosistema en cuanto a sus efectos biológicos (ver **Error! Reference source not found.**). A esta condición actual se le considera un daño ambiental.

A fin de determinar la presencia de daños preexistentes en los campos del Área Contractual 4 se realizó una inspección visual detallada de la integridad de los pozos Ichalkil-1, Ichalkil-1DL y Pokoch-1, específicamente de sus sistemas de suspensión mud line, detectándose emanaciones de burbujas de gas en los cabezales de Ichalkil-1 y Pokoch-1, así como también la remoción del capuchón y de los tornillos de opresión en Pokoch-1.

Por lo tanto, con base en a los resultados obtenidos y cuyos resultados hacen referencia a un único momento temporal, se concluye que existen evidencias de daño ambiental en el ecosistema marino así como de pasivos ambientales en el Área Contractual 4, los cuales constituyen daños preexistentes conforme se estipula en las cláusulas 1.1 y 13.4 del Contrato Para la Extracción de Hidrocarburos Bajo la Modalidad de Producción Compartida. En particular, se hace notar, independientemente de su causa u origen, la existencia de emanaciones de burbujas de gas detectadas en los cabezales de los pozos Ichalkil-1 y Pokoch-1, así como la remoción del capuchón y de los tornillos de opresión reportada

Se enfatiza que la Comisión Nacional de Hidrocarburos notificó a Fieldwood Energy la aprobación de estos daños preexistentes por medio del oficio No. 220.1777/2016 de fecha 26 de agosto de 2016. Esos daños preexistentes fueron incluidos en el informe de la Línea Base Ambiental entregada a esa Comisión y a la ASE. En escrito de Fieldwood Energy del 5 de julio de 2016 (Ver Anexo 2)

Finalmente, y en el marco de los hallazgos obtenidos, cabe recalcar que no se descarta la existencia de daños ambientales o daños preexistentes en aquellas cinco locaciones donde no pudieron colectarse muestras de sedimento por disposición de Centro de Control de Tráfico Marítimo de PEMEX.

- f. *El REGULADO deberá justificar técnicamente el por qué únicamente tomó un escenario calificado como Riesgo Medio para la simulación del análisis de consecuencias y no en la totalidad de los escenarios identificados como Riesgo Medio (5 escenarios para el nodo 1y 4 escenarios para el nodo 2); en su caso actualizar el análisis de consecuencias.*

Fieldwood Energy eligió utilizar una sesión de HazID (Identificación de Peligros por sus siglas en Inglés) como el método de evaluación de riesgo a nivel de proyecto para las actividades de la Etapa de Evaluación de este proyecto. El estudio fue facilitado por un experto externo y se basa en las mejores prácticas identificadas en el estándar internacional ISO 17776: 2000 "Industrias de petróleo y gas natural - Instalaciones de producción costas afuera - Directrices sobre herramientas y técnicas para la identificación y evaluación de riesgos". Según la metodología, la clasificación del riesgo de cada peligro identificado se basa en la probabilidad de ocurrencia junto con un análisis de las **posibles** consecuencias para las vidas humanas, el medio ambiente o los bienes. Esta es una evaluación cualitativa hecha por el equipo de HazID basado en la **ausencia de medidas de control / mitigación**.

El **análisis de las consecuencias** para cada escenario de peligro identificado dio lugar a una calificación de gravedad potencial, que luego se combinó con una calificación de la probabilidad de ocurrencia , para dar lugar a la clasificación de riesgo (alta, media o baja). En la mayoría de los casos, los escenarios de peligro y sus consecuencias son bien conocidos y comprendidos por la industria, y el equipo de HazID no requirió información adicional para analizar y calificar cualitativamente las posibles consecuencias. Sin embargo, hubo un escenario de peligro identificado, en el cual la gravedad de la consecuencia es afectada en gran medida por factores externos / no controlados. En ese caso, el escenario de un derrame debido a la pérdida del control del pozo, el equipo de HazID se basó en el modelado de las consecuencias para determinar el análisis y la asignación de la clasificación de gravedad (más información a continuación).

Una vez que los rankings de riesgo fueron asignados a todos los escenarios de peligro identificados, el equipo identificó los controles y mitigaciones que se instalarán para manejar cada riesgo y / o reducir la severidad de las consecuencias . A continuación, el equipo analizó cada escenario de peligro en términos de severidad *real* de la consecuencia y probabilidad de ocurrencia *considerando los controles / barreras existentes*. En los casos en que el Equipo HazID determinó que los

controles / *barreras* resultan en una reducción del riesgo a un nivel bajo o tan bajo como sea razonablemente practicable, los controles / *barreras* existentes fueron considerados adecuados. En los casos en que no lo fue, el equipo determinó los controles / *barreras* adicionales necesarios o recomendaciones para reducir la gravedad de la consecuencia o probabilidad de ocurrencia a un nivel aceptable, los cuales fueron luego documentados para su implementación.

Con respecto a los escenarios de peligro identificados, para los cuales se consideró adecuado un análisis cualitativo de las consecuencias, se incluyen discusiones adicionales como sigue:

- El riesgo de la posible presencia de gas H<sub>2</sub>S se mitiga mediante el uso de un plan de contingencia de H<sub>2</sub>S. Este plan describe la preparación, capacitación, monitoreo, detección, equipos de rescate y protocolos de sistemas de paro por emergencia automatizados que se utilizarán en caso de que se detecten cantidades potencialmente peligrosas de este gas. Teniendo en cuenta que este gas podría presentarse durante una situación de control de pozo, todas las partes involucradas con el control de contingencia, incluidos los recursos de respuesta a derrames, son considerados en el desarrollo del plan de contingencias.
- La caída de objetos y los trabajos en alturas se disminuyen mediante el uso de prácticas de trabajo seguras y sistemas de permisos de trabajo que son parte integral del sistema general de gestión de riesgos. No existen metodologías de modelización generalmente aceptadas que se apliquen a estas exposiciones generales.
- Las operaciones con helicópteros no requieren de modelado adicional más allá de lo que ha guiado a la industria del transporte para poner en práctica las medidas de control que se encuentran actualmente implementadas. Experiencias previas donde se involucra errores humanos, condiciones climatológicas severas y falla mecánica, han sido tomados en cuenta en los controles ya existentes actualmente.
- El fenómeno climatológico que constituye el mayor riesgo potencial son los huracanes. Este riesgo no está sujeto a modelación. De hecho, el riesgo planteado por un huracán depende de la experiencia de los impactos de este tipo de fenómenos en el sitio del proyecto. Fieldwood Energy ha considerado esto en el elemento Plan de Respuesta a Emergencias en el programa de gestión de riesgos, como un plan de monitoreo de huracanes y evacuación.
- La potencial ignición o explosión de gases y líquidos (vapores) inflamables se mitiga a través de múltiples controles. Los sistemas de seguridad y control para

pozo son el método primario para reducir la probabilidad de que una cantidad importante de gas o vapores represente un riesgo. Controles adicionales incluyen el diseño de las instalaciones y equipos para reducir o eliminar las posibles fuentes de ignición. En situaciones en las que la eliminación de la fuente de ignición no es posible, se utilizan métodos de detección para iniciar las alarmas y cierres automáticos para aislar las fuentes de gas y desenergizar las fuentes de ignición. El riesgo potencial presentado, incluso por pequeñas cantidades de gases o vapores inflamables se considera en el desarrollo del programa de gestión de riesgos, que utiliza prácticas de trabajo seguro y sistemas de permisos de trabajo. Por último, teniendo en cuenta que los gases o vapores inflamables podrían ser experimentados durante una situación de control de pozo, todas las partes involucradas con el control de contingencia (incluido el recurso de respuesta a derrames) son consideradas en el desarrollo de los planes de respuesta.

- Las operaciones del buque no requieren de modelado adicional de los que han guiado a la industria del transporte para poner en práctica las medidas de control que se encuentran actualmente establecidas. Las experiencias previas donde se involucra errores humanos, condiciones climatológicas severas y falla mecánica han sido tomadas en cuenta.

Fieldwood identificó un escenario de peligro en la Etapa de Evaluación del proyecto, el escenario de un derrame debido a la pérdida de control de pozos, lo cual requirió modelado para determinar los controles / barreras apropiados. El modelado de las consecuencias potenciales de una descarga del peor caso resultante de este escenario se usó para determinar los receptores específicos que podrían ser impactados basados en amplias variaciones en un amplio número de factores de influencia externos no controlables.

g. *REGULADO deberá realizar la justificación técnica de suponer un derrame de 6,259 BPD y porque se acotó la duración del derrame a 15 días. Lo anterior deberá ser sustentado y/o ajustado con la finalidad de tener la certeza que se está simulando el Peor Escenario sin subestimar o sobreestimar el riesgo en caso de derrame de hidrocarburo.*

#### Justificación de flujo de derrame

Para la determinación del flujo de derrame a considerar dentro del modelo de simulación, se tomaron en consideración las propiedades físicas y petrofísicas del fluido.

Se analizaron los escenarios de posible descarga por pérdida de control en el pozo, los cuales suceden al estar perforando o terminando las zonas del yacimiento productor (incluidas formaciones Cretácicas y Jurásico Superior Kimmeridgiano (JSK)).

El escenario de descontrol con máxima descarga se presenta al tener expuesto el JSK sin tubería de perforación. El cual tiene como flujo estimado de **6,259 BPD** de aceite.

El ejercicio se realizó mediante un modelo de flujo multisálico el cual se ajusta a los datos de la prueba de presión producción en los yacimiento Cretácico y JSK del campo Ichalkil. Para la determinación del espesor neto productor y la fracción de agua, en la sección completa del yacimiento se utilizan los registros del campo.

La Tabla 11, resume los resultados de la simulación de los casos analizados, donde se observa que el caso más crítico se da durante la perforación del yacimiento JSK, cuando se tiene el agujero descubierto sin tubería en el interior (ver Figura 4).


**Tabla 11 Simulación de flujo de derrame de pérdida de control de pozo**

Caso	Formación	Condición	Qo max BPD
1	Cretácico	Flujo Anular en Agujero Descubierto 12-1/4" x TR 11-7/8", con TP 5-7/8"	3480
2	Cretácico	Flujo Anular Agujero Descubierto 12-1/4" x TR 11-7/8", sin TP	3847
3	Jurásico	Flujo Anular Agujero Descubierto 9-1/2" x Liner 9-7/8" x TR 11-7/8", con TP 5-7/8"	5329
4	Jurásico	Flujo Anular Agujero Descubierto 9-1/2" x Liner 9-7/8" x TR 11-7/8", sin TP	6259

Fuente: Información provista por Fieldwood Energy. Octubre de 2016.

Nota: Qo max = Flujo de derrame máximo; BPD = Barriles por día

**Figura 4 Modelo de flujo multifásico para el escenario de mayor volumen derramado**



Nota: Liquid Rate = Flujo líquido; Gas Rate = Flujo Gas; Oil Rate = Flujo de Hidrocarburo; Water Rate = Flujo de Agua; STB = Barril de tanque de almacenamiento; Pressure = Presión; psia = libras por pulgada cuadrada.

### Justificación de duración de derrame

Se ha estimado que el tiempo de respuesta para los proveedores de servicios de control de pozo es aproximadamente de 5 a 6 días. Los diversos tipos de equipos especializados utilizados por estos proveedores están ubicados a lo largo de la costa del Golfo en los Estados Unidos (Corpus Christie, Houston, Fourchon, Grand Isle, etc.) y se mantienen en una condición que permite su despliegue inmediato. Estos días son calculados teniendo en cuenta la experiencia previa de Fieldwood Energy con escenarios de control de pozos anteriores. Es importante señalar que estos proveedores de recursos tienen experiencia previa en servicios dentro de México.

El tiempo de respuesta para la movilización de recursos de Nivel 3 de respuesta a derrames (global) de petróleo se aproxima a los 3-5 días, incluida la movilización inmediata completa. Los de nivel 1 y 2 recursos se encuentran a lo largo de la costa del Golfo de México en las proximidades de la ubicación del proyecto (Dos Bocas y Ciudad del Carmen) y se mantienen en una condición que permite el despliegue inmediato para respuesta a emergencias. Los recursos adicionales necesarios para complementar los recursos en el país para una respuesta de Nivel 3 están situados a lo largo de la Costa del Golfo en los Estados Unidos (Texas, Luisiana y Florida).

Por último, es importante tener en cuenta que tanto el control del pozo y de los recursos de respuesta a derrames se iniciarían simultáneamente. Como tal, sus respectivos tiempos de respuesta podrían traslaparse, y la realización de un control total de la liberación se estima que ocurre dentro de aproximadamente 5 días. Sin embargo, a efectos de asegurar una adecuada estimación del tiempo requerido de contención, se toma un factor de seguridad de aproximadamente 2.5-3x aplicado al tiempo de respuesta. Por lo tanto, el escenario de peor caso de derrame para efectos de modelación se estimó en 15 días.

*h. El REGULADO deberá ingresar información de soporte respecto al uso del modelo tridimensional GEMS y COSIM, con la finalidad de evidenciar los datos que se ingresaron a dichos modelos de simulación y los resultados obtenidos para los mismos /memoria numérica.*

En el Anexo 3, se incluye un ejemplo del archivo creado por el modelo GEMSS-COSIM en cada una de las temporadas para las 120 simulaciones (50 para la temporada lluviosa, 40 para la temporada de frentes fríos anticiclónicos y 30 para la temporada seca). Dichos archivos presentan los valores de entrada y de salidas generados por cada modelación para ser posteriormente integrados en el resumen de resultados. Al ser los archivos muy extensos se presentó un resumen de los resultados de las 120 simulaciones en el capítulo 9 de la MIA, mismo que se presenta nuevamente en la Tabla 12 para el derrame de 15 días.

**Tabla 12 Resumen de los Resultados del Modelo – Derrame de 6,259 BPD de Crudo Ligero, Golfo de México**

Escenario	Iteración (peor escenario)	Concentración Máxima de HAD (ppb)	Área de superficie en riesgo d/HAD > 5 ppb (km <sup>2</sup> )	Tiempo mínimo para impactar la costa (horas)	Área máxima con crudo visible en la superficie oceánica (km <sup>2</sup> )	Área superficial > 1 ppb (km <sup>2</sup> )	Línea costera en riesgo de ser cubierta de crudo (km)
Temporada lluviosa (junio a octubre)	Superficie máxima cubierta de crudo Tiempo mínimo para impactar la costa Máxima extensión de costa cubierta de crudo	49 103 103	221 1,316 1,316	42 2,630 2,630	85,826 2,450 2,450	13,120 2,450 2,450	15 155 155
Temporada Frías y fríos anticiclónicos (octubre a febrero)	Superficie máxima cubierta de crudo Tiempo mínimo para impactar la costa Máxima extensión de costa cubierta de crudo	64 78 100	230 657 1,564	23 758 7,891	64,748 758 6,975	2,351 758 6,975	0 68 235
Temporada Seca (febrero a mayo)	Superficie máxima cubierta de crudo Tiempo mínimo para impactar la costa Máxima extensión de costa cubierta de crudo	55 110 110	1,328 1,879 1,879	35 35 35	86,112 8,640 8,640	17,777 8,177 8,177	2 346 346

BFD = barril; km = kilómetros; km<sup>2</sup> = kilómetros cuadrados; PPB = partes Por billón; HAD= Hidrocarburos Aromáticos Disueltos

**Nota:** para cada temporada (lluvias, frentes fríos anticiclónicos y secas), hay un set de peores escenarios (iteraciones); dependiendo del escenario de particular interés; Superficie máxima cubierta de crudo, tiempo mínimo para impactar la costa, o máxima extensión cubierta de crudo, y el resultado, son presentados para cada uno de ellos en su correspondiente línea.


- i. *El REGULADO deberá ingresar planos a escala adecuada donde se observen los sitios probables de deposición de crudo en la costa en tres temporadas climáticas del año distintas (secas, frentes fríos y lluvias). Aunado a lo anterior, deberá realizar el análisis y discusión de las posibles sitios vulnerables a impactar (arrecifes de coral, áreas naturales protegidas, vegetación de manglar, entre otros).*


Los resultados del modelo de derrames presentado en el Capítulo 9 de la MIA indican que el derrame tendría una baja probabilidad (menor a un 20% de deposición) de alcanzar receptores ambientales, tales como las Áreas Nacionales Protegidas (ANP) Federales, Arrecifes Coralinos y Regiones Marinas Prioritarias (Delta del Río Coatzacoalcos, Los Tuxtlas, Pantanos de Centla-Laguna de Términos, Sistema Lagunar de Alvarado, Laguna Verde-Antón Lizardo, Tecolutla, Pueblo Viejo-Tamiahua, Giro Tamaulipeco, Fosa Segsbee y Cayos Campeche) ubicadas en las costas de Veracruz, Tabasco y/o Campeche y el Golfo de México. La probabilidad de que el crudo se deposite en la zona de arrecifes ubicada frente a las costas de Veracruz sería mucho menor al 10% (ver Figuras 8 a 10) y en la superficie del agua cercana a las zonas de arrecifes coralinos en el Golfo de México (aproximadamente 180 km al norte del sitio del derrame) sería menor al 40% en las tres temporadas climáticas analizadas. En algunos casos, la probabilidad de alcanzar las costas de Tabasco sería menor al 40% durante las tres temporadas climatológicas (entre 50 km y 100 km al oeste del Puerto Frontera) en las regiones marinas prioritarias y zonas de Arrecifes para la mancha de crudo sobre la superficie del agua (Bajíos Obispo y Triángulos; y en menor probabilidad los arrecifes Cayos Arcos, Nuevo y Banco Ingleses). También, los resultados de las simulaciones indican que el derrame podría alcanzar algún arrecife coralino (con probabilidad menor a 40%) ubicados en el Golfo de México, tal y como se muestra de la Figuras 5 a 7.


Los resultados de las simulaciones indican que la temporada seca presentó la más extensa superficie máxima cubierta de crudo con 86,112 km<sup>2</sup>; mientras que la temporada de frentes fríos anticiclónicos presentó la menor superficie máxima cubierta de crudo con 64,748 km<sup>2</sup>. Gran parte de la superficie ocupada por la mancha de crudo presentaría un espesor menor a 1 µm, visible como una capa delgada y brillosa pero con pocas probabilidades de provocar incrustaciones en aves y mamíferos marinos. Tal y como el crudo se meteoriza, este puede formar bolas de



crudo y emulsionar de forma que su densidad se vuelve más cercana a la del agua marina, entrando en la columna de agua más fácilmente, en donde se degradará.



En los tres diferentes peores casos, las concentraciones de hidrocarburos aromáticos disueltos (HAD) podrían estar presentes en magnitudes que pueden causar narcosis aguda en la fauna acuática. Las regiones, que típicamente se podrían ver afectadas, se localizan en las proximidades de la liberación sub-superficial, en donde la pluma de constituyentes disueltos se eleva con la liberación dentro de los primeros metros de la columna de agua por debajo de la mancha oleosa. Lo anterior, particularmente sucede dentro de la primera semana en que ocurre el derrame antes de que muchos compuestos de hidrocarburos se evaporen o degraden.















- j. *El REGULADO deberá realizar el análisis de consecuencias de la dispersión de los gases inflamables, la evaluación de la radiación térmica derivada de posibles eventos de dardo de fuego (jet fire), charco de fuego (pool fire) así como la sobrepresión debido a la posibilidad de una explosión, identificando en cada uno de estos las zonas de alto riesgo y amortiguamiento.*

Antes de la sesión de HazID para la Etapa de Evaluación de este proyecto, Fieldwood Energy sabía que el dueño de la plataforma autoelevable Ocean Sceptre (Rig), Mexdrill (Diamond Offshore) tenía información de análisis de peligros para el tipo y alcance de las operaciones llevadas a cabo a bordo de la plataforma. Esta información consiste en un Registro de Peligros y un Análisis de Corbata de Moño. Este estudio se realizó y documentó según la guía de mejores prácticas presentada por la Asociación Internacional de Contratistas de Perforación (IADC). Cabe señalar que los peligros analizados incluyen incendios de hidrocarburos, explosiones, sobrepresión, líquidos calientes y fuentes de ignición a flama abierta para operaciones típicas de las que se realizan en esta etapa del proyecto. Fieldwood Energy revisó y aceptó esta información que luego fue proporcionada a la persona responsable de planificar y facilitar la sesión de HazID. Por lo tanto, esta información fue revisada y adoptada como base para la planificación del ejercicio de análisis de peligros a nivel de proyecto.

Como parte del diseño extendido e ingeniería para las instalaciones de producción, que se incluirá en la Etapa de Desarrollo del proyecto, se realizarán ejercicios de análisis de riesgos posteriores. Se identificarán y analizarán los riesgos asociados al tipo de operaciones específicamente aplicables a la Etapa de Desarrollo. Se espera que esto incluya el análisis de los peligros potenciales causados por la dispersión de los gases inflamables, la radiación térmica de los incendios y los eventos de sobrepresión causados por el fuego o la explosión.

En el Anexo 4 se incluye la traducción al español del registro de peligros de la liberación de hidrocarburos líquidos, gas y ácido sulfídrico H<sub>2</sub>S como accidentes mayores. De la metodología corbata de moño se presentan el análisis de 15 tipos diferentes de accidentes. Igualmente se describe la relación de los riesgos residuales.

Asimismo se incluye una presentación del análisis tipo corbata de moño para los eventos de liberación de hidrocarburos líquidos, de gas y ácido sulfídrico y se entrega en extenso el análisis tipo corbata de moño completo.

Por lo que se concluye que se llevó a cabo un análisis sólido de consecuencias para los riesgos de la Etapa de Evaluación.

*k. El REGULADO deberá identificar y proponer medidas de contención y mitigación específicas para el escenario de derrame de hidrocarburo en el agua, considerando los parámetros de dispersión y las simulaciones de derrames realizadas.*

Como antecedente, se señala que Fieldwood Energy tiene en cuenta controles primarios para la mitigación del peor escenario de derrame y estos están incorporados en los planes y equipos operacionales, tales como Preventores (BOP, por sus siglas en inglés). Sin embargo, la siguiente información puede ser añadida a la existente en relación con el plan de respuesta a derrames:

- Las respuestas de Nivel 1 y Nivel 2 están establecidas en el país en las inmediaciones de la zona de operación. El proveedor de respuesta a derrames de petróleo está ubicado en Paraíso - Dos Bocas.
- La respuesta a Nivel 3 se estableció a través de un recurso global de Fieldwood Energy que se encuentra ubicado en las costas del Golfo de México en los Estados Unidos.
- Se han seleccionado los recursos (personal y equipos) que están planeados por el proveedor de servicios de respuesta a derrames basado en el peor de los casos de derrame.

En la Tabla 13, se presenta un resumen de los recursos disponibles que se tienen contemplados como parte de los equipos de respuesta a emergencias.

**Tabla 13 Recursos disponibles para la atención de respuesta por derrame**

Recursos	Descripción
Personal en el país	Comandante de incidente/ Gerente del País – 1 Supervisor- 1 Encargados de respuesta -5 20 personas adicionales disponibles a través de socios locales en caso de ser necesario
Soporte marino/ aviación	Marino – Acceso con embarcaciones propias en conjunto con soporte adicional disponible a través de socios locales.

Recursos	Descripción
	Aviación – Compañía con avión propio ubicado en Florida con 6 horas de vuelos a las operaciones en México.
Ubicación Nivel 3/Tiempo de respuesta	La ubicación más cercana es los Estados Unidos, incluyendo bases a lo largo de la costa del Golfo de México. Recursos parciales para respuesta en 48 horas y adicionales disponibles para los siguientes 3-5 días.
Dispersantes	Estados Unidos – 100 ton Corexit 9500, 50 ton Finasol México – 16 ton Coreix 9500 Reino Unido – 50 ton Slickgone, 50 ton Finasol Dubai – 25 ton Slickgone y Corexit 9500
Recursos de contención en mar abierto	5 sistemas de recuperación y contención en tierra incluidos 2 embarcaciones para un total de 7 sistemas para mar abierto. Además 6 botes con 100 unidades con operación para dispersantes.
Equipo de desnatación	7 desnatadores para recuperación de más de 50 ton por hora, con 4 más ubicados en línea de costa para recuperación de 30 ton por hora localizados en Dos Bocas.

Fuente: Información provista por Fieldwood Energy. Octubre de 2016.

## ***ANEXO 1***

***Recorte original de la publicación***

# Protexa provoca caos vehicular

LA EMPRESA PROPIEDAD DE LA FAMILIA LOBO MORALES, SE APROPIÓ DE LAS CALLES Y PUSO A SERVICIO A LAS CORPORACIONES POLICIAZAS.

**CD. DEL CARMEN**

AGUSTÍN FERRER  
CAMPECHE HOY

**P**arador "bifásico" gas y aceite, de la carretera Carmen Puerto Real al Puerto Industrial, la petrolera Protexa dispuso de un macro operativo que incluyó a trabajadores de la Comisión Federal de Electricidad (CFE) y la policía municipal.

Deteniendo el tráfico pasada la medianoche de ayer, y usando como medio de transporte a la compañía Acción Logística Integral (ALI), Protexa transportó con lentitud dicho tanque.

Quienes arribaban a la ciudad debían esperar los lento movimientos que hacia la compañía ALI, contratada para trasladar el tanque propiedad de Protexa.

Babajan y subían las cuchillas de los postes de la CFE cuando la altura del tanque pegaba en líneas de alta tensión, que por segundos provocaba la suspensión de energía eléctrica.

El amplio convoy era custodiado por dos patrullas enviadas por el titular de la corporación Jonny Alberto Morales León, que prefirió atender el tráfico que ocasionó Protexa que cuidar a la población.

Una mujer policía corría de un lado a otro auxiliando en la vialidad, todo para obedecer las indicaciones de su "jefe".

Protexa para evitar que resultara involucrada en estas peligrosas maniobras, tapó los logos de sus unidades pesadas.

Sin embargo, las decenas de obreros que custodiaron la pesada carga, traían overoles de la compañía regiomontana.



. El tanque que sería llevado al Puerto Industrial provocó caos en el tránsito, sin embargo, fue custodiado por la policía municipal.



Se volvió lento el tráfico vehicular sobre la Isla de Tris, y todos debían esperar que se movieran las unidades al servicio de Protexa

## Jorge Fuerte irresponsable

**CD. DEL CARMEN**

AGUSTÍN FERRER  
CAMPECHE HOY

Rectificando que Jorge Fuerte Mancera es el titular del Colegio Gardner, algunos habitantes del fraccionamiento Héroes de Nacozari, pidieron al funcionario educativo que se disculpe con la comunidad, por atentar contra el medio ambiente.

Después de que hace dos días, Jorge Fuerte –aunque ayer por una omisión se dijo que su nombre era René– introdujo su lujoso carro a un predio que es conservado por vecinos, estos pidieron que el director del colegio explique su mal proceder.

### DOBLE MORAL

Más que disculparse –Jorge Fuerte Mancera– debería darle una explicación a sus alumnos, porque pregonó tener la mejor escuela del Carmen, pero da un pésimo ejemplo.

Usa una doble moral, ya que exige que su alumnado tenga una buena educación, pero actúa como un pelafustán ante la comunidad, dice una vecina.

### ES JORGE

Por un error se le confundió con el señor René, pero en realidad su nombre es Jorge Fuerte Mancera, quien acabó con algunas plantas sembradas en un predio, señaló otra vecina.

Ojalá que la policía le aplique una sanción ejemplar, porque de lo contrario volverá a delinquir administrativamente.



Fotografía: Redacción

Jorge Fuerte Mancera, director del Gardner debe pedir una disculpa pública a la comunidad

## AVISO DE EVALUACIÓN DE IMPACTO AMBIENTAL

Con la finalidad de garantizar el derecho a la información y de la participación ciudadana y en cumplimiento al Artículo 34 párrafo 3º, fracción I de la Ley General del Equilibrio Ecológico y Protección al Ambiente, FIELDWOOD ENERGY, informa acerca de la siguiente obra, que se pretende realizar en la provincia petrolera Cuenca del Sureste y cuya Manifestación de Impacto Ambiental en Modalidad Regional (MIA-R), se encuentra en procedimiento de evaluación por parte de la Agencia de Seguridad Energía y Ambiente (ASEA).

### Nombre de la persona moral responsable del Proyecto:

**FIELDWOOD ENERGY E&P MÉXICO, S. DE R.L. DE C.V.**

### Nombre y descripción del proyecto:

El "Proyecto Integral de Extracción Ichalkil-Pokoch" fue asignado mediante contrato CNH-R01-L02-A4/2015 y consiste en evaluar el potencial petrolero de los campos Ichalkil y Pokoch. El proyecto comprende la perforación de pozos, la instalación de plataformas de explotación de diferentes tipos y dimensiones, así como la instalación de ductos para el transporte de la producción. El Proyecto se divide contractualmente en dos Etapas: La Etapa de Evaluación con una duración de 2 años en la cual se perfuran dos pozos y se reevalúa la información existente de los campos y la Etapa de Desarrollo inicia en enero de 2018 y termina en enero de 2041.

### Ubicación y referencia a los ecosistemas existentes y su condición al momento del estudio:

El Proyecto se llevará a cabo en la provincia petrolera Cuenca del Sureste, con un área de 58 km<sup>2</sup>, ubicados frente a las costas del estado de Campeche en la Zona Económica Exclusiva (ZEE) del Golfo de México, a una distancia aproximada de 40 km de las costas, partiendo del vértice más cercano en línea recta a costa que corresponde al campo Ichalkil. Debido a la extensión del área de estudio, la misma cuenta con muchas especies de flora y fauna, desde plancton hasta mamíferos marinos, pasando por comunidades benthicas, corales peces y tortugas marinas. El desarrollo del Proyecto se prevé que no altere a la calidad de los pueblos de Dos Bocas o Isla del Carmen, ya que las actividades actuales en los mismos hacen que los buques del proyecto realicen operaciones adicionales marginales.

### Principales efectos ambientales que se pueden generar y sus medidas de mitigación:

De acuerdo a la evaluación descrita en la MIA-R, debido a las características del "Proyecto Integral de Extracción Ichalkil-Pokoch", no se generarán impactos directos, acumulativos, sinérgicos o residuales significativos en el entorno físico y biológico. Adicionalmente, se considerarán beneficios económicos favorables al país por la posible apertura del sector de hidrocarburos en sus aguas del Golfo de México, ya que se genera la posibilidad de crear nuevos empleos lo cual ayudará a mejorar las condiciones de la población, así como generar nuevas oportunidades de desarrollo en los diferentes aspectos. A pesar de que en ninguna etapa del Proyecto se esperan impactos moderados o significantes, se tendrán medidas de manejo ambiental, orientadas a prevenir, mitigar y compensar la huella ecológica del Proyecto, tales como: medidas de conservación de la calidad del aire, medidas para el control de ruido y manejo de residuos sólidos y líquidos.

## ***ANEXO 2***

***Oficio No. 220.1777/2016 y Memorandum  
Daños Preexistentes***



COMISIÓN NACIONAL DE HIDROCARBUROS  
SECRETARÍA EJECUTIVA

Oficio No.220.1777/2016

Comisión Nacional de  
Hidrocarburos

Ciudad de México, a 26 de agosto de 2016.

**Asunto:** Se notifica aprobación de daños preexistentes.

**SR. ANDRÉS BRÜGMANN BALMASEDA  
REPRESENTANTE LEGAL DEL CONTRATISTA  
FIELDWOOD ENERGY E&P MÉXICO, S. DE R.L. DE C.V.  
P R E S E N T E**

Hago referencia al Contrato para la Extracción de Hidrocarburos bajo la modalidad de Producción Compartida No. CNH-R01-L02-A4/2015 (en adelante, Contrato), celebrado entre esta Comisión Nacional de Hidrocarburos (en adelante, Comisión) y Fieldwood Energy E&P México, S. de R.L. de C.V. (en adelante Operador) y Petrobal Upstream Delta 1, S.A de C.V el 7 de enero del 2016.

Al respecto, atendiendo a su escrito de fecha 5 de julio de 2016, mediante los cuales presentó a esta Comisión y a la Agencia Nacional de Seguridad Industrial y Protección al Medio Ambiente del Sector Hidrocarburos (en adelante, Agencia) el informe de la Línea Base Ambiental, me permito hacer de su conocimiento que la Dirección General de Asignaciones y Contratos de Exploración de esta Comisión emitió el MEMO No.261.132/2016, el cual se adjunta al presente en copia simple y se notifica del mismo.

El presente oficio se emite con fundamento en los artículos 1,2, fracción III, y 43 Ter de la Ley Orgánica de la Administración Pública Federal; 2, fracción I, 3, 5, 22, fracciones I, X, XXIV y XXVII, y 25, fracciones VII y XI de la Ley de los Órganos Reguladores Coordinados en Materia Energética; 32 de la Ley Federal de Procedimiento Administrativo; 10, fracción II y III, 11, 14, fracción II, 18, fracciones VIII y IX, 19 fracción XIII, así como 21, fracción X del Reglamento Interno de la Comisión Nacional de Hidrocarburos y del oficio de instrucción 200.011/2015 signado por el Comisionado Presidente de este Órgano Regulador Coordinado.

Sin otro particular, reciba un cordial saludo.

ATENTAMENTE  
LA SECRETARÍA EJECUTIVA

CARLA GABRIELA GONZÁLEZ RODRÍGUEZ

C.c.p.

Mtro. Juan Carlos Zepeda Molina. - Comisionado Presidente de la CNH. - Para su conocimiento.  
Mtro. Gaspar Franco Hernández. - Comisionado CNH. - Para su conocimiento.  
Mtro. Fausto Álvarez Hernández. - Titular de la Unidad de Administración Técnica de Asignaciones y Contratos de la CNH. - Para su conocimiento.  
Lic. Marco Antonio de la Peña Sánchez. - Titular de la Unidad Jurídica de la CNH. Para su conocimiento.  
Mtra. Teresa Angelina Gallegos Ramírez. - Directora General de Contratos de la CNH. - Para su conocimiento.  
Mtro. Alfonso Reyes Pimentel. - Director General de Asignaciones y Contratos de Exploración. - Para su conocimiento.  
Ing. Juan Raúl Gómez Obele. - Director General de Gestión de Exploración y Extracción de Recursos Convencionales. - ASEA. - Para su conocimiento.  
Ing. Antonio Hernández Patiño. - Director General de Gestión de Exploración y Extracción de Recursos No Convencionales Marítimos. - ASEA. - Para su conocimiento. - Control de gestión. - En atención al torno 1544.



Comisión Nacional  
de Hidrocarburos

UNIDAD DE ADMINISTRACIÓN TÉCNICA DE  
ASIGNACIONES Y CONTRATOS  
DIRECCIÓN GENERAL DE ASIGNACIONES Y  
CONTRATOS DE EXPLORACIÓN



MEMO No. 261.132/2016

Ciudad de México, a 26 de agosto de 2016

**Asunto:** Aprobación de Daños Preeexistentes en relación al Contrato CNH-R01-L02-A4/2015.

**DE: MTRO. ALFONSO REYES PIMENTEL**  
**DIRECTOR GENERAL DE ASIGNACIONES Y CONTRATOS DE EXPLORACIÓN**

**PARA: LIC. CARLA GABRIELA GONZÁLEZ RODRÍGUEZ**  
**SECRETARIA EJECUTIVA DE LA COMISIÓN NACIONAL DE HIDROCARBUROS**

Hago referencia al Contrato para la Extracción de Hidrocarburos bajo la modalidad de Producción Compartida No. CNH-R01-L02-A4/2015 (en adelante Contrato), celebrado entre esta Comisión Nacional de Hidrocarburos (en adelante Comisión) y Fieldwood Energy E&P México, S. de R.L. de C.V. (en adelante Operador) y Petrobal Upstream Delta 1, S.A de C.V el 7 de enero del 2016.

Sobre el particular, me permito hacer de su conocimiento que el 5 de julio del año en curso, el Operador ingresó ante esta Comisión y ante la Agencia Nacional de Seguridad Industrial y Protección al Medio Ambiente del Sector Hidrocarburos (en lo sucesivo, Agencia) el informe de la línea base ambiental correspondiente al área contractual 4, en cumplimiento a las cláusulas 3.4, inciso (d) y 13.4 del Contrato, de igual forma, en la misma fecha, se notificó la existencia de los daños preeistentes identificados.

En respuesta a dicho informe y en términos de la cláusula 13.4 del Contrato; el 19 de agosto de 2016, la Agencia remitió a esta Comisión el oficio ASE/UGI/DGGEERC/0903/2016, mediante el cual aprobó la línea base ambiental presentada por el Operador y determinó como daños preeistentes los siguientes:

1. Emanaciones de gas detectadas en los cabezales de los pozos Ichalkil-1 y Pokoch-1, en virtud de que dichas emanaciones son consideradas como liberación de material que puede originar afectaciones al medio marino donde ésta ocurre y que no ha sido remediada para impedir su dispersión.

Por lo que respecta a la aprobación de la Comisión, se advierte que ésta es competente para emitirla en términos de la cláusula 13.4 del Contrato y el artículo 31, fracción XII de la Ley de Hidrocarburos; mientras que la evaluación técnica específica es competencia de la Agencia en razón de la materia, en términos del artículo 5, fracciones III y VI de la Ley de la Agencia, dicha aprobación debe ser emitida por esta Dirección General en función de la evaluación realizada por la propia Agencia y previa validación de la Unidad Jurídica de esta Comisión. Lo anterior, en términos del Acuerdo CNH.E.32.001/16, por el que la Comisión Nacional de Hidrocarburos autoriza a la Unidad de Administración Técnica de Asignaciones y Contratos, por conducto de la Dirección General de Asignaciones y Contratos de Exploración, previa validación de la Unidad Jurídica, para que lleve a cabo diversos actos previstos en los contratos para la exploración y extracción de hidrocarburos, emitido el 1 de agosto del año en curso por el Órgano de Gobierno de éste Órgano Regulador Coordinado.


**UNIDAD DE ADMINISTRACIÓN TÉCNICA DE  
ASIGNACIONES Y CONTRATOS  
DIRECCIÓN GENERAL DE ASIGNACIONES Y  
CONTRATOS DE EXPLORACIÓN****MEMO No. 261.132/2016**

En virtud de lo anterior, en función de la evaluación realizada por la Agencia mediante oficio ASEA/UGI/DGGEERC/0903/2016, el cual se adjunta al presente para pronta referencia, esta Dirección General de Asignaciones y Contratos de Exploración aprueba los daños preexistentes presentados por el Operador en el informe de la línea base ambiental y su respectiva notificación, los cuales se encuentran referidos con antelación, en los mismos términos señalados en el oficio en cita, toda vez que se cuenta con la validación de la Unidad Jurídica como consta al calce; por lo que le solicito atentamente notificar al Operador la aprobación de los daños preexistentes descritos en el presente documento.

Lo anterior, con fundamento en los artículos 1, 2, fracción III, y 43 Ter de la Ley Orgánica de la Administración Pública Federal; 2, fracción I, 3, 4, 22, fracciones I, III, X y XXVII, y 38, fracción III, de la Ley de los Órganos Reguladores Coordinados en Materia Energética; 31, fracciones VI y XII de la Ley de Hidrocarburos; 10, fracción VII, inciso a., 11, 19, fracción XIV, 21, fracciones X, XII y XXVI, y 32, fracción XIV del Reglamento Interno de la Comisión Nacional de Hidrocarburos, así como en la cláusula 13.4 del Contrato y el Acuerdo CNH.E.32.001/16.

Sin otro particular, reciba un cordial saludo.

ATENTAMENTE  
DIRECTOR GENERAL



Mtro. ALFONSO REYES PIMENTEL

Validación Jurídica  
TITULAR DE LA UNIDAD JURÍDICA

LIC. MARCO ANTONIO DE LA PEÑA SÁNCHEZ

La presente validación se emite con fundamento en el artículo 19, fracción XIV del Reglamento Interno de la Comisión Nacional de Hidrocarburos, en relación con el Acuerdo CNH.E.32.001/16; únicamente en cuanto al contenido legal del presente oficio, con base en la documentación que se tuvo a la vista; por lo que no implica una validación de la información técnica contenida.

C.c.p. Mtro. Juan Carlos Zepeda Molina.- Comisionado Presidente de la CNH.- Para su conocimiento.

Mtro. Gaspar Franco Hernandez.- Comisionado CNH.- Para su conocimiento.

Mtro. Fausto Álvarez Hernández.- Titular de la Unidad de Administración Técnica de Asignaciones y Contratos de la CNH.- Para su conocimiento.

Lic. Marco Antonio de la Peña Sánchez.- Titular de la Unidad Jurídica de la CNH. Para su conocimiento.

Mtra. Teresa Angelina Gallegos Ramírez. - Directora General de Contratos de la CNH.- Para su conocimiento.

## ***ANEXO 3***

### ***Ejemplo de resultados del modelo GEMSS-COSIM***

**Temporada de Secas**

Resumen de caracterización de punto de ebullición para:  
crudoFieldwood

Cor te	Punto ebull (deg f)	api gravedad (api unidad)	Gravedad especif (mt/m**3)	Fracci ón masa ( % )	Peso molecul (gm/mol)
1	122.4	-99.0	0.870	0.010	98.0
2	395.4	-99.0	1.078	0.009	204.8
3	456.3	-99.0	1.107	0.011	238.8
4	57.2	-99.0	0.662	0.050	86.2
5	124.7	-99.0	0.704	0.056	116.9
6	252.8	-99.0	0.765	0.096	199.6
7	345.4	-99.0	0.787	0.135	279.6
8	400.6	-99.0	0.788	0.167	347.4
9	458.2	-99.0	0.985	0.212	439.4
10	503.6	-99.0	0.985	0.254	527.2

Tamaño de gota de aceite para 1

= 100 micras

Tamaño de gota de aceite para 2

= 250 micras

Tamaño de gota de aceite para 3

= 500 micras

Tamaño de gota de aceite para 4

= 1000 micras

Energía de oleaje: 0.100000E+04J/m^2

diámetro mínimo de gota : 50micras

diámetro máximo de gota : 500micras

GEMSS® LICENSE TERMS

These license terms are an agreement  
between GEMSS Development and Distribution  
LLC y usted. Por favor leerlos.

Los términos de licencia se aplican al  
software arriba mencionado, el cual incluye  
los soportes en los que lo haya recibido, si  
los hay. Los términos también se aplican a  
cualquier actualización, suplementos,  
servicios basados en Internet, y servicios de  
apoyo para este software, a menos que haya  
otros términos aplicables a dichos elementos.

Si es así, se aplicarán dichos términos.

Si cumple con estos términos de licencia,  
usted tiene los derechos y obligaciones que se  
indican a continuación para cada licencia que

adquiera. CON EL USO DEL SOFTWARE, USTED  
ACEPTA ESTOS TÉRMINOS. SI NO ACEPTA, NO USE EL  
SOFTWARE.

1. RESUMEN Y DEFINICIONES.

- a. **Modelo de licencia.** El software está disponible en una copia por cada base por usuario individual. Ninguna otra persona puede utilizar el software con la misma licencia al mismo tiempo.
- b. **GEMSS.** GEMSS® es el Sistema Generalizado de Modelización Ambiental para agua y es propiedad única y exclusiva de GEMSS Desarrollo y Distribución LLC. GEMSS® es una marca comercial registrada de GEMSS Desarrollo y Distribución LLC, que también es propietaria de los derechos de autor GEMSS ("Copyright © 1985-2006 GEMSS Desarrollo y Distribución LLC Reservados todos los derechos"). GEMSS® existe como código fuente y como código ejecutable. Excepto cuando se indique, el término "GEMSS®" que se utiliza en la licencia se refiere al código ejecutable.
- c. **Código fuente.** La combinación de Fortran y las instrucciones de Visual Basic que cuando se compila y se enlaza, crea el ejecutable GEMSS®.
- d. **Ejecutable.** La representación binaria del código fuente GEMS®.
- e. **Solicitud.** Una aplicación GEMSS® consiste en la GEMSS® ejecutable y el conjunto de archivos de entrada con formato, incluidos los datos batimétricos, los datos de condición de contorno variables en el tiempo, y archivos de control, que en conjunto representan un cuerpo de agua específico (río, lago, embalse, depósito, estuario o región costera) cuando se utiliza con el ejecutable suministrado.

---

## 2. INSTALACIÓN Y DERECHOS DE USO.

- a. Dispositivo con licencia. El dispositivo con licencia es el dispositivo en el que se utiliza el software. Puede instalar y utilizar una copia del software en el dispositivo con licencia.
- b. Dispositivo portátil. Es posible instalar otra copia en un dispositivo portátil para su uso por el usuario principal del dispositivo con licencia.
- c. Separación de componentes. Los componentes del software se licencia como una sola unidad. No puede separar los componentes e instalarlas en diferentes dispositivos.

## 3. REQUERIMIENTOS ADICIONALES DE LICENCIA.

- a. Alcance de la licencia. El software se licencia, no se vende.

Este contrato sólo le otorga algunos derechos de uso y distribuir el software. GEMSS Desarrollo y Distribución LLC se reserva todos los demás derechos. A menos que la ley aplicable le otorgue más derechos a pesar de esta limitación, puede utilizar el software tal como se permite expresamente en este contrato. Al hacerlo, deberá ajustarse a las limitaciones técnicas del software que sólo permiten utilizarlo de determinadas formas. No deberías

- " Redistributions GEMSS®, los ejemplos de aplicaciones y archivos de soporte proporcionados en el sitio ftp o las instrucciones de ftp descarga, excepto como se indica en las disposiciones específicas de esta licencia;
- " Ingeniería inversa, descompilar y desensamblar el software, excepto y únicamente en la medida en que la ley aplicable lo permita expresamente, a pesar de esta limitación;
- " Hacer más copias del software de las que especifica este contrato o permite la legislación vigente, a pesar de esta limitación;
- " Publicar el software para que otros lo copien
- " Alquilar, arrendar o prestar el software; o
- " Utilizar el software para prestar servicios de alojamiento de software comercial.

- b. Vigencia de la licencia. La licencia se concede por un período de un año que comienza el día en las instrucciones del ftp son proporcionados a usted.

Las actualizaciones para un período de la duración de la licencia se incluyen en esta licencia y puede obtenerse en el sitio ftp desde la que se descarga el software. La licencia puede ser renovada si se solicita al final de la vigencia de la licencia.

- c. Los requisitos de reporte. Usted se compromete a

- presentar un breve documento que resume su experiencia con GEMS® al final de la vigencia de la licencia.
- d. Copia de respaldo. Usted puede hacer una (1) copia de seguridad del software. Puede usarlo sólo para volver a instalar el software.
4. DOCUMENTACIÓN. Cualquier persona que tenga acceso válido a su equipo o a la red interna puede copiar y utilizar la documentación a efectos de consulta internos.
5. TRANSFERENCIA A OTRO DISPOSITIVO. Puede desinstalar el software e instalarlo en otro dispositivo para su uso. El usuario no puede hacerlo para compartir esta licencia entre dispositivos.
6. RESTRICCIONES DE EXPORTACIÓN. El software está sujeto a las leyes y regulaciones de exportación de Estados Unidos. Usted debe cumplir con todas las leyes de exportación nacionales e internacionales y reglamentos que se aplican Al software. Estas leyes incluyen restricciones sobre destinos, usuarios finales y uso final.
7. SERVICIOS DE SOPORTE TÉCNICO. Debido a que este software se suministra "tal cual", JUEGOS Desarrollo y Distribución LLC no proporcionarán servicios de apoyo para ella a menos acordado en un contrato independiente.
8. ACUERDO COMPLETO. Este acuerdo (incluyendo la garantía más adelante), y los términos de suplementos, actualizaciones, servicios basados en Internet y servicios de soporte que usted utilice, constituyen el contrato para los servicios de software y soporte.
9. LEY APPLICABLE.
- a. Estados Unidos. Si ha adquirido el software en los Estados Unidos, la ley del estado de Washington rige la interpretación de este acuerdo y se aplica a las reclamaciones por incumplimiento del mismo, independientemente de los conflictos de leyes. Las leyes del estado en el que rigen en vivo todas las demás reclamaciones, incluidas las bajo las leyes de protección al consumidor, leyes de competencia desleal o por responsabilidad civil.
- b. Fuera de los Estados Unidos. Si adquirió el software en otro país, se aplicará la legislación de ese país.

---

10. EFECTO LEGAL. Este acuerdo describe ciertos aspectos legales

Es posible que tenga otros derechos conforme a las leyes de su estado o país. Usted también puede tener derechos con respecto a la parte de la que adquirió el software. Este contrato no modifica sus derechos bajo las leyes de su estado o país si las leyes de su estado o país no permiten que lo haga.

11. Renuncia de garantía. El software está bajo licencia "tal cual".

Usted asume el riesgo de utilizarlo. GEMSS Desarrollo y Distribución LLC no da ninguna garantía expresa, garantías o condiciones. Es posible que tenga otros derechos como consumidor en virtud de sus leyes locales que el presente contrato no pueda modificar.

En la medida permitida por la legislación local, Desarrollo GEMSS y Distribución LLC excluye las garantías implícitas de comerciabilidad, adecuación para un propósito particular y no infracción.

12. LIMITACIÓN Y EXCLUSIÓN DE LA RESPONSABILIDAD.

Puede recuperarse de GEMSS Desarrollo y Distribución LLC y sus proveedores solamente los daños directos hasta EE.UU. \$ 0,01.

No se puede recuperar ningún otro daño, incluyendo la pérdida de beneficios, consecuentes, especiales, indirectos o incidentales.

Esta limitación se aplica a

"Todo lo relacionado con el software, servicios, contenidos (incluido el código) de sitios de Internet de terceros, o programas de terceros, así

"reclamaciones por incumplimiento de contrato, incumplimiento de garantía o condición, responsabilidad objetiva, negligencia u otra responsabilidad extracontractual en la medida permitida por la ley aplicable.

También se aplica incluso si el desarrollo y distribución GEMSS LLC conocía o debería haber conocido la posibilidad de los daños y perjuicios.

La limitación o exclusión anterior no se aplique en su debido país no permite la exclusión o limitación de daños incidentales, consecuentes o de otro tipo.

\*\* Dirección de contacto

\*\*\*\*\*

---

Venkat S. Kolluru  
Surfacewater Modeling  
Group  
Environmental Resource Management  
350 Eagleview  
Road Suite 200  
Exton, PA 19341-1155  
(610) 524-3500  
(610) 524-3566(fax)  
(610) 524-3654(directo)  
e-mail: [venkat.kolluru@erm.com](mailto:venkat.kolluru@erm.com)

\*\*\*\*\*

Nombre del escenario:

Fecha : Lun Sep 19

\*\*\*\*\*

\*\*\*\* Encabezados del archivo de control

Paso\_Tiempo, dt = 720.00 s

Velocidad del viento a 10 m altura: -  
9.474378E+00 m/sec  
Dirección dc viento: 7.512408E+01 deg

Tiempo in = 2010 4 1 0: 0  
Tiempo = 2010 4 1 1:12  
Tiempo fin = 2010 5 1 0: 0

Masa total liberada = 3.908629E+01 ton  
Número total de partículas liberadas hasta el momento = 11

Paso\_Tiempo, dt = 720.00 s

Velocidad del viento a 10 m altura:  
9.470686E+00 m/sec  
Dirección de viento: 7.511635E+01 deg

Tiempo in = 2010 4 1 0: 0  
Tiempo = 2010 4 1 2: 0  
Tiempo fin = 2010 5 1 0: 0

Masa total liberada = 6.751269E+01 ton  
Número total de partículas liberadas hasta el momento = 19

Paso Tiempo, dt = 720.00 s

Velocidad del viento a 10 m altura:  
9.468448E+00 m/sec  
Dirección del viento: 7.512801E+01 deg

Tiempo in = 2010 4 1 0: 0  
Tiempo = 2010 4 1 3: 0  
Tiempo fin = 2010 5 1 0: 0

Masa total liberada = 1.030457E+02 ton  
Número total de partículas liberadas hasta el momento = 29

Paso tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:  
9.466382E+00 m/sec  
Dirección del viento: 7.512014E+01 deg

Tiempo in = 2010 4 1 0: 0  
Tiempo = 2010 4 1 4: 0  
Tiempo fin = 2010 5 1 0: 0

Masa total liberada = 1.385787E+02 ton  
Número total de partículas liberadas hasta el momento = 39

Paso tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:  
9.467360E+00 m/sec  
Dirección del viento: 7.511796E+01 deg

Tiempo in = 2010 4 1 0: 0  
Tiempo = 2010 4 1 5: 0  
Tiempo fin = 2010 5 1 0: 0

Masa total liberada = 1.741117E+02 ton  
Número total de partículas liberadas hasta el momento = 49

Paso\_tiempo, dt = 720.00 s

—

Velocidad del viento a 10 m de altura: —

9.474083E+00 m/sec

Dirección del viento: 7.515710E+01 deg

Tiempo in = 2010 4 1 0: 0

Tiempo = 2010 4 1 6: 0

Tiempo fin = 2010 5 1 0: 0

Masa total liberada = 2.096447E+02 ton

Número total de partículas liberadas hasta el momento =

59

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:

9.293628E+00 m/sec

Dirección del viento: 8.000859E+01 deg

Tiempo in = 2010 4 1 0: 0

Tiempo = 2010 4 1 7: 0

Tiempo fin = 2010 5 1 0: 0

Masa total liberada = 2.451776E+02 ton

Número total de partículas liberadas hasta el momento =

69

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura: —

9.171229E+00 m/sec

Dirección del viento: 8.501350E+01 deg

Tiempo in = 2010 4 1 0: 0

Tiempo = 2010 4 1 8: 0

Tiempo fin = 2010 5 1 0: 0

Masa total liberada = 2.807107E+02 ton

Número total de partículas liberadas hasta el momento =

79

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura: —

9.129771E+00 m/sec

Dirección del viento: 9.011140E+01 deg

Tiempo in = 2010 4 1 0: 0  
Tiempo = 2010 4 1 9: 0  
Tiempo fin = 2010 5 1 0: 0

Masa total liberada = 3.162439E+02 ton

Número total de partículas liberadas hasta el momento = 89

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura: -

9.172581E+00 m/sec

Dirección del viento: 9.522858E+01 deg

Tiempo in = 2010 4 1 0: 0  
Tiempo = 2010 4 1 10: 0  
Tiempo fin = 2010 5 1 0: 0

Secuencia hasta completar 3600 partículas liberadas en el siguiente esquema:

Tiempo in = 2010 4 16 0: 0  
Tiempo = 2010 5 16 10: 0  
Tiempo fin = 2010 5 16 0: 0

**Temporada de frentes fríos anticiclónicos**

Resumen de caracterización de punto de ebullición para:  
crudoFieldwood

Cor te	Punto ebull (deg f)	api gravedad (api unidad)	Gravedad especif (mt/m**3)	Fracci ón masa ( % )	Peso molecul (gm/mol)
1	122.4	-99.0	0.870	0.010	98.0
2	395.4	-99.0	1.078	0.009	204.8
3	456.3	-99.0	1.107	0.011	238.8
4	57.2	-99.0	0.662	0.050	86.2
5	124.7	-99.0	0.704	0.056	116.9
6	252.8	-99.0	0.765	0.096	199.6
7	345.4	-99.0	0.787	0.135	279.6
8	400.6	-99.0	0.788	0.167	347.4
9	458.2	-99.0	0.985	0.212	439.4
10	503.6	-99.0	0.985	0.254	527.2

Tamaño de gota de aceite para 1

= 100 micras

Tamaño de gota de aceite para 2

= 250 micras

Tamaño de gota de aceite para 3

= 500 micras

Tamaño de gota de aceite para 4

= 1000 micras

Energía de oleaje: 0.100000E+04J/m^2

diámetro mínimo de gota : 50micras

diámetro máximo de gota : 500micras

GEMSS® LICENSE TERMS

These license terms are an agreement  
between GEMSS Development and Distribution  
LLC y usted. Por favor leerlos.

Los términos de licencia se aplican al  
software arriba mencionado, el cual incluye  
los soportes en los que lo haya recibido, si  
los hay. Los términos también se aplican a  
cualquier actualización, suplementos,  
servicios basados en Internet, y servicios de  
apoyo para este software, a menos que haya  
otros términos aplicables a dichos elementos.

Si es así, se aplicarán dichos términos.

Si cumple con estos términos de licencia,  
usted tiene los derechos y obligaciones que se  
indican a continuación para cada licencia que

adquiera. CON EL USO DEL SOFTWARE, USTED  
ACEPTA ESTOS TÉRMINOS. SI NO ACEPTA, NO USE EL  
SOFTWARE.

1. RESUMEN Y DEFINICIONES.

- f. **Modelo de licencia.** El software está disponible en una copia por cada base por usuario individual. Ninguna otra persona puede utilizar el software con la misma licencia al mismo tiempo.
- g. **GEMSS.** GEMSS® es el Sistema Generalizado de Modelización Ambiental para agua y es propiedad única y exclusiva de GEMSS Desarrollo y Distribución LLC. GEMSS® es una marca comercial registrada de GEMSS Desarrollo y Distribución LLC, que también es propietaria de los derechos de autor GEMSS ("Copyright © 1985-2006 GEMSS Desarrollo y Distribución LLC Reservados todos los derechos"). GEMSS® existe como código fuente y como código ejecutable. Excepto cuando se indique, el término "GEMSS®" que se utiliza en la licencia se refiere al código ejecutable.
- h. **Código fuente.** La combinación de Fortran y las instrucciones de Visual Basic que cuando se compila y se enlaza, crea el ejecutable GEMSS®.
- i. **Ejecutable.** La representación binaria del código fuente GEMS®.
- j. **Solicitud.** Una aplicación GEMSS® consiste en la GEMSS® ejecutable y el conjunto de archivos de entrada con formato, incluidos los datos batimétricos, los datos de condición de contorno variables en el tiempo, y archivos de control, que en conjunto representan un cuerpo de agua específico (río, lago, embalse, depósito, estuario o región costera) cuando se utiliza con el ejecutable suministrado.

---

13. INSTALACIÓN Y DERECHOS DE USO.

- a. Dispositivo con licencia. El dispositivo con licencia es el dispositivo en el que se utiliza el software. Puede instalar y utilizar una copia del software en el dispositivo con licencia.
- b. Dispositivo portátil. Es posible instalar otra copia en un dispositivo portátil para su uso por el usuario principal del dispositivo con licencia.
- c. Separación de componentes. Los componentes del software se licencia como una sola unidad. No puede separar los componentes e instalarlas en diferentes dispositivos.

14. REQUERIMIENTOS ADICIONALES DE LICENCIA.

- a. Alcance de la licencia. El software se licencia, no se vende.

Este contrato sólo le otorga algunos derechos de uso y distribuir el software. GEMSS Desarrollo y Distribución LLC se reserva todos los demás derechos. A menos que la ley aplicable le otorgue más derechos a pesar de esta limitación, puede utilizar el software tal como se permite expresamente en este contrato. Al hacerlo, deberá ajustarse a las limitaciones técnicas del software que sólo permiten utilizarlo de determinadas formas. No deberías

- " Redistributions GEMSS®, los ejemplos de aplicaciones y archivos de soporte proporcionados en el sitio ftp o las instrucciones de ftp descarga, excepto como se indica en las disposiciones específicas de esta licencia;
- " Ingeniería inversa, descompilar y desensamblar el software, excepto y únicamente en la medida en que la ley aplicable lo permita expresamente, a pesar de esta limitación;
- " Hacer más copias del software de las que especifica este contrato o permite la legislación vigente, a pesar de esta limitación;
- " Publicar el software para que otros lo copien
- " Alquilar, arrendar o prestar el software; o
- " Utilizar el software para prestar servicios de alojamiento de software comercial.

- b. Vigencia de la licencia. La licencia se concede por un período de un año que comienza el día en las instrucciones del ftp son proporcionados a usted.

Las actualizaciones para un período de la duración de la licencia se incluyen en esta licencia y puede obtenerse en el sitio ftp desde la que se descarga el software. La licencia puede ser renovada si se solicita al final de la vigencia de la licencia.

- c. Los requisitos de reporte. Usted se compromete a

- presentar un breve documento que resume su experiencia con GEMS® al final de la vigencia de la licencia.
- d. Copia de respaldo. Usted puede hacer una (1) copia de seguridad del software. Puede usarlo sólo para volver a instalar el software.
15. DOCUMENTACIÓN. Cualquier persona que tenga acceso válido a su equipo o a la red interna puede copiar y utilizar la documentación a efectos de consulta internos.
16. TRANSFERENCIA A OTRO DISPOSITIVO. Puede desinstalar el software e instalarlo en otro dispositivo para su uso. El usuario no puede hacerlo para compartir esta licencia entre dispositivos.
17. RESTRICCIONES DE EXPORTACIÓN. El software está sujeto a las leyes y regulaciones de exportación de Estados Unidos. Usted debe cumplir con todas las leyes de exportación nacionales e internacionales y reglamentos que se aplican Al software. Estas leyes incluyen restricciones sobre destinos, usuarios finales y uso final.
18. SERVICIOS DE SOPORTE TÉCNICO. Debido a que este software se suministra "tal cual", JUEGOS Desarrollo y Distribución LLC no proporcionarán servicios de apoyo para ella a menos acordado en un contrato independiente.
19. ACUERDO COMPLETO. Este acuerdo (incluyendo la garantía más adelante), y los términos de suplementos, actualizaciones, servicios basados en Internet y servicios de soporte que usted utilice, constituyen el contrato para los servicios de software y soporte.
20. LEY APPLICABLE.
- a. Estados Unidos. Si ha adquirido el software en los Estados Unidos, la ley del estado de Washington rige la interpretación de este acuerdo y se aplica a las reclamaciones por incumplimiento del mismo, independientemente de los conflictos de leyes. Las leyes del estado en el que rigen en vivo todas las demás reclamaciones, incluidas las bajo las leyes de protección al consumidor, leyes de competencia desleal o por responsabilidad civil.
- b. Fuera de los Estados Unidos. Si adquirió el software en otro país, se aplicará la legislación de ese país.

21. **EFFECTO LEGAL.** Este acuerdo describe ciertos aspectos legales

Es posible que tenga otros derechos conforme a las leyes de su estado o país. Usted también puede tener derechos con respecto a la parte de la que adquirió el software. Este contrato no modifica sus derechos bajo las leyes de su estado o país si las leyes de su estado o país no permiten que lo haga.

22. **Renuncia de garantía.** El software está bajo licencia "tal cual".

Usted asume el riesgo de utilizarlo. GEMSS Desarrollo y Distribución LLC no da ninguna garantía expresa, garantías o condiciones. Es posible que tenga otros derechos como consumidor en virtud de sus leyes locales que el presente contrato no pueda modificar.

En la medida permitida por la legislación local, Desarrollo GEMSS y Distribución LLC excluye las garantías implícitas de comerciabilidad, adecuación para un propósito particular y no infracción.

23. **LIMITACIÓN Y EXCLUSIÓN DE LA RESPONSABILIDAD.**

Puede recuperarse de GEMSS Desarrollo y Distribución LLC y sus proveedores solamente los daños directos hasta EE.UU. \$ 0,01.

No se puede recuperar ningún otro daño, incluyendo la pérdida de beneficios, consecuentes, especiales, indirectos o incidentales.

Esta limitación se aplica a

"Todo lo relacionado con el software, servicios, contenidos (incluido el código) de sitios de Internet de terceros, o programas de terceros, así

"reclamaciones por incumplimiento de contrato, incumplimiento de garantía o condición, responsabilidad objetiva, negligencia u otra responsabilidad extracontractual en la medida permitida por la ley aplicable.

También se aplica incluso si el desarrollo y distribución GEMSS LLC conocía o debería haber conocido la posibilidad de los daños y perjuicios.

La limitación o exclusión anterior no se aplique en su debido país no permite la exclusión o limitación de daños incidentales, consecuentes o de otro tipo.

\*\* Dirección de contacto

\*\*\*\*\*

Venkat S. Kolluru  
Surfacewater Modeling  
Group  
Environmental Resource Management  
350 Eagleview  
Road Suite 200  
Exton, PA 19341-1155  
(610) 524-3500  
(610) 524-3566(fax)  
(610) 524-3654(directo)  
e-mail: [venkat.kolluru@erm.com](mailto:venkat.kolluru@erm.com)

\*\*\*\*\*

Nombre del escenario:

/mnt/resource/GEMSS/Apps/Fieldwood/Output/FateAC4\_2009\_Dec/FateAC4\_2009\_Dec  
Fecha : Sun Sep 18

\*\*\*\*\*

\*\*\*\* Encabezados del archivo de control

Paso\_Tiempo, dt = 720.00 s

Velocidad del viento a 10 m altura: -  
5.940708E+00 m/sec  
Dirección de viento: 5.635004E+01 deg

Tiempo in = 2009 12 1 0: 0  
Tiempo = 2009 12 1 1:12  
Tiempo fin = 2009 12 31 0: 0

Masa total liberada = 3.908629E+01 ton  
Número total de partículas liberadas hasta el momento = 11

Paso\_Tiempo, dt = 720.00 s

Velocidad del viento a 10 m altura:  
6.074566E+00 m/sec  
Dirección de viento: 6.150255E+01 deg

Tiempo in = 2009 12 1 0: 0  
Tiempo = 2009 12 1 2: 0  
Tiempo fin = 2009 12 31 0: 0

Masa total liberada = 6.751269E+01 ton  
Número total de partículas liberadas hasta el momento = 19

Paso Tiempo, dt = 720.00 s

Velocidad del viento a 10 m altura:  
6.310746E+00 m/sec  
Dirección del viento: 6.749626E+01 deg

Tiempo in = 2009 12 1 0: 0  
Tiempo = 2009 12 1 3: 0  
Tiempo fin = 2009 12 31 0: 0

Masa total liberada = 1.030457E+02 ton  
Número total de partículas liberadas hasta el momento = 29

Paso tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:  
6.597721E+00 m/sec  
Dirección del viento: 7.314482E+01 deg

Tiempo in = 2009 12 1 0: 0  
Tiempo = 2009 12 1 4: 0  
Tiempo fin = 2009 12 31 0: 0

Masa total liberada = 1.385787E+02 ton  
Número total de partículas liberadas hasta el momento = 39

Paso tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:  
6.924342E+00 m/sec  
Dirección del viento: 7.841383E+01 deg

Tiempo in = 2009 12 1 0: 0  
Tiempo = 2009 12 1 5: 0  
Tiempo fin = 2009 12 31 0: 0

Masa total liberada = 1.741117E+02 ton  
Número total de partículas liberadas hasta el momento = 49

Paso\_tiempo, dt = 720.00 s

—

Velocidad del viento a 10 m de altura: —

7.324064E+00 m/sec

Dirección del viento: 8.298235E+01 deg

Tiempo in = 2009 12 1 0: 0

Tiempo = 2009 12 1 6: 0

Tiempo fin = 2009 12 31 0: 0

Masa total liberada = 2.096447E+02 ton

Número total de partículas liberadas hasta el momento =

59

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:

7.057885E+00 m/sec

Dirección del viento: 8.964858E+01 deg

Tiempo in = 2009 12 1 0: 0

Tiempo = 2009 12 1 7: 0

Tiempo fin = 2009 12 31 0: 0

Masa total liberada = 2.451776E+02 ton

Número total de partículas liberadas hasta el momento =

69

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura: —

6.896989E+00 m/sec

Dirección del viento: 9.668029E+01 deg

Tiempo in = 2009 12 1 0: 0

Tiempo = 2009 12 1 8: 0

Tiempo fin = 2009 12 31 0: 0

Masa total liberada = 2.807107E+02 ton

Número total de partículas liberadas hasta el momento =

79

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura: —

6.84551E+00 m/sec

Dirección del viento: 1.039369E+02 deg

Tiempo in = 2009 12 1 0: 0  
Tiempo = 2009 12 1 9: 0  
Tiempo fin = 2009 12 31 0: 0

Masa total liberada = 3.162439E+02 ton

Número total de partículas liberadas hasta el momento = 89

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura: -

6.900829E+00 m/sec

Dirección del viento: 1.111805E+02 deg

Tiempo in = 2009 12 1 0: 0  
Tiempo = 2009 12 1 10: 0  
Tiempo fin = 2009 12 31 0: 0

Secuencia hasta completar 3600 partículas liberadas en el siguiente esquema:

Tiempo in = 2009 12 15 0: 0  
Tiempo = 2010 1 16 0: 0  
Tiempo fin = 2010 1 16 0: 0

**Temporada de lluvias**

Resumen de caracterización de punto de ebullición para:  
crudoFieldwood

Cor te	Punto ebull (deg f)	api gravedad (api unidad)	Gravedad especif (mt/m**3)	Fracci ón masa ( % )	Peso molecul (gm/mol)
1	122.4	-99.0	0.870	0.010	98.0
2	395.4	-99.0	1.078	0.009	204.8
3	456.3	-99.0	1.107	0.011	238.8
4	57.2	-99.0	0.662	0.050	86.2
5	124.7	-99.0	0.704	0.056	116.9
6	252.8	-99.0	0.765	0.096	199.6
7	345.4	-99.0	0.787	0.135	279.6
8	400.6	-99.0	0.788	0.167	347.4
9	458.2	-99.0	0.985	0.212	439.4
10	503.6	-99.0	0.985	0.254	527.2

Tamaño de gota de aceite para 1  
= 100 micras

Tamaño de gota de aceite para 2  
= 250 micras

Tamaño de gota de aceite para 3  
= 500 micras

Tamaño de gota de aceite para 4  
= 1000 micras

Energía de oleaje: 0.100000E+04J/m^2

diámetro mínimo de gota : 50micras

diámetro máximo de gota : 500micras

GEMSS® LICENSE TERMS

These license terms are an agreement  
between GEMSS Development and Distribution  
LLC y usted. Por favor leerlos.

Los términos de licencia se aplican al  
software arriba mencionado, el cual incluye  
los soportes en los que lo haya recibido, si  
los hay. Los términos también se aplican a  
cualquier actualización, suplementos,  
servicios basados en Internet, y servicios de  
apoyo para este software, a menos que haya  
otros términos aplicables a dichos elementos.

Si es así, se aplicarán dichos términos.

Si cumple con estos términos de licencia,  
usted tiene los derechos y obligaciones que se  
indican a continuación para cada licencia que

adquiera. CON EL USO DEL SOFTWARE, USTED  
ACEPTA ESTOS TÉRMINOS. SI NO ACEPTA, NO USE EL  
SOFTWARE.

1. RESUMEN Y DEFINICIONES.

- k. **Modelo de licencia.** El software está disponible en una copia por cada base por usuario individual. Ninguna otra persona puede utilizar el software con la misma licencia al mismo tiempo.
- l. **GEMSS.** GEMSS® es el Sistema Generalizado de Modelización Ambiental para agua y es propiedad única y exclusiva de GEMSS Desarrollo y Distribución LLC. GEMSS® es una marca comercial registrada de GEMSS Desarrollo y Distribución LLC, que también es propietaria de los derechos de autor GEMSS ("Copyright © 1985-2006 GEMSS Desarrollo y Distribución LLC Reservados todos los derechos"). GEMSS® existe como código fuente y como código ejecutable. Excepto cuando se indique, el término "GEMSS®" que se utiliza en la licencia se refiere al código ejecutable.
- m. **Código fuente.** La combinación de Fortran y las instrucciones de Visual Basic que cuando se compila y se enlaza, crea el ejecutable GEMSS®.
- n. **Ejecutable.** La representación binaria del código fuente GEMS®.
- o. **Solicitud.** Una aplicación GEMSS® consiste en la GEMSS® ejecutable y el conjunto de archivos de entrada con formato, incluidos los datos batimétricos, los datos de condición de contorno variables en el tiempo, y archivos de control, que en conjunto representan un cuerpo de agua específico (río, lago, embalse, depósito, estuario o región costera) cuando se utiliza con el ejecutable suministrado.

---

24. INSTALACIÓN Y DERECHOS DE USO.

- a. Dispositivo con licencia. El dispositivo con licencia es el dispositivo en el que se utiliza el software. Puede instalar y utilizar una copia del software en el dispositivo con licencia.
- b. Dispositivo portátil. Es posible instalar otra copia en un dispositivo portátil para su uso por el usuario principal del dispositivo con licencia.
- c. Separación de componentes. Los componentes del software se licencia como una sola unidad. No puede separar los componentes e instalarlas en diferentes dispositivos.

25. REQUERIMIENTOS ADICIONALES DE LICENCIA.

- a. Alcance de la licencia. El software se licencia, no se vende.

Este contrato sólo le otorga algunos derechos de uso y distribuir el software. GEMSS Desarrollo y Distribución LLC se reserva todos los demás derechos. A menos que la ley aplicable le otorgue más derechos a pesar de esta limitación, puede utilizar el software tal como se permite expresamente en este contrato. Al hacerlo, deberá ajustarse a las limitaciones técnicas del software que sólo permiten utilizarlo de determinadas formas. No deberías

- " Redistributions GEMSS®, los ejemplos de aplicaciones y archivos de soporte proporcionados en el sitio ftp o las instrucciones de ftp descarga, excepto como se indica en las disposiciones específicas de esta licencia;
- " Ingeniería inversa, descompilar y desensamblar el software, excepto y únicamente en la medida en que la ley aplicable lo permita expresamente, a pesar de esta limitación;
- " Hacer más copias del software de las que especifica este contrato o permite la legislación vigente, a pesar de esta limitación;
- " Publicar el software para que otros lo copien
- " Alquilar, arrendar o prestar el software; o
- " Utilizar el software para prestar servicios de alojamiento de software comercial.

- b. Vigencia de la licencia. La licencia se concede por un período de un año que comienza el día en las instrucciones del ftp son proporcionados a usted.

Las actualizaciones para un período de la duración de la licencia se incluyen en esta licencia y puede obtenerse en el sitio ftp desde la que se descarga el software. La licencia puede ser renovada si se solicita al final de la vigencia de la licencia.

- c. Los requisitos de reporte. Usted se compromete a

- presentar un breve documento que resume su experiencia con GEMS® al final de la vigencia de la licencia.
- d. Copia de respaldo. Usted puede hacer una (1) copia de seguridad del software. Puede usarlo sólo para volver a instalar el software.
26. DOCUMENTACIÓN. Cualquier persona que tenga acceso válido a su equipo o a la red interna puede copiar y utilizar la documentación a efectos de consulta internos.
27. TRANSFERENCIA A OTRO DISPOSITIVO. Puede desinstalar el software e instalarlo en otro dispositivo para su uso. El usuario no puede hacerlo para compartir esta licencia entre dispositivos.
28. RESTRICCIONES DE EXPORTACIÓN. El software está sujeto a las leyes y regulaciones de exportación de Estados Unidos. Usted debe cumplir con todas las leyes de exportación nacionales e internacionales y reglamentos que se aplican Al software. Estas leyes incluyen restricciones sobre destinos, usuarios finales y uso final.
29. SERVICIOS DE SOPORTE TÉCNICO. Debido a que este software se suministra "tal cual", JUEGOS Desarrollo y Distribución LLC no proporcionarán servicios de apoyo para ella a menos acordado en un contrato independiente.
30. ACUERDO COMPLETO. Este acuerdo (incluyendo la garantía más adelante), y los términos de suplementos, actualizaciones, servicios basados en Internet y servicios de soporte que usted utilice, constituyen el contrato para los servicios de software y soporte.
31. LEY APPLICABLE.
- a. Estados Unidos. Si ha adquirido el software en los Estados Unidos, la ley del estado de Washington rige la interpretación de este acuerdo y se aplica a las reclamaciones por incumplimiento del mismo, independientemente de los conflictos de leyes. Las leyes del estado en el que rigen en vivo todas las demás reclamaciones, incluidas las bajo las leyes de protección al consumidor, leyes de competencia desleal o por responsabilidad civil.
- b. Fuera de los Estados Unidos. Si adquirió el software en otro país, se aplicará la legislación de ese país.

---

32. **EFFECTO LEGAL.** Este acuerdo describe ciertos aspectos legales

Es posible que tenga otros derechos conforme a las leyes de su estado o país. Usted también puede tener derechos con respecto a la parte de la que adquirió el software. Este contrato no modifica sus derechos bajo las leyes de su estado o país si las leyes de su estado o país no permiten que lo haga.

33. **Renuncia de garantía.** El software está bajo licencia "tal cual".

Usted asume el riesgo de utilizarlo. GEMSS Desarrollo y Distribución LLC no da ninguna garantía expresa, garantías o condiciones. Es posible que tenga otros derechos como consumidor en virtud de sus leyes locales que el presente contrato no pueda modificar.

En la medida permitida por la legislación local, Desarrollo GEMSS y Distribución LLC excluye las garantías implícitas de comerciabilidad, adecuación para un propósito particular y no infracción.

34. **LIMITACIÓN Y EXCLUSIÓN DE LA RESPONSABILIDAD.**

Puede recuperarse de GEMSS Desarrollo y Distribución LLC y sus proveedores solamente los daños directos hasta EE.UU. \$ 0,01.

No se puede recuperar ningún otro daño, incluyendo la pérdida de beneficios, consecuentes, especiales, indirectos o incidentales.

Esta limitación se aplica a

"Todo lo relacionado con el software, servicios, contenidos (incluido el código) de sitios de Internet de terceros, o programas de terceros, así

"reclamaciones por incumplimiento de contrato, incumplimiento de garantía o condición, responsabilidad objetiva, negligencia u otra responsabilidad extracontractual en la medida permitida por la ley aplicable.

También se aplica incluso si el desarrollo y distribución GEMSS LLC conocía o debería haber conocido la posibilidad de los daños y perjuicios.

La limitación o exclusión anterior no se aplique en su debido país no permite la exclusión o limitación de daños incidentales, consecuentes o de otro tipo.

\*\* Dirección de contacto

\*\*\*\*\*

Venkat S. Kolluru  
Surfacewater  
Modeling Group  
Environmental Resource Management  
350  
Eagleview  
Road Suite  
200  
Exton, PA 19341-1155  
(610) 524-3500  
(610) 524-3566(fax)  
(610) 524-3654(directo)  
e-mail: venkat.kolluru@erm.com

\*\*\*\*\*  
\*\*\*

\*\*\*\*\*  
\*\*\*

Nombre del escenario:

/mnt/resource/GEMSS/Apps/Fieldwood/Output/FateAC4\_2009\_Aug/FateAC4\_2009\_Aug  
Fecha : Sun Sep 18

\*\*\*\*\*

\*\*\*\*\* Encabezados del archivo de control

Paso\_Tiempo, dt = 720.00 s

Velocidad del viento a 10 m altura: -  
8.51933E+00 m/sec  
Dirección de viento: 7.639766E+01 deg

Tiempo in = 2009 8 1 0: 0  
Tiempo = 2009 8 1 1:12  
Tiempo fin = 2009 8 31 0: 0

Masa total liberada = 3.908629E+01 ton  
Número total de partículas liberadas hasta el momento = 11

Paso\_Tiempo, dt = 720.00 s

Velocidad del viento a 10 m altura:  
8.451591E+00 m/sec  
Dirección de viento: 7.988180E+01 deg

Tiempo in = 2009 8 1 0: 0  
Tiempo = 2009 8 1 2: 0  
Tiempo fin = 2009 8 31 0: 0

Masa total liberada = 6.751269E+01 ton

Número total de partículas liberadas hasta el momento = 19

Paso\_Tiempo, dt = 720.00 s

Velocidad del viento a 10 m altura:

8.413456E+00 m/sec

Dirección del viento: 8.434035E+01 deg

Tiempo in = 2009 8 1 0: 0

Tiempo = 2009 8 1 3: 0

Tiempo fin = 2009 8 31 0: 0

Masa total liberada = 1.030457E+02 ton

Número total de partículas liberadas hasta el momento = 29

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:

8.424261E+00 m/sec

Dirección del viento: 8.879118E+01 deg

Tiempo in = 2009 8 1 0: 0

Tiempo = 2009 8 1 4: 0

Tiempo fin = 2009 8 31 0: 0

Masa total liberada = 1.385787E+02 ton

Número total de partículas liberadas hasta el momento =

39

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:

8.482681E+00 m/sec

Dirección del viento: 9.318285E+01 deg

Tiempo in = 2009 8 1 0: 0

Tiempo = 2009 8 1 5: 0

Tiempo fin = 2009 8 31 0: 0

Masa total liberada = 1.741117E+02 ton

Número total de partículas liberadas hasta el momento =

49

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:

8.598753E+00 m/sec

Dirección del viento: 9.754070E+01 deg

Tiempo in = 2009 8 1 0: 0  
Tiempo = 2009 8 1 6: 0  
Tiempo fin = 2009 8 31 0: 0

Masa total liberada = 2.096447E+02 ton

Número total de partículas liberadas hasta el momento =

59

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:

8.564813E+00 m/sec

Dirección del viento: 9.596998E+01 deg

Tiempo in = 2009 8 1 0: 0  
Tiempo = 2009 8 1 7: 0

Tiempo fin = 2009 8 31 0: 0

Masa total liberada = 2.451776E+02 ton

Número total de partículas liberadas hasta el momento =

69

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:

8.531591E+00 m/sec

Dirección del viento: 9.434347E+01 deg

Tiempo in = 2009 8 1 0: 0  
Tiempo = 2009 8 1 8: 0  
Tiempo fin = 2009 8 31 0: 0

Masa total liberada = 2.807107E+02 ton

Número total de partículas liberadas hasta el momento =

79

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:

8.513450E+00 m/sec

Dirección del viento: 9.275574E+01 deg

Tiempo in = 2009 8 1 0: 0  
Tiempo = 2009 8 1 9: 0  
Tiempo fin = 2009 8 31 0: 0

Masa total liberada = 3.162439E+02 ton

Número total de partículas liberadas hasta el momento =

89

Paso\_tiempo, dt = 720.00 s

Velocidad del viento a 10 m de altura:

8.490808E+00 m/sec

Dirección del viento: 9.110388E+01 deg

Tiempo in = 2009 8 1 0: 0

Tiempo = 2009 8 1 10: 0

Tiempo fin = 2009 8 31 0: 0

Secuencia hasta completar 3600 partículas liberadas en el siguiente esquema:

Tiempo in = 2009 16 15 0: 0

Tiempo = 2009 15 16 0: 0

Tiempo fin = 2009 15 16 0: 0

## ***ANEXO 4***

*Registro de Peligros*

Identificación de peligros						Peor de los casos Consecuencia Razonable		Medidas de control de Prevención		Medidas de control de Recuperación		Riesgos Residuales		Riesgos Residuales	
Fuente de peligro y evento peligroso		Salud y Seguridad		Ambiente	Categoría	Técnicas	Administrativas	Técnicas	Administrativas	C	P	Salud y Seguridad	C	P	Ambiente
0.01	Hidrocarburos														
1.01	Accidente bajo presión	Evento superior=Perdida de contención; Resultados= Incendio y explosión, descarga al ambiente					Véase el Análisis corbata de mono para el mayor accidente-BT-001 - Hidrocarburos en la Formación - Pérdida de Contención del Pozo			5	B- Ha ocurrido en la industria	B5	5	B- Ha ocurrido en la industria	B5
2	Accidente bajo presión- Cabezal de pozo en superficie de la plataforma	5- Fatalidades múltiples	5- Efecto Masivo	MH											
1.06	Gas de hidrocarburos	Evento tope=Perdida de contención; Resultados= Incendio y explosión, descarga al ambiente					Véase el Análisis corbata de mono para el mayor accidente - BT 002 - Hidrocarburos en Equipo de Pruebas de Pozos .-Pérdida de Contención de Equipos de Prueba de Pozos			5	B- Ha ocurrido en la industria	B5	2	B- Ha ocurrido en la industria	B5
20	Gas tóxico														
20.01	Ácido Sulfídrico					Véase el Análisis corbata de mono para el mayor accidente-BT-001 - Hidrocarburos en la Formación - Pérdida de Contención del Pozo									
1	Reventón sin fuego	5- Fatalidades múltiples	1- Efecto leve	MH		Véase el Análisis corbata de mono para el mayor accidente-BT-005 - Gas de Sulfuro de Hidrógeno (H2S) - Pérdida de Contención de Gas de Sulfuro de Hidrógeno			5	B- Ha ocurrido en la industria	B5	1	B- Ha ocurrido en la industria	B1	

M/AE: Mayor Accident Event

BT: BowTie

M/H: Major Hazard

**Eventos de Accidentes Mayores y Modelos de Corbata de Moño**

Código	Peligro Mayor	Evento Superior
MAE 01	Hidrocarburos en la formación	Pérdida de contención del pozo
MAE02	Hidrocarburos en equipos de prueba de pozos	Pérdida de contención de los equipos de prueba de pozo
MAE 03	Otros materiales inflamables	Incendio a gran escala en la instalación
MAE 04	Materiales explosivos	Ignición accidental de explosivos
MAE 05	Ácido Sulfídrico	Pérdida de contención de ácido sulfídrico
MAE 06	Atmosferas inseguras en espacios confinados	Personal expuesto en atmósferas inseguras
MAE 07	Personal trabajando en altura	Caída de personal
MAE 08	Objetos en altura (operaciones de perforación)	Caída u oscilación de objetos en la torre de perforación o en la cubierta
MAE 09	Objetos en altura (operaciones de grúa)	Caída u oscilación de objetos en la grúa
MAE 10	Otros obstáculos y embarcaciones	Colisión con la instalación
MAE 11	Modo de operación elevado	Pérdida de estabilidad en modo elevado
MAE 12	Modo de operación flotante	Pérdida de estabilidad en modo flotante
MAE 13	Modo de operación en tránsito	Pérdida del control de remolcador en tránsito
MAE 14	Helicópteros en tránsito	El helicóptero no puede completar el vuelo al destino
MAE 15	Llegada y salida de helicópteros	Pérdida de control sobre helicóptero

**Detalles de Estimación de Riesgos Residuales de Peligros Mayores por Análisis Corbata de Moño**  
**Peligro: BT.001 Hidrocarburos en la Formación/ Pérdida de contención del pozo**


Resultado	Tipo de Riesgo	Riesgo Residual
Reventón en la parte superior sin ignición, liberación de hidrocarburos en la instalación	Personas	C2: Nivel 1
Reventón en la parte superior sin ignición, liberación de hidrocarburos en la instalación	Ambiental	C2: Nivel 1
Reventón e incendio en la parte superior, fuego y explosión en la instalación	Personas	B5: Nivel 2
Reventón e incendio en la parte superior, fuego y explosión en la instalación	Ambiental	B5: Nivel 2
Reventón submarino sin ignición debajo de la instalación- Pérdida de estabilidad en modo elevado	Personas	A5: Nivel 2
Reventón submarino sin ignición debajo de la instalación- Pérdida de estabilidad en modo elevado	Ambiental	A5: Nivel 2
Fuego en la superficie del mar alrededor de la instalación	Personas	A5: Nivel 2
Fuego en la superficie del mar alrededor de la instalación	Ambiental	A5: Nivel 2
Incendio y explosión en el área de temblorinas	Personas	B5: Nivel 2
Incendio y explosión en el área de temblorinas	Ambiental	B3: Nivel 1
Fuego y explosión en el cuarto de lodos	Personas	B5: Nivel 2
Fuego y explosión en el cuarto de lodos	Ambiental	B3: Nivel 1
Nube de ácido sulfídrico sin ignición en la instalación	Personas	B5: Nivel 2
Nube de ácido sulfídrico sin ignición en la instalación	Ambiental	B1: Nivel 1

**Peligro: BT.002 Hidrocarburos en equipos de prueba de pozo/ Pérdida de contención del equipo de prueba de pozo**

Resultado	Tipo de Riesgo	Riesgo Residual
Liberación de hidrocarburos sin ignición en la parte superior de la instalación	Personas	B2: Nivel 1
Liberación de hidrocarburos sin ignición en la parte superior de la instalación	Ambiental	B5: Nivel 2
Ignición de hidrocarburos en la parte superior con fuego y explosión en la instalación	Personas	A5: Nivel 2
Ignición de hidrocarburos en la parte superior con fuego y explosión en la instalación	Ambiental	A5: Nivel 2
Nube de ácido sulfídrico sin ignición en la instalación	Personas	A5: Nivel 2
Nube de ácido sulfídrico sin ignición en la instalación	Ambiental	A1: Nivel 1


**Peligro: BT.005 Ácido Sulfídrico (H2S) / Pérdida de contención de ácido sulfídrico**


Resultado	Tipo de Riesgo	Riesgo Residual
Personal expuesto a Ácido Sulfídico	Personas	B5: Nivel 2





Clasificación	Icono	Efectividad	Factor Humano	Confiabilidad	Disponibilidad
++		Muy Efectivo	No implicación humana; instrucciones simples, fácil de operar; funcionamiento intuitivo y probado del operador. Error prácticamente improbable.	Muy Confiable (100%)	En su lugar y utilizado todo el tiempo
+		Efectivo	Tarea claramente definida, procedimientos operativos definidos, persona capacitada y con experiencia. Error concebible pero muy improbable.	Confiable (>95% pero <100%)	En su lugar y utilizado la mayor parte del tiempo (Aprox. >90%)
0		Poco Efectivo	Operando bajo estrés, multitarea. Procedimientos complicados, difíciles de operar, la persona está entrenada pero se consideran posibles errores.	Poco Confiable (>75% pero <95%)	En su lugar y utilizado inconsistente: e (Aprox. >20% pero <90%)
-		Inefectivo	Operando bajo estrés elevado, procedimientos complejos o poco claros, capacitación inadecuada. Errores considerados bastante posible.	Desconfiable (>50% pero <75%)	No siempre en su lugar y utilizado infrecuentemente (Aprox. <50%)
--		Muy Inefectivo	Personal no familiarizado con la tarea, procedimientos muy complejos, sin capacitación del operador. Se pueden esperar errores o situaciones de emergencia.	Muy Desconfiable (>50%)	No en su lugar y nunca usado
N		No Implementado	Estos controles han sido identificados. Sin embargo, no se aplican. Todos los controles potenciales fueron identificados durante el proceso de desarrollo del esquema de seguridad. Sin embargo, algunos no podrían implementarse posteriormente por cambios operacionales específicos basados en la evaluación de los peligros y riesgos relacionados con esa campaña operacional específica.		
TP		Tercero	Este control es proporcionado por terceros externos a la organización. Por lo tanto, la eficacia de este control depende de condiciones y consideraciones específicas de terceros y clientes. Su efectiva debe determinarse durante el proceso de revisión de riesgos de ISO9001.		
LS		Ubicación Específica	Esta medida de reducción del riesgo es proporcionada por la organización; sin embargo, la efectividad depende de consideraciones específicas de campaña o ubicación. Su implementación / efectividad debe determinarse durante el proceso de revisión de riesgos de ISO9001.		

Optimización de jerarquía	Leyenda	Método de Optimización
Eliminación - Técnico		Diseñar o eliminar completamente el riesgo es la prioridad durante el tratamiento del riesgo. Los controles de eliminación están relacionados con los peligros, sus causas y los eventos principales.
Eliminación - Administración		Cuando los peligros y las causas no pueden ser "eliminados", se requieren controles para evitar que lleven a eventos y consecuencias no deseadas. Los controles de prevención están relacionados con los peligros, sus causas y los principales eventos.
Prevención - Técnico		Los controles que detectan la ocurrencia de eventos son a menudo críticos para poder responder con otras medidas de control que reduzcan la propagación de los eventos. Los controles de detección a menudo no proporcionan ningún control real aparte de estar consciente de la necesidad de responder.
Prevención - Administración		Dado que siempre hay posibilidades de que los controles fallen, se requieren medidas adicionales para limitar el escalamiento y la gravedad de cualquier evento resultante no deseado, que puede surgir al proporcionar la capacidad de intervenir y limitar la propagación de los eventos.
Detección - Técnico		También se requiere controles que disminuyan la importancia o el daño causado por un evento no deseado. Dichos controles sólo surten efecto después de que se produzcan el evento principal y los resultados. Los controles de mitigación son generalmente aquellos diseñados para proteger al personal contra las consecuencias de un peligro o para ayudar a recuperarse de los efectos del peligro.
Detección - Administración		
Reducción - Técnico		
Reducción - Administración		
Mitigación - Técnico		Estos controles están relacionados con los factores atenuantes que debilitan o impiden completamente los controles de causa y de resultado. Se les exige que garanticen el funcionamiento efectivo de otros controles y / que proporcionen redundancia cuando otros controles fallen.
Mitigación - Administración		
Escalamiento - Técnico		
Escalamiento - Administración		









# Ocean Scepter Hazard Register

ID	Hazard Source and Hazardous Event	Worst Case Reasonable Consequence			Category	Preventive Control Measures	Administrative	Technical	Administrative	C	P	Health & Safety	C	P	Health & Safety	C	P	Residual Risk
		Health & Safety	Environment	Citizens														
<b>01</b>	<b>Hydrocarbons</b>																	
G1.01	Oil under pressure	Top Event = Loss of Containment. Outcomes = Fire and explosion, Environmental Discharge																
1	Oil under pressure - release production infrastructure	5 - Major Failure	MHI															
2	Oil under pressure - vessel wall/read platform infrastructure	5 - Major Failure	MHI															
G1.02	Hydrocarbons in formation	Top Event = Loss of Containment. Outcomes = Fire and explosion, Environmental Discharge																
1	Hydrocarbons in formation - drilling operations	5 - Major Failure	MHI															
G1.03	LPG (propane gas)	Top Event = Loss of Containment. Outcomes = Fire and explosion, Environmental Discharge																
1	LPG Gas Bottles - - vessel/bottle/piping system	4 - Severe Injury	OWH															
G1.04	LNG	Top Event = Loss of Containment. Outcomes = Fire and explosion, Environmental Discharge																
1	No Source Identified	-	-	-														
G1.05	Condensate (natural gas liquids)	Top Event = Loss of Containment. Outcomes = Fire and explosion, Environmental Discharge																
1	Condensate - seabed production infrastructure	5 - Major Failure	MHI															
2	Condensate - seabed production infrastructure	5 - Major Failure	MHI															
3	Condensate - well testing surface equipment/reuse	5 - Major Failure	MHI															
G1.06	Hydrocarbon gas	Top Event = Loss of Containment. Outcomes = Fire and explosion, Environmental Discharge																
1	Hydrocarbon gas - older steel and/or older structure	5 - Major Failure	2 - Local Effect	MHI														
2	Hydrocarbon gas - older steel top floor release	5 - Major Failure	2 - Local Effect	MHI														
3	Hydrocarbon gas - gas oil tank - shelter area	1 - Slight Effect	MHI															
4	Hydrocarbon gas - gas oil tank - gas oil room	5 - Major Failure	1 - Slight Effect	MHI														
5	Hydrocarbon gas - solvent release	5 - Major Failure	2 - Local Effect	MHI														
6	Hydrocarbon gas - tank/gas storage tanks (internal)	5 - Major Failure	2 - Local Effect	MHI														
7	Hydrocarbon gas - surface vessel/tank infrastructure	5 - Major Failure	2 - Local Effect	MHI														
8	Hydrocarbon gas - surface vessel/tank infrastructure	5 - Major Failure	2 - Local Effect	MHI														
9	Hydrocarbon gas - well intervention equipment release	5 - Major Failure	2 - Local Effect	MHI														
10	Hydrocarbon gas - well testing surface equipment release	5 - Major Failure	2 - Local Effect	MHI														
11	Hydrocarbon gas - well testing surface equipment release	2 - Minor Harm	O-Avg Effect	OWH														
12	Hydrocarbon gas - information centre	2 - Minor Harm	O-Zero Effect	OWH														
13	Hydrocarbon gas - tool gas separator device and/or release	1 - Slight Harm	O-Avg Effect	OWH														
14	Hydrocarbon gas - vacuum degasser device and/or release	1 - Slight Harm	O-Avg Effect	OWH														
G1.07	Oil at low pressure	Top Event = Loss of Containment. Outcomes = Fire and explosion, Environmental Discharge																
1	No Source Identified	-	-	-														
G1.08	Wax	Top Event = Loss of Containment. Outcomes = Fire																
1	Oil at low pressure - drilling rigging	4 - Severe Injury	2 - Local Effect	OWH														
G1.09	Coal	Top Event = Loss of Containment. Outcomes = Fire																
1	No Source Identified	-	-	-														
<b>02</b>	<b>Refined Hydrocarbons</b>																	
G2.01	Lube and seal oil	Top Event = Loss of Containment. Outcomes = Fire and explosion, Environmental Discharge																
1	Lube oil storage tank in repair room	4 - Severe Injury	2 - Local Effect	OWH														
2	Lube oil main engine	4 - Severe Injury	1 - Slight Effect	OWH														
3	Lube oil storage main pump room	4 - Severe Injury	2 - Local Effect	OWH														
4	Lube oil - emergency generator	4 - Severe Injury	1 - Slight Effect	OWH														
5	Lube oil storage tank in tanks	3 - Major Harm	2 - Local Effect	OWH														
6	Lube oil - separators	3 - Major Harm	1 - Slight Effect	OWH														
7	Lube oil - fuel oil separators	2 - Minor Harm	1 - Slight Effect	OWH														
8	Lube oil - fuel oil service pump	2 - Minor Harm	1 - Slight Effect	OWH														
9	Lube oil - bearing pump	1 - Slight Harm	1 - Slight Effect	OWH														
10	Lube oil - feed water pump	2 - Minor Harm	1 - Slight Effect	OWH														
11	Lube oil - compressor	2 - Minor Harm	1 - Slight Effect	OWH														
12	Lube oil - fuel oil/water pump	1 - Slight Harm	1 - Slight Effect	OWH														
13	Lube oil - fuel oil service pump	1 - Slight Harm	1 - Slight Effect	OWH														
14	Lube oil - oil/water separators	1 - Slight Harm	1 - Slight Effect	OWH														
15	Lube oil - bearing pump	1 - Slight Harm	1 - Slight Effect	OWH														
16	Lube oil - fire water pump	1 - Slight Harm	1 - Slight Effect	OWH														
17	Lube oil - oil/water pump	1 - Slight Harm	1 - Slight Effect	OWH														
18	Lube oil - bearing pump	1 - Slight Harm	1 - Slight Effect	OWH														
19	Lube oil - oil compressor	1 - Slight Harm	1 - Slight Effect	OWH														
20	Lube oil - oil/water separators	1 - Slight Harm	1 - Slight Effect	OWH														
21	Lube oil - bearing pump	1 - Slight Harm	1 - Slight Effect	OWH														
22	Lube oil - fire water / sea water pump	1 - Slight Harm	1 - Slight Effect	OWH														
23	Lube oil - general service pump	1 - Slight Harm	1 - Slight Effect	OWH														

# Ocean Scepter Hazard Register

ID	Hazard Identifier	Hazard Source and Hazardous Event	Worst Case Reasonable Consequence			Preventive Control Measure	Administrative	Technical			Reactive Risk	Residual Risk
			Health & Safety	Environment	Category			C	P	Habit & Study		
24	Lube oil - big pumping pump	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
25	Lube oil - big system	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
26	Lube oil - low grade oil	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
27	Lube oil - continuous working tank	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
28	Lube oil - tank compressor	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
29	Lube oil - air dryers units	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
30	Lube oil - separator units	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
31	Lube oil - tube shells	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
32	Lube oil - mud cleaner	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
33	Lube oil - hydraulic power units	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
34	Lube oil - fire tube furnace	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
35	Lube oil - BOP control system	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
36	Lube oil - gearbox	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
37	Lube oil - power plants	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
38	Lube oil - hydro-pneumatic unit	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
39	Lube oil - hydraulic actuators	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
40	Lube oil - hydraulic cylinders	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
41	Lube oil - turn couplings	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
42	Lube oil - deck corner, travelling block, top of grade pipe	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
43	Lube oil - BOP block	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
44	Lube oil - rotary stabilizer	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
45	Lube oil - air separator / desalter unit	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
46	Lube oil - de-ring device	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
47	Lube oil - BOP test system	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
48	Lube oil - tank bottom valves	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
49	Lube oil - main piping system	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
50	Lube oil - wellhead units	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
51	Lube oil - lubrication system	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
52	Lube oil - wobblers	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
53	Lube oil - mud generators	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
Top Event = 1 out of Containment Outcomes = Fire and explosion, Environmental Discharge												
02.02	Hydraulic oil (flammable)											
1	Hydraulic oil - deck valves	3 - Major Harm	2 - Local Effect	OWH				3	B - Has occurred in industry	B3	2	B - Has occurred in industry
2	Hydraulic oil - pressure filter system	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
3	Hydraulic oil - driving isolator	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
4	Hydraulic oil - drive hub, holding equipment	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
5	Hydraulic oil - gear system	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
6	Hydraulic oil - shear blades	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
7	Hydraulic oil - bar chart fluid	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
8	Hydraulic oil - drive system	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
9	Hydraulic oil - gear unit	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
10	Hydraulic oil - motor unit	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
11	Hydraulic oil - pump unit	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
12	Hydraulic oil - central locking system picks	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
13	Hydraulic storage tank bays	2 - Minor Harm	2 - Local Effect	OWH				2	B - Has occurred in industry	B2	2	B - Has occurred in industry
14	Hydraulic oil - central reservoir system	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
15	Hydraulic oil - remote valve, pump	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
16	Hydraulic oil - hydraulic valve actuators	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
17	Hydraulic oil - remote machine, valve, pump	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
18	Hydraulic oil - tank connector	1 - Slight Harm	1 - Slight Effect	OWH				1	B - Has occurred in industry	B1	1	B - Has occurred in industry
Top Event = Loss of Containment Outcomes = Fire and explosion, Environmental Discharge												
02.03	Diesel fuel											
1	Diesel fuel - main engines (tires, vents)	5 - Multiple Fatalities	4 - Major Effect	OWH				5	B - Has occurred in industry	BB	4	B - Has occurred in industry
2	Diesel fuel - emergency generator engine back fire, vent	3 - Major Effect	4 - Slight Effect	OWH				4	B - Has occurred in industry	B4	3	B - Has occurred in industry
3	Diesel fuel - vent and valve actuator	3 - Major Effect	4 - Slight Effect	OWH				4	B - Has occurred in industry	B4	3	B - Has occurred in industry
4	Diesel fuel - main pump - driving mud positive	4 - Major Effect	4 - Slight Effect	OWH				4	B - Has occurred in industry	B4	4	B - Has occurred in industry
5	Diesel fuel - deck crane engines and drives	4 - Major Effect	4 - Slight Effect	OWH				4	B - Has occurred in industry	B4	4	B - Has occurred in industry
6	Diesel fuel - sea storage tanks, bays, vent, pump	3 - Major Effect	4 - Major Effect	OWH				3	B - Has occurred in industry	BB	4	B - Has occurred in industry
7	Diesel fuel - remote valve actuators	3 - Major Effect	4 - Major Effect	OWH				3	B - Has occurred in industry	BB	3	B - Has occurred in industry
8	Diesel fuel - remote unit	3 - Major Effect	4 - Major Effect	OWH				3	B - Has occurred in industry	BB	3	B - Has occurred in industry
9	Diesel fuel - robust hoses and nozzles	3 - Major Effect	3 - Major Effect	OWH				3	B - Has occurred in industry	BB	3	B - Has occurred in industry
10	Diesel fuel - service connecting flexible water units	3 - Major Effect	1 - Slight Effect	OWH				1	B - Has occurred in industry	BB	1	B - Has occurred in industry
Top Event = Diesel oil/gasoline												
1	Helicopter - helicopter fuel tanks - helicopter crash and fire	5 - Multiple Fatalities	4 - Major Effect	MH				5	B - Has occurred in industry	BB	4	B - Has occurred in industry
2	Helicopter - helicopter fuel storage and delivery	5 - Multiple Fatalities	4 - Major Effect	MH				5	B - Has occurred in industry	BB	4	B - Has occurred in industry
03 Other Flammable Materials												
03.01	Cellulosic materials											
1	Flammable solids and/or laundry operations	5 - Multiple Fatalities	0 - Zero Effect	OWH				5	A - Never occurred in industry	AB	0	A - Never occurred in industry
2	Flammable liquids and/or wastes - solid waste	4 - Slight Effect	0 - Zero Effect	OWH				4	B - Has occurred in industry	B4	0	B - Has occurred in industry
3	Flammable furnaces and/or materials - accommodation	4 - Slight Effect	0 - Zero Effect	OWH				4	B - Has occurred in industry	B4	0	B - Has occurred in industry
4	Flammable liquids and/or wastes - ventilation	4 - Slight Effect	0 - Zero Effect	OWH				4	B - Has occurred in industry	B4	0	B - Has occurred in industry
5	Flammable liquids and/or wastes - workplace	4 - Slight Effect	0 - Zero Effect	OWH				4	A - Never occurred in industry	AB	0	A - Never occurred in industry
6	Flammable liquids and/or wastes - rubber glove	2 - Minor Harm	0 - Zero Effect	OWH				2	B - Has occurred in industry	B2	0	B - Has occurred in industry
7	Flammable gases - waste lines	2 - Minor Harm	0 - Zero Effect	OWH				2	B - Has occurred in industry	B2	0	B - Has occurred in industry
8	Flammable materials - heat transfer	1 - Slight Harm	0 - Zero Effect	OWH				1	B - Has occurred in industry	B1	0	B - Has occurred in industry
03.02 Pyrophoric materials (flammable chemicals)												
Top Event = Loss of Containment Outcomes = Fire and explosion, Environmental Discharge												
Refer to Major Bowtie Analysis - BT0201-Other Flammable Materials - Large Scale Fire on the Facility												
Refer to Major Bowtie Analysis - BT0202-Other Flammable Materials - Large Scale Fire on the Facility												
Refer to Major Bowtie Analysis - BT0203-Other Flammable Materials - Large Scale Fire on the Facility												
Refer to Major Bowtie Analysis - BT0204-Diesel Fuel												
Refer to Major Bowtie Analysis - BT0205-Other Flammable Materials - Waste Management Plan												
Refer to Major Bowtie Analysis - BT0206-Other Flammable Materials - Fire Protection												
Refer to Major Bowtie Analysis - BT0207-Other Flammable Materials - Personnel Protection												
Refer to Major Bowtie Analysis - BT0208-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0209-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0210-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0211-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0212-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0213-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0214-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0215-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0216-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0217-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0218-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0219-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0220-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0221-Other Flammable Materials - Workforce Protection												
Refer to Major Bowtie Analysis - BT0222-Other Flammable Materials - Workforce Protection												

# Ocean Scepter Hazard Register

ID	Hazard Source and Hazardous Event		Worst-Case Reasonable Consequence		Environment	Category	Recovery Control Measures		Administrative		Technical		Residual Risk	
	Hazard Identification	Hazard Source	Health & Safety	Environment			C	P	H	S	C	P	H	S
1	Fammable coding oils & gels - galley		5 - Multiple Fatalities	1-Slight Effect	MHI	Refer to Major Bodily Analysis - BT1001 - Other Fammable Materials - Large Scale Fire on the Facility			5 - A: Never occurred in industry	AS	1	A: Never occurred in industry	A1	
2	Fammable chemicals - back room		5 - Multiple Fatalities	2 - Local Effect	OWH	Submitted Design and Specifications			4 - B: Has occurred in industry	B4	2	B: Has occurred in industry	B2	
3	Fammable chemicals - vehicle		4 - Slight Effect	CWH		Planned Maintenance (SEMS 1.3)			4 - B: Has occurred in industry	B4	1	B: Has occurred in industry	B1	
4	Fammable chemicals - cockpit		4 - Slight Effect	CWH		Job Safety Analysis (SEMS 3.4)			4 - B: Has occurred in industry	B4	1	B: Has occurred in industry	B1	
5	Fammable waste oil - storage tanks		4 - Slight Effect	CWH		Designated Storage Areas			4 - B: Has occurred in industry	B4	2	B: Has occurred in industry	B2	
6	Fammable waste oil - waste tank		4 - Slight Effect	CWH		Corrosive			4 - B: Has occurred in industry	B4	2	B: Has occurred in industry	B2	
7	Fammable chemicals - cold storage tanks		4 - Slight Effect	CWH		Drainage & Oil Separation			4 - B: Has occurred in industry	B4	1	B: Has occurred in industry	B1	
8	Fammable paints or thinner - paint locker		4 - Slight Effect	CWH		Fire Protection			4 - B: Has occurred in industry	B4	1	A: Never occurred in industry	A1	
9	Fammable batteries - battery house		3 - Major Harm	1-Slight Effect	CWH	Personnel Protective Equipment (SEMS 6.1.3)			3 - A: Never occurred in industry	A3	1	A: Never occurred in industry	A1	
10	Fammable batteries - fuel cell truck		3 - Major Harm	1-Slight Effect	CWH	Work Area Inspection			3 - A: Never occurred in industry	A3	1	A: Never occurred in industry	A1	
11	Fammable chemicals - acid lab		2 - Minor Harm	1-Slight Effect	CWH	Workshop Competency Program (SEMS 7.1)			2 - B: Has occurred in industry	B2	1	A: Never occurred in industry	A1	
12	Fammable chemicals - 15A electrical controls		2 - Minor Harm	1-Slight Effect	CWH	Workshop Competency Program (SEMS 7.1)			2 - A: Never occurred in industry	A2	1	A: Never occurred in industry	A1	
13	Fammable chemicals - medical oxygen unit		2 - Minor Harm	1-Slight Effect	CWH	Workshop Competency Program (SEMS 7.1)			2 - A: Never occurred in industry	A2	1	A: Never occurred in industry	A1	
14	Fammable substances - liquids		Top Event = Fire ignition	Outcomes = Fire	CWH	Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
15	Fammable substances - liquids		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
16	Fammable electrical equipment - general electric services in porters		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
17	Fammable electrical equipment - control unit		0-Zero Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
18	Fammable electrical equipment - emergency power generators		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
19	Fammable electrical equipment - emergency power units/towers		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
20	Fammable electrical equipment - laundry equipment		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
21	Fammable electrical equipment - main power generators		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
22	Fammable electrical equipment - medical equipment		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
23	Fammable electrical equipment - engine rooms/fans		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
24	Fammable electrical equipment - fire protection systems		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
25	Fammable electrical equipment - fire extinguishers		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
26	Fammable electrical equipment - fire detection/parts /darts		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
27	Fammable electrical equipment - moving vehicles		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
28	Fammable electrical equipment - medical equipment		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
29	Fammable electrical equipment - medical parts		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
30	Fammable electrical equipment - oily separator unit		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
31	Fammable electrical equipment - sewage treatment unit		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
32	Fammable electrical equipment - utility trailers		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
33	Fammable electrical equipment - storage tanks		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
34	Fammable electrical equipment - ventilation equipment (ANL), condensers, fans		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
35	Fammable electrical equipment - welding machines		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
36	Fammable electrical equipment - well control equipment		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
37	Fammable electrical equipment - well logging unit		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
38	Fammable electrical equipment - well unit		2 - Minor Harm	0-Zero Effect	CWH	Emergency Response Manual (SEMS 10)			2 - B: Has occurred in industry	B2	0	B: Has occurred in industry	B0	
39	No Source Identified		-	-	-	Top Event = Accidental ignition	Outcomes = Explosion							
40	Explosives		Conventional explosive material			Top Event = Accidental ignition	Outcomes = Explosion							
41	No Source Identified		Conventional explosives			Top Event = Accidental ignition	Outcomes = Explosion							
42	Perforating gun charges		Perforating gun charges			Top Event = Accidental ignition	Outcomes = Explosion							
43	No Source Identified		Perforating gun charges - storage areas - explosive operators			Top Event = Accidental ignition	Outcomes = Explosion							
44	Firearms and weapons		Firearms and weapons			Top Event = Accidental discharge	Outcomes = Explosion							
45	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
46.01	Bottled gas under pressure		Bottled gas under pressure			Top Event = Loss of containment	Outcomes = Pressure explosion, Environmental Discharge							
47	Gases under pressure - toxic/irritant/gas/bottle (no hazard)		5 - Multiple Fatalities	1-Slight Effect	MHI	Refer to Major Bodily Analysis - BT1001 - Other Fammable Materials - Large Scale Fire on the Facility			5 - A: Never occurred in industry	AD	1	A: Never occurred in industry	A1	
48	Gases under pressure - explosive/bottles		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
49	Gases under pressure - irritant/gas/bottle		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
50	Gases under pressure - explosive/gas/bottle		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	B: Has occurred in industry	B0	
51	Gases under pressure - medical/gas/bottle		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	A: Never occurred in industry	A0	
52	Gases under pressure - toxic/gas/bottle		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	A: Never occurred in industry	A0	
53	Gases under pressure - irritant/gas/bottle		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	A: Never occurred in industry	A0	
54	Gases under pressure - medical/gas/bottle		4 - Slight Effect	CWH		Emergency Response Manual (SEMS 10)			4 - B: Has occurred in industry	B4	0	A: Never occurred in industry	A0	
55	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
56	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
57	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
58	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
59	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
60	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
61	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
62	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
63	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
64	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
65	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
66	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
67	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
68	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
69	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
70	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
71	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
72	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
73	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
74	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
75	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
76	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
77	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
78	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
79	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
80	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
81	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
82	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
83	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
84	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
85	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
86	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
87	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
88	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
89	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
90	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
91	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
92	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
93	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
94	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
95	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
96	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
97	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
98	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
99	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
100	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
101	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
102	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
103	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
104	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
105	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
106	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
107	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
108	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
109	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							
110	No Source Identified		No Source Identified			Top Event = Accidental ignition	Outcomes = Explosion							

**Ocean Scepter Hazard Register**

Ocean Scepter Hazard Register

# Ocean Scepter Hazard Register

ID	Hazard Identifier	Hazard Source / Hazardous Event		Worst Case Reasonable Consequence		Preventive Control Measures	Administrative	Technical	Reactive Control Measures		Residual Risk	
		Health & Safety	Environment	Catagory	MHI				C	P		
2	Vessel collision / heavy load operation	5 - Multiple Failures	5 - Multiple Failures	5 - Multiple Failures	MHI	Refer to Major Bowtie Analysis - BT015 - "Initial Operating Mode - Loss of Tool Control in Transit"			5 - A - Never occurred in industry	AS	5 - A - Never occurred in industry	
3	Vessel collision / support vessel operating near facility	5 - Multiple Failures	5 - Multiple Failures	5 - Multiple Failures	MHI	Refer to Major Bowtie Analysis - BT015 - "Initial Operating Mode - Loss of Tool Control in Transit"	Other Major Bowtie Analysis - BT015 - "Initial Operating Mode - Loss of Tool Control in Transit"		5 - A - Never occurred in industry	AS	5 - A - Never occurred in industry	
4	Vessel collision / fishing vessels near facility	4 - Single Failure	4 - Single Failure	4 - Single Failure	OWH	Big Standard Integrity	Big Standard Integrity		4 - A - Never occurred in industry	A4	4 - A - Never occurred in industry	
08.04	<b>Equipment with moving or rotating parts</b>		Top Event = Unstable proximity with mechanical energy		Outcomes = Personnel caught by, struck by		Emergency Standard Deviations (SEMS 6.2.1)	Emergency Response Manual (SEMS 10) 10.10 Workforce Contingency Program (SEMS 11) Incident Reporting and Investigations (SEMS 11.2.9)	C4	C - Has occurred in company	C4	
	1	Moving or rotating equipment - drivelines	4 - Single Failure	0 - Zero Effect	OWH	Equipment Design and Specifications (SEMS 6.2.3)	Planned Maintenance (SEMS 6.3)	Job Safety Analysis (SEMS 6.2.5)	B - Has occurred in industry	B4	B - Has occurred in industry	B0
	2	Moving or rotating equipment - deck cranes, lattice bock	4 - Single Failure	0 - Zero Effect	OWH	Behavior Based Safety (OOS) (SEMS 6.2.6)	Behavior Based Safety (OOS) (SEMS 6.2.6)	Behavior Based Safety (OOS) (SEMS 6.2.6)	B - Has occurred in industry	B4	B - Has occurred in industry	B0
	3	Moving or rotating equipment - generic industrial equipment - general purpose rotors, engines	4 - Single Failure	0 - Zero Effect	OWH	Workplace Contingency Program (SEMS 7.1)	Workplace Contingency Program (SEMS 7.1)	Workplace Contingency Program (SEMS 7.1)	B - Has occurred in industry	B4	B - Has occurred in industry	B0
	4	Moving or rotating equipment - jetting nozzles	4 - Single Failure	0 - Zero Effect	OWH	Third Party Inspection - Certifier (SEMS 7.1)	Third Party Inspection - Certifier (SEMS 7.1)	Third Party Inspection - Certifier (SEMS 7.1)	B - Has occurred in industry	B4	B - Has occurred in industry	B0
	5	Moving or rotating equipment - cableway or hoisting system	4 - Single Failure	0 - Zero Effect	OWH	Personal Protective Equipment (SEMS 6.2.1)	Personal Protective Equipment (SEMS 6.2.1)	Personal Protective Equipment (SEMS 6.2.1)	B - Has occurred in industry	B4	B - Has occurred in industry	B0
	6	Moving or rotating equipment - cables or ropes of packages	4 - Single Failure	0 - Zero Effect	OWH	Personnel Jewelry Requirements (SEMS 6.2.1)	Personnel Jewelry Requirements (SEMS 6.2.1)	Personnel Jewelry Requirements (SEMS 6.2.1)	B - Has occurred in industry	B4	B - Has occurred in industry	B0
	7	Moving or rotating equipment - clutter near (FIR) part	4 - Single Failure	0 - Zero Effect	OWH	Personal Protective Equipment (SEMS 6.2.1) Standards	Personal Protective Equipment (SEMS 6.2.1) Standards	Personal Protective Equipment (SEMS 6.2.1) Standards	B - Has occurred in industry	B4	B - Has occurred in industry	B0
	8	Moving or rotating equipment - fire (FIR) safety traps	4 - Single Failure	0 - Zero Effect	OWH				B - Has occurred in industry	B4	B - Has occurred in industry	B0
	9	Moving or rotating equipment - fire (FIR) safety traps	4 - Single Failure	0 - Zero Effect	OWH				B - Has occurred in industry	B4	B - Has occurred in industry	B0
	10	Moving or rotating equipment - fire (FIR) protection system	4 - Single Failure	0 - Zero Effect	OWH				B - Has occurred in industry	B4	B - Has occurred in industry	B0
	11	Moving or rotating equipment - fire (FIR) protection system	4 - Single Failure	0 - Zero Effect	OWH				B - Has occurred in industry	B4	B - Has occurred in industry	B0
	12	Moving or rotating equipment - fire (FIR) protection system	4 - Single Failure	0 - Zero Effect	OWH				B - Has occurred in industry	B4	B - Has occurred in industry	B0
	13	Moving or rotating equipment - fire (FIR) protection system	4 - Single Failure	0 - Zero Effect	OWH				B - Has occurred in industry	B4	B - Has occurred in industry	B0
	14	Moving or rotating equipment - forklift	4 - Single Failure	0 - Zero Effect	OWH				B - Has occurred in industry	B4	B - Has occurred in industry	B0
	15	Moving or rotating equipment - forklift	4 - Single Failure	0 - Zero Effect	OWH				B - Has occurred in industry	B4	B - Has occurred in industry	B0
	16	Moving or rotating equipment - forklift	4 - Single Failure	0 - Zero Effect	OWH				B - Has occurred in industry	B4	B - Has occurred in industry	B0
	17	Moving or rotating equipment - forklift	4 - Single Failure	0 - Zero Effect	OWH				B - Has occurred in industry	B4	B - Has occurred in industry	B0
	18	Moving or rotating equipment - forklift	4 - Single Failure	0 - Zero Effect	OWH				B - Has occurred in industry	B4	B - Has occurred in industry	B0
	19	Moving or rotating equipment - forklift	4 - Single Failure	0 - Zero Effect	OWH				A - Never occurred in industry	A4	A - Never occurred in industry	A0
	20	Moving or rotating equipment - forklift	4 - Single Failure	0 - Zero Effect	OWH				A - Never occurred in industry	A4	A - Never occurred in industry	A0
	21	Moving or rotating equipment - hydraulic cylinders	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	22	Moving or rotating equipment - jacking system	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	23	Moving or rotating equipment - jacking system	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	24	Moving or rotating equipment - jumbo bow	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	25	Moving or rotating equipment - mobile phone and related items	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	26	Moving or rotating equipment - mobile phone and related items	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	27	Moving or rotating equipment - mobile phone and related items	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	28	Moving or rotating equipment - mobile phone and related items	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	29	Moving or rotating equipment - mobile phone and related items	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	30	Moving or rotating equipment - wear (gloves) and related items	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	31	Moving or rotating equipment - wear (gloves) and related items	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	32	Moving or rotating equipment - wear (gloves) and related items	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	33	Moving or rotating equipment - ventilation fans	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	34	Moving or rotating equipment - compressors	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	35	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	36	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	37	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	38	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	39	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	40	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	41	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	42	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	43	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	44	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	45	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
	46	Moving or rotating equipment - fasteners	3 - Major Harm	0 - Zero Effect	OWH				B - Has occurred in industry	B3	B - Has occurred in industry	B0
08.05	<b>Use of hazardous hand tools</b>		Top Event = Unstable proximity with sharp object		Outcomes = Personnel caught by, struck by		Emergency Response Manual (SEMS 10) 10.10 Workforce Contingency Program (SEMS 11) Incident Reporting and Investigations (SEMS 11.2.9)	C4	C - Has occurred in company	C4	C - Has occurred in company	
	1	Hand tool - single pointed blades	4 - Single Failure	0 - Zero Effect	OWH	Emergency Response Manual (SEMS 10) 10.10 Workforce Contingency Program (SEMS 11) Incident Reporting and Investigations (SEMS 11.2.9)						
	2	Hand tool - single pointed blades	4 - Single Failure	0 - Zero Effect	OWH							
	3	Hand tool - single pointed blades	4 - Single Failure	0 - Zero Effect	OWH							
	4	Hand tool - single pointed blades	3 - Major Harm	0 - Zero Effect	OWH							
	5	Hand tool - single pointed blades	3 - Major Harm	0 - Zero Effect	OWH							
	6	Hand tool - single pointed blades	3 - Major Harm	0 - Zero Effect	OWH							
	7	Hand tool - single pointed blades	3 - Major Harm	0 - Zero Effect	OWH							
	8	Hand tool - single pointed blades	3 - Major Harm	0 - Zero Effect	OWH							
	9	Hand tool - single pointed blades	3 - Major Harm	0 - Zero Effect	OWH							
08.06	<b>Use of knives, machetes and other sharp objects</b>		Top Event = Unstable proximity with sharp object		Outcomes = Personnel caught by, struck by		Emergency Response Manual (SEMS 10) 10.10 Workforce Contingency Program (SEMS 11) Incident Reporting and Investigations (SEMS 11.2.9)	C4	C - Has occurred in company	C4	C - Has occurred in company	
	1	Sharp objects - sharp knives and razors	3 - Major Harm	0 - Zero Effect	OWH							
	2	Sharp objects - sharp knives and razors	3 - Major Harm	0 - Zero Effect	OWH							
	3	Sharp objects - sharp knives and razors	3 - Major Harm	0 - Zero Effect	OWH							
	4	Sharp objects - sharp knives and razors	3 - Major Harm	0 - Zero Effect	OWH							
	5	Sharp objects - sharp knives and razors	3 - Major Harm	0 - Zero Effect	OWH							
	6	Sharp objects - sharp knives and razors	3 - Major Harm	0 - Zero Effect	OWH							
	7	Sharp objects - sharp knives and razors	3 - Major Harm	0 - Zero Effect	OWH							

# Ocean Scepter Hazard Register

ID	Hazard Source and Hazardous Event	Worst Case Reasonable Consequence		Preventive Control Measures			Administrative			Technical			Recovery Control Measures			Residual Risk		
		Health & Safety	Environment	Categorization	Control	Administrative	C	P	Health & Safety	C	P	Administrative	C	P	Health & Safety	C	P	Environment
09.01	Weather																	
1	Excessive wind/helicopter travel operations	Top Event = Excessive operational limits	Outcomes = Loss of control over equipment and operations															
2	Excessive wind/helicopter arrival/departure operations	5 - Multiple Failures	0 - Zero Effect	MNH														
3	Excessive wind/care/berthing operations	5 - Multiple Failures	0 - Zero Effect	MNH														
4	Excessive wind/care/berthing operations	5 - Multiple Failures	0 - Zero Effect	MNH														
5	Excessive wind/working at height/over the side	5 - Multiple Failures	0 - Zero Effect	MNH														
6	Excessive wind/support vessel operations	5 - Multiple Failures	0 - Zero Effect	MNH														
09.02	Sea state																	
1	Excessive sea state - helicopter/pickup operations (berthing mode)	5 - Multiple Failures	0 - Zero Effect	MNH														
2	Excessive sea state - crane offloading operations (berthing mode)	5 - Multiple Failures	0 - Zero Effect	MNH														
3	Excessive sea state - berthing operations	5 - Multiple Failures	0 - Zero Effect	MNH														
4	Excessive sea state - support vessel operations	5 - Multiple Failures	0 - Zero Effect	MNH														
5	Excessive sea state - vessel maintenance and launching	5 - Multiple Failures	0 - Zero Effect	MNH														
6	Excessive sea state - working over the side	5 - Multiple Failures	0 - Zero Effect	MNH														
7	Excessive sea state - working over the side	5 - Multiple Failures	0 - Zero Effect	MNH														
8	Excessive sea state - deck/cargo operations (berthing mode)	4 - Single Failure	0 - Zero Effect	OWH														
9	Excessive sea state - deck/cargo operations (berthing mode)	4 - Single Failure	0 - Zero Effect	OWH														
09.03	Tectonic																	
1	Seismic event (earthquake)	Top Event = Exceeds operational limits	Outcomes = Loss of control over equipment and operations															
10	Hot Surfaces CS																	
10.01	Process piping and equipment between 60 °C and 150 °C (140 °F and 302 °F)																	
1	Hot surfaces - compressors and fans	2 - Minor Harm	0 - Zero Effect	OWH														
2	Hot surfaces - Piping and valves	2 - Minor Harm	0 - Zero Effect	OWH														
3	Hot surfaces - Hull, interior walls and floors	2 - Minor Harm	0 - Zero Effect	OWH														
4	Hot surfaces - Hull during heat exchange/efflux	2 - Minor Harm	0 - Zero Effect	OWH														
5	Hot surfaces - engine cooling water lines	2 - Minor Harm	0 - Zero Effect	OWH														
6	Hot surfaces - insulation on lines	2 - Minor Harm	0 - Zero Effect	OWH														
7	Hot surfaces - hull/gear wharf	2 - Minor Harm	0 - Zero Effect	OWH														
8	Hot surfaces - safety cooling equipment	2 - Minor Harm	0 - Zero Effect	OWH														
9	Hot surfaces - safety equipment placement	2 - Minor Harm	0 - Zero Effect	OWH														
10	Hot surfaces - safety/valve operations	2 - Minor Harm	0 - Zero Effect	OWH														
10.02	Steam piping																	
1	No Source Identified	-	-	-														
11	Hot Liquids																	
11.01	Temperatures between 100 °C and 150 °C (212 °F and 302 °F)																	
1	Hot fluids - piping/valves	2 - Minor Harm	0 - Zero Effect	OWH														
2	Hot fluids - major piping/valves	2 - Minor Harm	0 - Zero Effect	OWH														
3	Hot fluids - controls on exhausts and cooling	2 - Minor Harm	0 - Zero Effect	OWH														
4	Hot fluids - controls on exhausts and cooling	2 - Minor Harm	0 - Zero Effect	OWH														
5	Hot fluids - exhausts/cooling air vents	2 - Minor Harm	0 - Zero Effect	OWH														
11.02	Temperatures greater than 150 °C (302 °F)																	

# Ocean Scepter Hazard Register

ID	Hazard Source and Hazardous Event	Worst Case Reasonable Consequence		Preventive Control Measures	Administrative	Technical	Recovery Control Measures	Residual Risk		
		Health & Safety	Environment					C	P	Environment
12	<b>Cold Surfaces</b>			Planned Maintenance (SEMS 6.3)	FaB/Medical Care (SEMS 6.17)	FaB/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10)	2	C - Has occurred in company	C2
1	Heli Liquids - galley cooling oils and fats	3 - Major Harm	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	2	C - Has occurred in company	C2
12.01	Process piping between -25 °C and +60 °C (+13 °F and +112 °F)	Top Event = Unsafe proximity with cold surface	Outcomes = Personnel contact with cold surface	Planned Maintenance (SEMS 6.3)	FaB/Medical Care (SEMS 6.17)	FaB/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10)	2	C - Has occurred in company	C2
1	Cold - refrigeration base - maintenance operations	2 - Minor Harm	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	2	C - Has occurred in company	C2
2	Cold ocean - helicopter ditching and escape to sea	2 - Minor Harm	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	2	C - Has occurred in company	C2
3	Cold ocean - crew member survival	2 - Minor Harm	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	2	C - Has occurred in company	C2
4	Cold oil floor or cooler afterfill unit	2 - Minor Harm	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	2	C - Has occurred in company	C2
12.02	Process piping less than -40 °C (-40°F)	Top Event = Unsafe proximity with cold surface	Outcomes = Personnel contact with cold surface	Planned Maintenance (SEMS 6.3)	FaB/Medical Care (SEMS 6.17)	FaB/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10)	3	B - Has occurred in industry	B3
1	No Success Identified	-	-	-	-	-	Emergency Drill and Exercises (SEMS 10)	3	B - Has occurred in industry	B3
13	<b>Cold Fluids</b>									
13.01	Oceans, seas and lakes less than 10 °C (50 °F)	Top Event = Unsafe proximity with cold fluid	Outcomes = Personnel contact with cold fluid	Planned Maintenance (SEMS 6.3)	FaB/Medical Care (SEMS 6.17)	FaB/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10)	5	B - Has occurred in industry	B5
1	Cold ocean - fully evacuated to sea	5 - Major Failure	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	5	B - Has occurred in industry	B5
2	Cold ocean - helicopter ditching and escape to sea	5 - Major Failure	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	5	B - Has occurred in industry	B5
3	Cold ocean - fail to enter during personnel transfer	5 - Major Failure	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	5	B - Has occurred in industry	B5
4	Cold ocean - fail to enter while working over the side	5 - Major Failure	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	5	B - Has occurred in industry	B5
14	<b>Open Flame</b>									
14.4.01	Heaters with fire tube	Top Event = Fire ignition	Outcomes = Fire	Planned Maintenance (SEMS 6.3)	FaB/Medical Care (SEMS 6.17)	FaB/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10)	3	B - Has occurred in industry	B3
1	No Success Identified	-	-	-	-	-	Emergency Drill and Exercises (SEMS 10)	3	B - Has occurred in industry	B3
14.4.02	Direct fired furnaces	Top Event = Fire ignition	Outcomes = Fire	Planned Maintenance (SEMS 6.3)	FaB/Medical Care (SEMS 6.17)	FaB/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10)	3	B - Has occurred in industry	B3
1	No Success Identified	-	-	-	-	-	Emergency Drill and Exercises (SEMS 10)	3	B - Has occurred in industry	B3
14.03	<b>Flares</b>									
1	Flare - stored in flares	3 - Major Harm	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Planned Maintenance (SEMS 6.3)	3	B - Has occurred in industry	B3
2	Flare - stored in barrels	3 - Major Harm	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Planned Maintenance (SEMS 6.3)	3	B - Has occurred in industry	B3
3	Flare - stored in container	3 - Major Harm	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Planned Maintenance (SEMS 6.3)	3	B - Has occurred in industry	B3
4	Open flame - welding equipment	2 - Minor Harm	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Planned Maintenance (SEMS 6.3)	2	C - Has occurred in company	C2
5	Open flame - matches (smoking areas)	1 - Slight Harm	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Planned Maintenance (SEMS 6.3)	1	B - Has occurred in industry	B1
6	Open flame - cigarettes	1 - Slight Harm	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Planned Maintenance (SEMS 6.3)	1	B - Has occurred in industry	B1
15	<b>Electricty</b>									
15.01	Voltage = 5kV To 440 V in cables	Top Event = Loss of containment	Outcomes = Personnel exposure	Planned Maintenance (SEMS 6.3)	FaB/Medical Care (SEMS 6.17)	FaB/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10)	4	B - Has occurred in industry	B4
1	Electricity in cables - general facility electrical equipment	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
2	Electricity in cables - general facility electrical wiring and panels	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
3	Electricity in cables - general electrical maintenance operations	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
4	Electricity in cables - electrical testing equipment	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
15.02	Voltage = 5kV To 440 V in equipment	Top Event = Loss of containment	Outcomes = Personnel exposure	Planned Maintenance (SEMS 6.3)	FaB/Medical Care (SEMS 6.17)	FaB/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10)	4	B - Has occurred in industry	B4
1	Electricity - equipment - general maintenance operations	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
2	Electricity - equipment - cables - electrical equipment	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
3	Electricity - equipment - general facility service points	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
4	Electricity - equipment - navigation lighting system	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
5	Electricity - equipment - lighting	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
6	Electricity - equipment - lighting equipment	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
7	Electricity - equipment - general facility electrical tools	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
8	Electricity - equipment - electrical parts	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
9	Electricity - equipment - portable and hand working equipment	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
10	Electricity - equipment - electrical wiring in aircraft	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
11	Electricity - equipment - personal electrical equipment	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
15.03	Voltage = 400 V	Top Event = Loss of containment	Outcomes = Personnel exposure	Planned Maintenance (SEMS 6.3)	FaB/Medical Care (SEMS 6.17)	FaB/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10)	4	B - Has occurred in industry	B4
1	Electricity - 400V - compressor	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
2	Electricity - 400V - compressors	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
3	Electricity - 400V - general facility service points	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
4	Electricity - 400V - APU unit	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
5	Electricity - 400V - air discharge pump	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
6	Electricity - 400V - tube air compressor	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
7	Electricity - 400V - current cell	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
8	Electricity - 400V - starters	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
9	Electricity - 400V - air circulation fans	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
10	Electricity - 400V - light fixtures	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
11	Electricity - 400V - electrical test panel	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
12	Electricity - 400V - emergency power generators	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
13	Electricity - 400V - general power switchboards	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
14	Electricity - 400V - emergency power transformers	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
15	Electricity - 400V - engine driven generator	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4
16	Electricity - 400V - vehicle charging station	4 - Severe Injury	OWH	0 - Zero Effect	OWH	0 - Zero Effect	Emergency Drill and Exercises (SEMS 10)	4	B - Has occurred in industry	B4

# Ocean Scepter Hazard Register

ID	Hazard Source and Hazardous Event	Worst Case Reasonable Consequence			Preventive Control Measure			Administrative			Technical			Residual Risk		
		Health & Safety	Environment	Citizens	Technician	Administrative	C	P	Habitat & Safety	C	P	Administrative	C	P	Environment	
17	Electrical - 440V - power equipment	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
18	Electrical - 440V - general 10V power requirements	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
19	Electrical - 440V - earthing box	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
20	Electrical - 440V - hot water heater units	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
21	Electrical - 440V - packing station system	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
22	Electrical - 440V - packing stations	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
23	Electrical - 440V - laundry equipment	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
24	Electrical - 440V - LHM equipment	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
25	Electrical - 440V - LED panels	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
26	Electrical - 440V - main power generators	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
27	Electrical - 440V - main power distribution	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
28	Electrical - 440V - main power transformers	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
29	Electrical - 440V - moving vehicles	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
30	Electrical - 440V - road signifiers	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
31	Electrical - 440V - road signs	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
32	Electrical - 440V - relay system separator rates	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
33	Electrical - 440V - SC1 panels	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
34	Electrical - 440V - storage treatment unit	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
35	Electrical - 440V - trailer trailers	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
36	Electrical - 440V - cockpit	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
37	Electrical - 440V - navigation equipment (ANAV) conferences (two)	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
38	Electrical - 440V - service vehicles	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
39	Electrical - 440V - seat control equipment	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
40	Electrical - 440V - seating unit	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
41	Electrical - 440V - site light unit	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
16.04	<b>Lightning strike</b>	Top Event = Loss of containment Outcomes = Personnel exposure			Weather Forecasting (SEMS 10.1)			Emergency Response Manual (SEMS 10.1)			B4			B4		
1	Lightning strike - device	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
2	Lightning strike - crews	4 - Single Faulty	0 - Zero Effect	OWH					4 - Has occurred in industry	B4	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
16.05	<b>Electrostatic energy</b>	Top Event = Loss of containment Outcomes = Personnel exposure			Facility Medical Care (SEMS 6.17)			Emergency Response Manual (SEMS 10.1)			B4			B4		
1	Electrostatic discharge - communication cables and devices	2 - Minor Harm	0 - Zero Effect	OWH					2 - Has occurred in industry	B2	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
2	Electrostatic discharge - telephone handset	2 - Minor Harm	0 - Zero Effect	OWH					2 - Has occurred in industry	B2	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
3	Electrostatic discharge - high pressure washing	2 - Minor Harm	0 - Zero Effect	OWH					2 - Has occurred in industry	B2	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
4	Electrostatic discharge - medical bulb, handle, name	2 - Minor Harm	0 - Zero Effect	OWH					2 - Has occurred in industry	B2	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
5	Electrostatic discharge - positive ventilation plenums in rooms	2 - Minor Harm	0 - Zero Effect	OWH					2 - Has occurred in industry	B2	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
16	<b>Electromagnetic Radiation</b>	Top Event = Exposure limit exceeded Outcomes = Personnel exposure to high level radiation			FAC/Medical Care (SEMS 6.17)			Emergency Response Manual (SEMS 10.1)			C3			C3		
16.01	<b>Infrared radiation</b>	Top Event = Exposure limit exceeded Outcomes = Personnel exposure			Planned Maintenance (SEMS 6.3)			Emergency Response Manual (SEMS 10.1)			C - Has occurred in company			C - Has occurred in company		
16.02	Top Event = Exposure limit exceeded Outcomes = Personnel exposure			Planned Maintenance (SEMS 3.4)			Job Safety Analysis (SEMS 3.9)			C - Has occurred in company			C - Has occurred in company			
1	UV radiation - mobile units	3 - Major Harm	0 - Zero Effect	OWH					2 - Has occurred in industry	B2	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
2	UV radiation - A31 water sterilization units	3 - Major Harm	0 - Zero Effect	OWH					2 - Has occurred in industry	B2	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
3	UV radiation - medical equipment	2 - Minor Harm	0 - Zero Effect	OWH					2 - Has occurred in industry	B2	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
4	UV radiation - entertainment	2 - Minor Harm	0 - Zero Effect	OWH					2 - Has occurred in industry	B2	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
16.04	<b>Lasers</b>	Top Event = Loss of containment Outcomes = Personnel exposure			FAC/Medical Care (SEMS 6.17)			Emergency Response Manual (SEMS 10.1)			C - Has occurred in company			C - Has occurred in company		
16.03	<b>Microwaves</b>	Top Event = exposure limit exceeded Outcomes = Personnel exposure to high level radiation			FAC/Medical Care (SEMS 6.17)			Emergency Response Manual (SEMS 10.1)			C - Has occurred in company			C - Has occurred in company		
1	Microwave radiation - communication interests	4 - Single Faulty	0 - Zero Effect	OWH					2 - Has occurred in industry	B2	0	B - Has occurred in industry	B0	0	B - Has occurred in industry	
2	Microwave radiation - mobile phone equipment	1 - Slight Harm	0 - Zero Effect	OWH					2 - Has occurred in industry	B2	0	B - Has occurred in industry	A0	0	B - Has occurred in industry	
3	Microwave radiation - microwave oven	1 - Slight Harm	0 - Zero Effect	OWH					1 - A - Never occurred in industry	A1	0	A - Never occurred in industry	A0	0	A - Never occurred in industry	
16.05	<b>EM radiation: high voltage AC cables</b>	Top Event = Loss of containment Outcomes = Personnel exposure			FAC/Medical Care (SEMS 6.17)			Emergency Response Manual (SEMS 10.1)			A4			A4		
1	No sources identified	-	-	-	Job Safety Analysis (SEMS 3.4)			Behavior Based Safety (OON) (SEMS 6.15)			A4			A4		
17.02	<b>Gamma ray - open source</b>	Top Event = Loss of containment Outcomes = Personnel exposure			Safe Work Practices System (SEMS 6.2)			Workplace Competency Program (SEMS 7.1)			A4			A4		
1	No sources identified	-	-	-	Incident Reporting and Investigation (SEMS 6.12)			Safe Space and Working Environment (SEMS 3.3)			A4			A4		
17.03	<b>Neutron - open source</b>	Top Event = Loss of containment Outcomes = Personnel exposure			Safe Space and Working Environment (SEMS 3.3)			Safe Space and Working Environment (SEMS 2.2)			A4			A4		
1	No sources identified	-	-	-	Emergency Response Manual (SEMS 10.1)			Workplace Competency Program (SEMS 7.1)			A4			A4		
17.04	<b>Naturally occurring ionizing radiation (NORMS)</b>	Top Event = Loss of containment Outcomes = Personnel exposure			FAC/Medical Care (SEMS 6.17)			Emergency Response Manual (SEMS 10.1)			A2			A2		
1	Naturally occurring ionizing radiation - NORMS (radioactive materials)	2 - Minor Harm	0 - Zero Effect	OWH					2 - Has occurred in industry	A1	0	A - Never occurred in industry	A0	0	A - Never occurred in industry	

# Ocean Scepter Hazard Register

ID	Hazard Source and Hazardous Event	Worst Case Reasonable Consequence			Preventive Control Measures			Administrative			Technical			Reactive Control Measures			Residual Risk			
		Health & Safety	Environment	Category			C			Habitat & Safety	C	P			Habitat & Safety	C	P	Environment		
<b>Ionizing radiation - Closed source</b>																				
18.01	Alpha, beta - closed source	Top Event = Loss of containment Outcomes = Personnel exposure			0 - Zero Effect	OWH														
1	Alpha, beta closed source - drilling rigging tools / storage areas / lockers	2 - Minor Harm			2 - Minor Harm	OWH												B2	0	B - Has occurred in industry
2	Alpha, beta strong radiation - non-destructive testing (NDT)	2 - Minor Harm			0 - Zero Effect	OWH												B2	0	B - Has occurred in industry
3	Alpha, beta strong radiation - well logging equipment / storage areas / lockers	2 - Minor Harm			0 - Zero Effect	OWH												B2	0	B - Has occurred in industry
18.02	Gamma ray - closed source	Top Event = Loss of containment Outcomes = personnel exposure																		
1	Gamma ionizing radiation - capping color locators	2 - Minor Harm			0 - Zero Effect	OWH												B2	0	B - Has occurred in industry
2	Gamma ionizing radiation - well logging equipment / storage areas / lockers	2 - Minor Harm			0 - Zero Effect	OWH											B2	0	B - Has occurred in industry	
18.03	Neutron - closed source	Top Event = Loss of containment Outcomes = personnel exposure																		
1	Neutron ionizing radiation - well logging tools / storage areas / lockers	2 - Minor Harm			0 - Zero Effect	OWH											B2	0	B - Has occurred in industry	
<b>Astrophysics</b>																				
18.04	Inufficient oxygen Atmospheres	Top Event = Loss of containment Outcomes = Personnel exposure																		
1	Inufficient oxygen - confined space entry operations	5 - Major Failures			0 - Zero Effect	MH											B5	0	B - Has occurred in industry	
18.05	Excessive CO2	Top Event = Loss of containment Outcomes = Personnel exposure																		
1	CO2 - fire suppression system - main engine room	5 - Major Failures			0 - Zero Effect	MH											B5	0	B - Has occurred in industry	
2	CO2 - fire suppression system - emergency generator room	5 - Major Failures			0 - Zero Effect	MH											B5	0	B - Has occurred in industry	
3	CO2 - fire suppression system - CCO2 boost room	4 - Single Faulty			0 - Zero Effect	OWH											B4	0	B - Has occurred in industry	
4	CO2 - fire suppression system - paint locker	4 - Single Faulty			0 - Zero Effect	OWH											B4	0	B - Has occurred in industry	
5	CO2 - fire suppression system - above decking	2 - Minor Harm			0 - Zero Effect	OWH											B2	0	B - Has occurred in industry	
18.06	Drowning	Top Event = Loss of proximity to liquid orphyate Outcomes = Personnel exposure																		
1	Drowning - man overboard	4 - Single Faulty			0 - Zero Effect	OWH											C4	0	C - Has occurred in company	
2	Drowning - boats in tanks (confined space)	4 - Single Faulty			0 - Zero Effect	OWH											B4	0	B - Has occurred in industry	
18.07	Excessive H2	Top Event = Loss of containment Outcomes = Personnel exposure																		
1	N2 - transportable nitrogen tanks	4 - Single Faulty			0 - Zero Effect	OWH											A4	0	A - Never occurred in industry	
2	N2 - BOP API PNs	1 - Slight Harm			0 - Zero Effect	OWH											A1	0	A - Never occurred in industry	
3	N2 - conductor blowout system API6	1 - Slight Harm			0 - Zero Effect	OWH											A1	0	A - Never occurred in industry	
4	N2 - vibrating support/piping dampeners	1 - Slight Harm			0 - Zero Effect	OWH											A1	0	A - Never occurred in industry	
18.08	Helium	Top Event = Loss of containment Outcomes = Personnel exposure																		
1	No sources identified	-			-	No source														
18.09	Smoke	Top Event = Loss of containment Outcomes = Personnel exposure																		
1	Smoke - fire fighting and rescue	5 - Major Failures			0 - Zero Effect	MH											B5	0	B - Has occurred in industry	
2	Smoke - fire escape and evacuation	5 - Major Failures			0 - Zero Effect	MH											B5	0	B - Has occurred in industry	
20	<b>Toxic Gs</b>			Top Event = Loss of containment Outcomes = Personnel exposure Environmental Discharging																
20.01	H2S/hydrogen sulfide, sour gas	Top Event = Loss of containment Outcomes = Personnel exposure																		
1	H2S - original blowout	5 - Major Failures			1 - Slight Effect	MH											B5	1	B - Has occurred in industry	
2	H2S - drilling fluid controls	5 - Major Failures			1 - Slight Effect	MH											B5	1	B - Has occurred in industry	
3	H2S - accident release from adjacent well platform	5 - Major Failures			1 - Slight Effect	MH											B5	1	B - Has occurred in industry	
4	H2S - confined spaces entry - basic breaths	5 - Major Failures			0 - Zero Effect	MH											B5	0	B - Has occurred in industry	
5	H2S - H2S senior calibration bottles	1 - Slight Harm			0 - Zero Effect	OWH											A1	0	A - Never occurred in industry	
6	H2S - stepped in forming cones	1 - Slight Harm			0 - Zero Effect	OWH											B1	0	B - Has occurred in industry	
7	H2S - stepped in logging tools	1 - Slight Harm			0 - Zero Effect	OWH											B1	0	B - Has occurred in industry	
20.02	Exhaust fumes	Top Event = Loss of containment Outcomes = Personnel exposure Environmental Discharging																		
1	Exhaust fumes - expert control engine exhaust	1 - Slight Harm			1 - Slight Effect	OWH											B1	1	B - Has occurred in industry	
2	Exhaust fumes - main engine exhaust	1 - Slight Harm			1 - Slight Effect	OWH											B1	1	B - Has occurred in industry	
3	Exhaust fumes - emergency generator exhaust	1 - Slight Harm			1 - Slight Effect	OWH											B1	1	B - Has occurred in industry	
4	Exhaust fumes - control exhaust	1 - Slight Harm			1 - Slight Effect	OWH											B1	1	B - Has occurred in industry	
5	Exhaust fumes - helicopter exhaust	1 - Slight Harm			1 - Slight Effect	OWH											B1	1	B - Has occurred in industry	
6	Exhaust fumes - Heli crane exhaust	1 - Slight Harm			1 - Slight Effect	OWH											B1	1	B - Has occurred in industry	
7	Exhaust fumes - deck crane engine exhaust	1 - Slight Harm			1 - Slight Effect	OWH											B1	1	B - Has occurred in industry	
8	Exhaust fumes - service company / deck gear winter units	1 - Slight Harm			1 - Slight Effect	OWH											B1	1	B - Has occurred in industry	

# Ocean Scepter Hazard Register

ID	Hazard Identifier	Hazard Source and Hazardous Event	Worst Case Reasonable Consequence			Preventive Control Measure	Administrative	Technical	C	P	Health & Safety	C	P	Residual Risk
			Health & Safety	Environment	Category									
20.03	Sulphur dioxide	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	No sources identified	-	-	-	-	-	-	-	-	-	-	-	-	-
20.04	Benzene	Top Event = Loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	No sources identified	-	-	-	-	-	-	-	-	-	-	-	-	-
20.05	Chlorite	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	Chlorine - storage instrument plant	1 - Sight/Harm	1 - Sight Effect	OWH	-	-	-	-	-	-	-	-	-	-
20.06	Welding fumes	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	Welding fume - portable and fixed welding equipment - involving operations	2 - Minor Harm	0 - Zero Effect	OWH	Portable Ventilation System Workstation Designated for Work Area	-	-	-	-	-	-	-	-	-
2	Welding fume - welding shop	2 - Minor Harm	0 - Zero Effect	OWH	-	-	-	-	-	-	-	-	-	-
20.07	Tobacco smoke	Top Event = loss of containment Outcomes = Personnel exposure	-	-	-	-	-	-	-	-	-	-	-	-
21.07	Tobacco smoke - passive smoking exposure in smoking areas	1 - Sight/Harm	0 - Zero Effect	OWH	Designated Smoking Areas	-	-	-	-	-	-	-	-	-
20.08	CFCs	Top Event = loss of containment Outcomes = Personnel exposure	-	-	-	-	-	-	-	-	-	-	-	-
1	No sources identified	-	-	-	-	-	-	-	-	-	-	-	-	-
2.1	Toxic Fluid	-	-	-	-	-	-	-	-	-	-	-	-	-
21.01	Mercury	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	Mercury - fluorescent light tubes	1 - Sight/Harm	1 - Sight Effect	OWH	Job Safety Analysis (JSA) (SMS 6.2.1.5) Behavior Based Safety (OQD) (SMS 6.2.1.5) Safe Work Practices System (SMS 6.2.2) Area Housekeeping (SMS 6.2.3) Work Area Inspection (SMS 6.2.4) Workplace Competency Program (SMS 7.1) Work Management Plan	-	-	-	-	-	-	-	-	-
2	Mercury - medical instruments	1 - Sight/Harm	1 - Sight Effect	OWH	-	-	-	-	-	-	-	-	-	-
21.02	PCBs	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	No sources identified	-	-	-	-	-	-	-	-	-	-	-	-	-
21.03	Biocide (glutaraldehyde)	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	Biocide - sick room - mad additive	1 - Sight/Harm	1 - Sight Effect	OWH	Proper Storage Containers Designated Storage Areas	-	-	-	-	-	-	-	-	-
21.04	Methanol	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	Methanol - methanol hydrate prevention	5 - Major Failure	3 - Minor Effect	NH	Refer to Major Bottle Analysis - BT002: Hydrocarbons in Water Testing Equipment	-	-	-	-	-	-	-	-	-
21.05	Brines	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	Brines - drilling fluids	2 - Minor Harm	1 - Sight Effect	OWH	Job Safety Analysis (JSA) (SMS 6.2.1.5) Behavior Based Safety (OQD) (SMS 6.2.1.5) Safe Work Practices System (SMS 6.2.2) Area Housekeeping (SMS 6.2.3) Work Area Inspection (SMS 6.2.4) Workplace Competency Program (SMS 7.1) Occupational Health Practice (SMS 8.1) Med Processing Procedure (SMS 5.3)	-	-	-	-	-	-	-	-	-
2	Brines - water makes unit discharge	2 - Minor Harm	1 - Sight Effect	OWH	-	-	-	-	-	-	-	-	-	-
21.06	Glycols	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	Glycols - drilling fluid additive	1 - Sight/Harm	1 - Sight Effect	OWH	Proper Storage Containers Designated Storage Areas	-	-	-	-	-	-	-	-	-
2	Glycols - mineral oil engine cooling water additive	1 - Sight/Harm	1 - Sight Effect	OWH	-	-	-	-	-	-	-	-	-	-
3	Glycols - vegetable/glycerin engine cooling water additive	1 - Sight/Harm	1 - Sight Effect	OWH	-	-	-	-	-	-	-	-	-	-
4	Glycols - crane engine cooling water additive	1 - Sight/Harm	1 - Sight Effect	OWH	-	-	-	-	-	-	-	-	-	-
5	Glycols - cement unit engine cooling water additive	1 - Sight/Harm	1 - Sight Effect	OWH	-	-	-	-	-	-	-	-	-	-
6	Glycols - dehumidifier cooling water additive	1 - Sight/Harm	1 - Sight Effect	OWH	-	-	-	-	-	-	-	-	-	-
21.07	Degreasers (temperatures)	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	Degreasers - maintenance cleaning operations	2 - Minor Harm	1 - Sight Effect	OWH	Job Safety Analysis (JSA) (SMS 6.2.1.5) Behavior Based Safety (OQD) (SMS 6.2.1.5) Safe Work Practices System (SMS 6.2.2) Area Housekeeping (SMS 6.2.3) Work Area Inspection (SMS 6.2.4) Workplace Competency Program (SMS 7.1) Occupational Health Practice (SMS 8.1)	-	-	-	-	-	-	-	-	-
21.08	Iso-organanes	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	Iso-organanes - part of other - refrigerants - non-petroleum	3 - Major Harm	0 - Zero Effect	OWH	Proper Storage Containers Designated Storage Areas	-	-	-	-	-	-	-	-	-
21.09	Sulfuric acid	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	No sources identified	-	-	-	-	-	-	-	-	-	-	-	-	-
21.10	Amines	Top Event = loss of containment Outcomes = Personnel exposure, Environmental Discharge	-	-	-	-	-	-	-	-	-	-	-	-
1	Corrosion inhibitors - maintenance operations	1 - Sight/Harm	0 - Zero Effect	OWH	Job Safety Analysis (JSA) (SMS 6.2.1.5) Behavior Based Safety (OQD) (SMS 6.2.1.5) Safe Work Practices System (SMS 6.2.2)	-	-	-	-	-	-	-	-	-
2	Corrosion inhibitors - main engine cooling water	1 - Sight/Harm	0 - Zero Effect	OWH	-	-	-	-	-	-	-	-	-	-

# Ocean Scepter Hazard Register

ID	Hazard Source and Hazardous Event	Worst Case Reasonable Consequence		Preventive Control Measures	Recovery Control Measures		Residual Risk		
		Health & Safety	Environment		Administrative	Technical	C	P	
3	Corrosion inhibitors emergency rigging cooling water	1 - Sight Harm 0 - Zero Effect	OWH	Safety Standard (SMS) 6.2.1.3 Work Area Inspection Workshop Competency Program (SMS) 7.1)	Safety Standard (SMS) 6.1.7 Safety Response Kit	Fish/Medical Care (SMS) 6.1.7 Medical/Care of casualties (SMS) 6.2.1) Personnel Protective Equipment (SMS) 6.2.1)	C - Has occurred in company C - Has occurred in industry	C0	
4	Corrosion inhibitors cause cooler unit water leak	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
5	Corrosion inhibitors cause cooler unit water	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
6	Corrosion inhibitors cause unit water cooling water	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
7	Corrosion inhibitors B/D control tanks	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
8	Corrosion inhibitors B/D bottom flaps	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
9	Corrosion inhibitors parking procedure	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
21.1.2	<b>Scale inhibitor/borates</b>	Top Event = Loss of containment Outcomes = Personnel exposure, Environmental Discharge		Job Safety Analysis (SMS) 3.5 Behavior Based Safety (OOS) (SMS) 6.2.1.5 Safe Work Practices System (SMS) 6.2.2 Area Housekeeping (SMS) 6.1.3 Workshop Competency Program (SMS) 7.1)	Marine Safety Data Sheets	Fish/Medical Care (SMS) 6.1.7 Medical/Care of casualties (SMS) 6.2.1) Personnel Protective Equipment (SMS) 6.2.1)	B - Has occurred in industry B - Has occurred in industry	B0	
1	Scale inhibitor cause engine cooling water system	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
2	Scale inhibitor emergency rigging cooling water	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
3	Scale inhibitor cause cooler unit water	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
4	Scale inhibitor cause engine cooling water system	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
5	Scale inhibitor cause unit engine cooling water system	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
6	Scale inhibitor cause engine heat exchanger generator unit	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
7	Scale inhibitor reverse osmosis water generator unit	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company C - Has occurred in industry	C0	
21.1.3	<b>Liquid additives (metaphosphates)</b>	Top Event = Loss of containment Outcomes = Personnel exposure, Environmental Discharge		Job Safety Analysis (SMS) 3.5 Behavior Based Safety (OOS) (SMS) 6.2.1.5 Safe Work Practices System (SMS) 6.2.2 Area Housekeeping (SMS) 6.1.3 Workshop Competency Program (SMS) 7.1)	Marine Safety Data Sheets	Fish/Medical Care (SMS) 6.1.7 Medical/Care of casualties (SMS) 6.2.1) Personnel Protective Equipment (SMS) 6.2.1)	C - Has occurred in company C - Has occurred in industry	C3	
1	Liquid additives - mid-mix operations	3 - Major Harm 2 - Local Effect	OWH				C - Has occurred in company C - Has occurred in industry	C2	
2	Liquid additives - drift operations	1 - Sight Harm 2 - Local Effect	OWH				C - Has occurred in company C - Has occurred in industry	C2	
11.1.4	Top Event = Loss of containment Outcomes = Personnel exposure, Environmental Discharge		-	-	-	-	-	-	
1	No sources identified	-	-	-	-	-	-	-	
11.1.5	<b>Alcohol-containing beverages</b>	Top Event = Present on Facility Outcome = Personnel exposure - Human error related accident		5 - Major Failures 0 - Zero Effect	MHI	Ref to Major Bowes Analysis - BT2020 - Dependence on Human Performance - Human Error	A - Never occurred in industry	A0	
1	Alcohol - person not wearing to safety	5 - Major Failures 0 - Zero Effect	OWH				A - Never occurred in industry	A0	
11.1.6	Top Event = Controlled Accidents Failure - Outcomes = Personnel exposure, Environmental Discharge		-	-	-	-	-	-	
1	Dope - person not wearing to safety	5 - Major Failures 0 - Zero Effect	OWH				A - Never occurred in industry	A0	
2	Dope - prescribed and wear straps	5 - Major Failures 0 - Zero Effect	OWH				A - Never occurred in industry	A0	
11.1.7	<b>Used engine oil</b>	Top Event = Loss of containment Outcomes = Personnel exposure, Environmental Discharge		Job Safety Analysis (SMS) 3.5 Behavior Based Safety (OOS) (SMS) 6.2.1.5 Safe Work Practices System (SMS) 6.2.2 Area Housekeeping (SMS) 6.1.3 Workshop Competency Program (SMS) 7.1)	Marine Safety Data Sheets	Fish/Medical Care (SMS) 6.1.7 Medical/Care of casualties (SMS) 6.2.1) Personnel Protective Equipment (SMS) 6.2.1)	B - Has occurred in industry B - Has occurred in industry	B1	
1	Used engine oil - maintenance operations	1 - Sight Harm 2 - Local Effect	OWH				B - Has occurred in industry	B1	
2	Used engine oil - waste bins - oily rags	1 - Sight Harm 2 - Local Effect	OWH				B - Has occurred in industry	B1	
3	Used engine oil - dry oil tank	1 - Sight Harm 2 - Local Effect	OWH				B - Has occurred in industry	B1	
4	Used engine oil/tube - oil tank	1 - Sight Harm 2 - Local Effect	OWH				B - Has occurred in industry	B2	
21.1.8	<b>Carbon tetrachloride</b>	Top Event = Loss of containment Outcomes = Personnel exposure, Environmental Discharge		-	-	-	-	-	
1	No sources identified	-	-	-	-	-	-	-	
21.1.9	<b>Grey and/or black water</b>	Top Event = Loss of containment Outcomes = Personnel exposure, Environmental Discharge		3 - Major Harm 2 - Local Effect	OWH	Pitless Waterline (SMS) 6.1.3 Pitless To Waste System (SMS) 3.9 Fume/Water System (SMS) 6.2.1 Workshop Competency Program (SMS) 7.1)	B - Has occurred in industry	B2	
1	Grey / Black water storage treatment system	3 - Major Harm 2 - Local Effect	OWH				B - Has occurred in industry	B2	
2	Grey / Black water - toilet, drains and sink	1 - Sight Harm 2 - Local Effect	OWH				B - Has occurred in industry	B2	
3	Grey / Black water - toilet, drains and sink	1 - Sight Harm 2 - Local Effect	OWH				B - Has occurred in industry	B2	
22	<b>Toxic Solids</b>		-	-	-	-	-	-	
22.0.1	<b>Asbestos</b>	Top Event = Loss of containment Outcomes = Personnel exposure		-	-	-	-	-	
1	No sources identified	-	-	-	-	-	-	-	
22.0.2	<b>Man-made mineral fiber</b>	Top Event = Loss of containment Outcomes = Personnel exposure		1 - Sight Harm 0 - Zero Effect	OWH	Job Safety Analysis (SMS) 3.5 Behavior Based Safety (OOS) (SMS) 6.2.1.5 Safe Work Practices System (SMS) 6.2.2 Area Housekeeping (SMS) 6.1.3 Workshop Competency Program (SMS) 7.1)	Fish/Medical Care (SMS) 6.1.7 Medical/Care of casualties (SMS) 6.2.1) Personnel Protective Equipment (SMS) 6.2.1)	C - Has occurred in company C - Has occurred in industry	C0
1	Man-made mineral fiber - maintenance operations, cutting and grinding	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in industry	C0	
2	Man-made mineral fiber - LCM - back room	1 - Sight Harm 0 - Zero Effect	OWH				B - Has occurred in industry	B0	
3	Man-made mineral fiber - brittle wires and pads,	1 - Sight Harm 0 - Zero Effect	OWH				A - Never occurred in industry	A0	
4	Man-made mineral fiber - accommodation insulation material	1 - Sight Harm 0 - Zero Effect	OWH				A - Never occurred in industry	A0	
5	Man-made mineral fiber - engine heat exchanger insulation material	1 - Sight Harm 0 - Zero Effect	OWH				A - Never occurred in industry	A0	
6	Man-made mineral fiber - tank or heat exchangers	1 - Sight Harm 0 - Zero Effect	OWH				A - Never occurred in industry	A0	
22.0.3	<b>Cement dust</b>	Top Event = Loss of containment Outcomes = Personnel exposure		-	-	-	-	-	
1	Cement dust - tank maintenance	1 - Sight Harm 0 - Zero Effect	OWH				C - Has occurred in company	C0	
2	Cement dust - concrete cleaning agents	2 - Minor Harm	OWH				B - Has occurred in industry	B0	
3	Cement dust - concrete maintenance	2 - Minor Harm	OWH				B - Has occurred in industry	B0	
4	Cement dust - air filter maintenance	1 - Sight Harm 0 - Zero Effect	OWH				B - Has occurred in industry	B1	
22.0.4	<b>Sodium hypochlorite (bleach)</b>	Top Event = Loss of containment Outcomes = Personnel exposure, Environmental Discharge		Designated Storage and Containers	Job Safety Analysis (SMS) 3.5 Behavior Based Safety (OOS) (SMS) 6.2.1.5 Safe Work Practices System (SMS) 6.2.2 Area Housekeeping (SMS) 6.1.3 Workshop Competency Program (SMS) 7.1)	Fish/Medical Care (SMS) 6.1.7 Medical/Care of casualties (SMS) 6.2.1) Personnel Protective Equipment (SMS) 6.2.1)	B - Has occurred in industry	B2	
1	Bleach - galaxy bleaching agents	2 - Minor Harm	OWH				B - Has occurred in industry	B1	
2	Bleach - acid cleaner - cleaning areas	1 - Sight Harm 0 - Zero Effect	OWH				B - Has occurred in industry	B0	
3	Bleach - hydrolysis - cement unit	1 - Sight Harm 0 - Zero Effect	OWH				B - Has occurred in industry	B0	
4	Bleach - hydrolysis - cement unit - concrete maintenance	1 - Sight Harm 0 - Zero Effect	OWH				B - Has occurred in industry	B0	
5	Bleach - hydrolysis - concrete cleaning agent	1 - Sight Harm 0 - Zero Effect	OWH				B - Has occurred in industry	B0	
22.0.5	<b>Powdered mud additives</b>	Top Event = Loss of containment Outcomes = Personnel exposure, Environmental Discharge		Job Safety Analysis (SMS) 3.5 Behavior Based Safety (OOS) (SMS) 6.2.1.5 Safe Work Practices System (SMS) 6.2.2 Area Housekeeping (SMS) 6.1.3 Workshop Competency Program (SMS) 7.1)	Marine Safety Data Sheets	Fish/Medical Care (SMS) 6.1.7 Medical/Care of casualties (SMS) 6.2.1) Personnel Protective Equipment (SMS) 6.2.1)	B - Has occurred in industry	B0	
1	Powdered mud additives - hole in tank maintenance	1 - Sight Harm 0 - Zero Effect	OWH				B - Has occurred in industry	B0	
2	Powdered mud additives - cement unit	1 - Sight Harm 0 - Zero Effect	OWH				B - Has occurred in industry	B0	
3	Powdered mud additives - cement unit - concrete maintenance	1 - Sight Harm 0 - Zero Effect	OWH				B - Has occurred in industry	B0	
4	Powdered mud additives - concrete cleaning agent	1 - Sight Harm 0 - Zero Effect	OWH				B - Has occurred in industry	B0	
5	Powdered mud additives - concrete cleaning agent	1 - Sight Harm 0 - Zero Effect	OWH				B - Has occurred in industry	B0	
22.0.6	<b>Sulfur dust</b>	Top Event = Loss of containment Outcomes = Personnel exposure, Environmental Discharge		-	-	-	-	-	

Ocean Scepter Hazard Register

# Ocean Scepter Hazard Register

ID	Hazard Source and Hazardous Event	Worst Case Reasonable Consequence			Preventive Control Measure	Administrative	Technical	Recovery Control Measures	Administrative	C	P	Residual Risk	Environment	
		Health & Safety	Environment	Category										
23.04	Caustic soda (caustic hydroxide)	Top Event = loss of containment Outcomes = Personnel exposure	Environmental Discharging	Technical										
1	Caustic soda - venting area	3 - Major Harm	OWH	Fatal Medical Care (SEMS 6.1.7)	Job Sales Analyst (SEMS 6.2.1.5)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	1	B - Has occurred in industry	B1			
2	Caustic soda - cleaning bay/areas	3 - Major Harm	1 - Single Effect	OWH	Safe Work Practices System (SEMS 6.2.2)	Safe Work Based Safety (DOD) (SEMS 6.2.1.5)	B - Has occurred in industry	B4	0	B - Has occurred in industry	B1			
3	Caustic soda - venting areas	3 - Major Harm	2 - Local Effect	OWH	Personal Protective Equipment (SEMS 6.2.1)	Incident Report and Investigations (SEMS 11.2)	B - Has occurred in industry	B3	2	B - Has occurred in industry	B2			
4	Caustic soda - cooling water treatment	3 - Major Harm	1 - Single Effect	OWH	Safety Shower / Eye Wash Stations	Marine Safety Guide (SEMS 6.2.1)	B - Has occurred in industry	B3	1	B - Has occurred in industry	B1			
5	Coolant storage - tank areas	3 - Major Harm	2 - Local Effect	OWH	Occupational Health Practices (SEMS 7.1)	Incident Report and Investigations (SEMS 11.2)	B - Has occurred in industry	B3	2	B - Has occurred in industry	B2			
24	<b>Biological Hazards</b>		Top Event = loss of containment Outcomes = Personnel exposure	Environmental Discharging										
24.01	Food-borne bacteria (e.g. e. coli)	Top Event = loss of containment Outcomes = Personnel exposure	Health & Safety	Administrative										
1	Food-borne bacteria - meat / fish / poultry	2 - Minor Harm	0 - Zero Effect	OWH	Spills Control Boards	Job Sales Analyst (SEMS 6.2.1.5)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B2	0	B - Has occurred in industry	B0		
24.02	Water-borne bacteria (e.g. legionella)	Top Event = loss of containment Outcomes = Personnel exposure	Health & Safety	Administrative										
1	Water-borne bacteria - mobile water system	2 - Minor Harm	0 - Zero Effect	OWH	Equipment Design and Specifications	Planned Maintenance (SEMS 6.3.3)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1)	B - Has occurred in industry	B2	0	B - Has occurred in industry	B0	
2	Water-borne bacteria - period water	2 - Minor Harm	0 - Zero Effect	OWH	Job Sales Analyst (SEMS 6.2.1.5)	Behavior Based Safety (DOD) (SEMS 6.2.1.5)	Personal Protective Equipment (SEMS 6.2.1)	B - Has occurred in industry	B2	0	B - Has occurred in industry	B0		
3	Water-borne bacteria - period water	2 - Minor Harm	0 - Zero Effect	OWH	Workers Cooperative Program (SEMS 7.1)	Workplace Inspection System (SEMS 6.2.2)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B2	0	B - Has occurred in industry	B0		
4	Water-borne bacteria - drainage system water	2 - Minor Harm	0 - Zero Effect	OWH	Occupational Health Practices (SEMS 7.1)	Occupational Health Practices (SEMS 7.1)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B2	0	B - Has occurred in industry	B0		
5	Water-borne bacteria - very black water	2 - Minor Harm	0 - Zero Effect	OWH										
6	Water-borne bacteria - cooling system	2 - Minor Harm	0 - Zero Effect	OWH										
24.03	Parasitic insects (pin worms, bed bugs, lice, fleas)	Top Event = loss of containment Outcomes = Personnel exposure	Health & Safety	Administrative										
1	No successful control	-	-	-										
24.04	Cold and flu virus	Top Event = loss of containment Outcomes = Personnel exposure	Health & Safety	Administrative										
1	Cold and flu virus - personnel travel / sick leave	1 - Slight Harm	0 - Zero Effect	OWH	Hand Sanitiser									
24.05	Human immunodeficiency virus (HIV)	Top Event = loss of containment Outcomes = Personnel exposure	Health & Safety	Administrative										
1	HIV - medical treatment of infected persons	3 - Major Harm	4 - Severe Injury	OWH	Accommodation Disinfecting	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B1	0	E - Multiple occurrences per year at E0	E0	
24.06	Other communicable diseases	Top Event = loss of containment Outcomes = Personnel exposure	Health & Safety	Administrative										
1	Blood-borne pathogens - sewage treatment unit	3 - Major Harm	0 - Zero Effect	OWH	Stainless Steel Containers	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
2	Blood-borne pathogens - medical treatment of infected patients	3 - Major Harm	0 - Zero Effect	OWH	Boatboarder Waste Containers	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
3	Blood-borne pathogens - bio-hazardous waste	3 - Major Harm	0 - Zero Effect	OWH	Household Waste Containers	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
4	Blood-borne pathogens - galaxy waste / oils	3 - Major Harm	0 - Zero Effect	OWH	Household Waste Containers	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
25	<b>Ergonomic Hazards</b>		Top Event = Personnel exposure	Outcomes = Exposure limit exceeded	Health & Safety	Administrative								
25.01	Manual materials handling	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded	Health & Safety	Administrative									
1	Manual handling - metal structures	3 - Major Harm	0 - Zero Effect	OWH	Mechanical lifting aids	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	C - Has occurred in company	C3	0	C - Has occurred in company	C0	
2	Manual handling - metal structures	3 - Major Harm	0 - Zero Effect	OWH	Safe Work Based Safety (DOD) (SEMS 6.2.1.5)	Safe Work Practices System (SEMS 6.2.2)	Personal Protective Equipment (SEMS 6.2.1)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	C - Has occurred in company	C3	0	C - Has occurred in company	C0	
3	Manual handling - vehicle store - stacking	3 - Major Harm	0 - Zero Effect	OWH	Vehicle Protection System (SEMS 7.1)	Vehicle Protection Equipment (SEMS 6.2.1)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	C - Has occurred in company	C3	0	C - Has occurred in company	C0		
4	Manual handling - hospital gondola / baggage	3 - Major Harm	0 - Zero Effect	OWH	Workers Cooperative Program (SEMS 7.1)	Workers Cooperative Program (SEMS 7.1)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	C - Has occurred in company	C3	0	C - Has occurred in company	C0		
5	Manual handling - accommodation stores - handling	3 - Major Harm	0 - Zero Effect	OWH	Workforce Training	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	C - Has occurred in company	C3	0	C - Has occurred in company	C0	
6	Manual handling - working while holding	3 - Major Harm	0 - Zero Effect	OWH	Workforce Training	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	C - Has occurred in company	C3	0	C - Has occurred in company	C0	
7	Manual handling - heavy items	3 - Major Harm	0 - Zero Effect	OWH	Workforce Training	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	C - Has occurred in company	C3	0	C - Has occurred in company	C0	
8	Manual handling - difficult locations	3 - Major Harm	0 - Zero Effect	OWH	Workforce Training	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	C - Has occurred in company	C3	0	C - Has occurred in company	C0	
9	Manual handling - difficult locations	3 - Major Harm	0 - Zero Effect	OWH	Workforce Training	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	C - Has occurred in company	C3	0	C - Has occurred in company	C0	
25.02	Damaging noise > L_Aeq,24h of 140 dB(A)	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded	Health & Safety	Administrative									
1	Damaging noise - pressure vessel / heat wave	3 - Major Harm	0 - Zero Effect	OWH	Saluted Signs and Whistlers (SEMS 6.2.2)	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
2	Damaging noise - pressure vessel / heat wave	3 - Major Harm	0 - Zero Effect	OWH	Safe Work Based Safety (DOD) (SEMS 6.2.1.5)	Safe Work Practices System (SEMS 6.2.2)	Personal Protective Equipment (SEMS 6.2.1)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
3	Damaging noise - Log / pump room	3 - Major Harm	0 - Zero Effect	OWH	Safe Work Based Safety (DOD) (SEMS 6.2.1.5)	Safe Work Practices System (SEMS 6.2.2)	Personal Protective Equipment (SEMS 6.2.1)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
25.03	Loud steady noise > L_Aeq,24h of 122 dB(A)	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded	Health & Safety	Administrative									
1	Loud steady noise - engine room	3 - Major Harm	0 - Zero Effect	OWH	Equipment Design and Specifications	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
2	Loud steady noise - pressure vessel / heat wave	3 - Major Harm	0 - Zero Effect	OWH	Noise Abatement	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
3	Loud steady noise - engine room	3 - Major Harm	0 - Zero Effect	OWH	Noise Abatement	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
4	Loud steady noise - engine room	3 - Major Harm	0 - Zero Effect	OWH	Noise Abatement	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
5	Loud steady noise - engine room	3 - Major Harm	0 - Zero Effect	OWH	Noise Abatement	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
6	Loud steady noise - heat / pump room	3 - Major Harm	0 - Zero Effect	OWH	Noise Abatement	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
7	Loud steady noise - heatwave	3 - Major Harm	0 - Zero Effect	OWH	Noise Abatement	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
8	Loud steady noise - cement plant area	3 - Major Harm	0 - Zero Effect	OWH	Noise Abatement	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
9	Loud steady noise - auxiliary machinery rooms	3 - Major Harm	0 - Zero Effect	OWH	Noise Abatement	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
10	Loud steady noise - engine room	3 - Major Harm	0 - Zero Effect	OWH	Noise Abatement	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0	
25.04	Heat stress (high ambient temperatures)	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded	Health & Safety	Administrative									
1	Heat stress - enclosed dock areas	4 - Severe Injury	0 - Zero Effect	OWH	Glaciators	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0	
2	Heat stress - 91°C	4 - Severe Injury	0 - Zero Effect	OWH	Glaciators	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0	
3	Heat stress - engine room	4 - Severe Injury	0 - Zero Effect	OWH	Glaciators	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0	
4	Heat stress - site office areas	4 - Severe Injury	0 - Zero Effect	OWH	Glaciators	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0	
5	Heat stress - refuel areas	4 - Severe Injury	0 - Zero Effect	OWH	Glaciators	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0	
6	Heat stress - heat / pump room	4 - Severe Injury	0 - Zero Effect	OWH	Glaciators	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0	
7	Heat stress - 40°C maximum	4 - Severe Injury	0 - Zero Effect	OWH	Glaciators	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0	
8	Heat stress - offices / factory areas	4 - Severe Injury	0 - Zero Effect	OWH	Glaciators	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0	
9	Heat stress - canteen / machinery rooms	4 - Severe Injury	0 - Zero Effect	OWH	Glaciators	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0	
10	Heat stress - crane engine cabin	4 - Severe Injury	0 - Zero Effect	OWH	Glaciators	Job Sales Analyst (SEMS 6.2.1.5)	Fatal Medical Care (SEMS 6.1.7)	Emergency Response Manual (SEMS 10) Emergency Crisis and Exercises (SEMS 10.1) Worldwide Contingency Program (SEMS 11)	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0	

# Ocean Scepter Hazard Register


ID	Hazard Source and Hazardous Event	Worst Case Reasonable Consequence			Category	Preventive Control Measure	Administrative	Technical	Recovery Control Measures	Administrative	C	P	Health & Safety	C	P	Residual Risk	Environment	
		Health & Safety	Environment	Outcomes = Exposure limit exceeded														
25.05	Cold stress (low ambient temperatures)	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded															
1	Cold stress - gassy / other / freeze	4 - Single Faulty	0 - Zero Effect	OWH														
25.06	High humidity	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded															
1	High humidity - caused sick areas	4 - Single Faulty	0 - Zero Effect	OWH	Confined Space	Job Safety Analysis (SEMS 3.5)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	4	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0		
2	High humidity - cold floor	4 - Single Faulty	0 - Zero Effect	OWH	Confined Space	Job Safety Analysis (SEMS 3.5)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	4	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0		
3	High humidity - cargo room	4 - Single Faulty	0 - Zero Effect	OWH	Confined Space	Job Safety Analysis (SEMS 3.5)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	4	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0		
4	High humidity - trailer area	4 - Single Faulty	0 - Zero Effect	OWH	Confined Space	Job Safety Analysis (SEMS 3.5)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	4	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0		
5	High humidity - cold rooms	4 - Single Faulty	0 - Zero Effect	OWH	Confined Space	Job Safety Analysis (SEMS 3.5)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	4	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0		
6	High humidity - washroom	4 - Single Faulty	0 - Zero Effect	OWH	Confined Space	Job Safety Analysis (SEMS 3.5)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	4	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0		
7	Hip bending - elbow fatiguing	4 - Single Faulty	0 - Zero Effect	OWH	Confined Space	Job Safety Analysis (SEMS 3.5)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	4	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0		
8	Hip bending - confined space entry	4 - Single Faulty	0 - Zero Effect	OWH	Confined Space	Job Safety Analysis (SEMS 3.5)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	4	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0		
9	Hip bending - ceiling hatch access	4 - Single Faulty	0 - Zero Effect	OWH	Confined Space	Job Safety Analysis (SEMS 3.5)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	4	B - Has occurred in industry	B4	0	B - Has occurred in industry	B0		
10	Vibration	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded															
1	Vibration - maintenance operations - lifting and tools	3 - Major Harm	0 - Zero Effect	OWH	Equipment Design and Specifications	Planned Maintenance (SEMS 6.3)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	3	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0		
2	Vibration - vibration in areas	4 - Single Faulty	0 - Zero Effect	OWH	Job Safety Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	1	B - Has occurred in industry	B1	0	B - Has occurred in industry	B0		
3	Vibration - emergency generator rooms	4 - Single Faulty	0 - Zero Effect	OWH	Job Safety Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	1	B - Has occurred in industry	B1	0	B - Has occurred in industry	B0		
4	Vibration - cold floor	4 - Single Faulty	0 - Zero Effect	OWH	Job Safety Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	1	B - Has occurred in industry	B1	0	B - Has occurred in industry	B0		
5	Vibration - general use area	4 - Single Faulty	0 - Zero Effect	OWH	Job Safety Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	1	B - Has occurred in industry	B1	0	B - Has occurred in industry	B0		
6	Vibration - R&D area	4 - Single Faulty	0 - Zero Effect	OWH	Job Safety Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	1	B - Has occurred in industry	B1	0	B - Has occurred in industry	B0		
7	Vibration - anti fire area	4 - Single Faulty	0 - Zero Effect	OWH	Job Safety Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	1	B - Has occurred in industry	B1	0	B - Has occurred in industry	B0		
8	Vibration - main pump room	4 - Single Faulty	0 - Zero Effect	OWH	Job Safety Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	1	B - Has occurred in industry	B1	0	B - Has occurred in industry	B0		
9	Vibration - engine room	4 - Single Faulty	0 - Zero Effect	OWH	Job Safety Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	1	B - Has occurred in industry	B1	0	B - Has occurred in industry	B0		
10	Vibration - washing machine rooms	4 - Single Faulty	0 - Zero Effect	OWH	Job Safety Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	1	B - Has occurred in industry	B1	0	B - Has occurred in industry	B0		
25.08	Lighting	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded															
1	Inadequate - accommodation offices	1 - Sight Harm	0 - Zero Effect	OWH	Workstation Layout	Work Area Inspections												
2	Workstations - office windows/cleaning areas	1 - Sight Harm	0 - Zero Effect	OWH														
3	Workstations - cold rooms	1 - Sight Harm	0 - Zero Effect	OWH														
4	Workstations - raw cables	1 - Sight Harm	0 - Zero Effect	OWH														
5	Workstations - sitting comfort and radio room	1 - Sight Harm	0 - Zero Effect	OWH														
6	Workstations - office cabin	1 - Sight Harm	0 - Zero Effect	OWH														
7	Workstations - hybrid offices	1 - Sight Harm	0 - Zero Effect	OWH														
8	Workstations - server test	1 - Sight Harm	0 - Zero Effect	OWH														
25.09	Lighting	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded															
1	Inadequate lighting - confined space entry	3 - Major Harm	0 - Zero Effect	OWH	Portable Lamps	Planned Maintenance (SEMS 6.3)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	3	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0		
2	Inadequate lighting - working machinery	3 - Major Harm	0 - Zero Effect	OWH	Equipment Design and Specifications	Job Safety Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	3	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0		
25.10	Incompatible controls	Top Event = Personnel exposure	Outcomes = Human error															
1	No source identified	-	-	-														
25.11	Awarded location at workplaces and machinery	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded															
1	Awarded workspaces - confined space entry	3 - Major Harm	0 - Zero Effect	OWH	Job Safety Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	3	B - Has occurred in industry	B3	0	B - Has occurred in industry	B0		
2	Awarded workspaces - origin bottom and midsection	3 - Major Harm	0 - Zero Effect	OWH														
25.12	Mismatch of work to cognitive abilities	Top Event = Personnel exposure	Outcomes = Human error															
1	No source identified	-	-	-														
25.13	Mismatch of work to physical abilities	Top Event = Personnel exposure	Outcomes = Human error															
1	No source identified	-	-	-														
25.14	Long and irregular working hours/births	5 - Major Faults	0 - Zero Effect	OWH	Top Event = Personnel exposure	Outcomes = Human error	Behavior Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	5	A - Never occurred in industry	A5	0	A - Never occurred in industry	A0	
25.15	Poor organization and job design	5 - Major Faults	0 - Zero Effect	OWH	Top Event = Personnel exposure	Outcomes = Human error	Behavior Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	5	A - Never occurred in industry	A5	0	A - Never occurred in industry	A0	
1	Poor organization - operations	5 - Major Faults	0 - Zero Effect	OWH	Top Event = Personnel exposure	Outcomes = Human error	Behavior Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	5	A - Never occurred in industry	A5	0	A - Never occurred in industry	A0	
25.16	Work planning Issues	5 - Major Faults	0 - Zero Effect	OWH	Top Event = Personnel exposure	Outcomes = Human error	Behavior Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	5	A - Never occurred in industry	A5	0	A - Never occurred in industry	A0	
1	Work fatigue issues - ergonomics	5 - Major Faults	0 - Zero Effect	OWH	Top Event = Personnel exposure	Outcomes = Human error	Behavior Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	5	A - Never occurred in industry	A5	0	A - Never occurred in industry	A0	
25.17	Indoor climate (too hot / cold / dry / humid / draught)	Top Event = Personnel exposure	Outcomes = Human error															
1	Living away from family - all operations	3 - Major Harm	0 - Zero Effect	OWH	Top Event = Personnel exposure	Outcomes = Human error	Behavior Analysis (SEMS 3.5)	Facilities/Medical Care (SEMS 6.17)	Emergency Response Manual (SEMS 10.1)	Emergency Crisis and Exercises (SEMS 10.1)	Emergency Response Manual (SEMS 10.1)	3	C - Has occurred in company	C3	0	C - Has occurred in company	C0	
26	Psychological Hazards	Top Event = Personnel exposure	Outcomes = Human error															
26.01	Living on the job / away from family	Top Event = Personnel exposure	Outcomes = Human error															
1	Living away from family - all operations	3 - Major Harm	0 - Zero Effect	OWH	Top Event = Personnel exposure	Outcomes = Human error	Behavior Analysis Program											
26.02	Working and living on a live plant	Top Event = Personnel exposure	Outcomes = Human error															
1	No source identified	-	-	-														
26.03	Post traumatic stress	Top Event = Personnel exposure	Outcomes = Human error															
1	Post traumatic stress - injury accident	3 - Major Harm	0 - Zero Effect	OWH	Top Event = Personnel exposure	Outcomes = Human error	Employee Assistance Program											

# Ocean Scepter Hazard Register

ID	Hazard Source and Hazardous Event	Health & Safety		Worst Case Reasonable Consequence		Administrative	Technical	Recovery Control Measures	Administrative	C	P	Residual Risk
		Outcomes	Environment	Outcomes	Environment							
26.04	Fatigue	Top Event = Personnel exposure	Outcomes = Human error related to accident	Top Event = Personnel exposure	Outcomes = Human error related to accident							
1	Fatigue - drowsed driving	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Human Performance - Human Error			5 - A - Never occurred in industry	A5	0	A - Never occurred in industry
2	Fatigue - excessive working hours	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Human Performance - Human Error			5 - A - Never occurred in industry	A5	0	A - Never occurred in industry
26.05	Shift work	Top Event = Personnel exposure	Outcomes = Human error related to accident	Top Event = Personnel exposure	Outcomes = Human error related to accident							
1	Shift work - all operations	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Human Performance - Human Error			5 - A - Never occurred in industry	A5	0	A - Never occurred in industry
26.06	Peer pressure	Top Event = Personnel exposure	Outcomes = Human error	Top Event = Personnel exposure	Outcomes = Human error							
1	Peer pressure - facility personnel	4 - Single Faulty	0 - Zero Effect	OWH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Human Performance - Human Error			4 - B - Has occurred in industry	B4	0	B - Has occurred in industry
2	Peer pressure - facility personnel	4 - Single Faulty	0 - Zero Effect	OWH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Human Performance - Human Error			4 - B - Has occurred in industry	B4	0	B - Has occurred in industry
27	Security Related Hazards	Top Event = Internal environment	Outcomes = Personnel attacked	Top Event = Internal environment	Outcomes = Personnel attacked							
27.01	Plunder	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Threatening Operating Mode - Loss of Tool Control in Transit			5 - A - Never occurred in industry	A5	0	A - Never occurred in industry
27.02	Assault	Top Event = Internal environment	Outcomes = Personnel attacked	Top Event = Internal environment	Outcomes = Personnel attacked							
1	Personnel assault - facility personnel	3 - Major Harm	0 - Zero Effect	OWH		Behavior Based Safety (OHS) (SEMS 2.1.5) Firewall and Conduct Policy	Facility Medical Care (SEMS 6.1.7) MEDEVAC of Casualties (SEMS 6.7)	Emergency Response Manual (SEMS 10.1) Incident Reporting and Investigation (SEMS 11.0) Whistleblower Protection (SEMS 12.5) Whistleblower to the President	3 - B - Has occurred in industry	B3	0	B - Has occurred in industry
27.03	Sabotage	Top Event = Internal environment	Outcomes = Equipment attacked	Top Event = Internal environment	Outcomes = Equipment attacked							
1	Sabotage - facility personnel	4 - Single Faulty	0 - Zero Effect	OWH		Personnel Supervision	Facility Medical Care (SEMS 6.1.7) MEDEVAC of Casualties (SEMS 6.7)	Emergency Response Manual (SEMS 10.1) Incident Reporting and Investigation (SEMS 11.0) Whistleblower Protection (SEMS 12.5)	4 - B - Has occurred in industry	B4	0	B - Has occurred in industry
27.04	Crisis (military action, civil disturbances, terrorism)											
1	No sources identified	-	-	-	-							
27.05	Theft/pillage											
1	No sources identified	-	-	-	-							
28	Use of Natural Resources	Top Event = Water	Outcomes = None	Top Event = Loss of containment	Outcomes = None							
28.01	Water											
1	No sources identified	-	-	-	-							
28.02	Air											
1	No sources identified	-	-	-	-							
29	Medical	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded							
29.01	Medical unit/trials											
1	Medical unit/trials - personnel presenting health condition	4 - Single Faulty	0 - Zero Effect	OWH	Gymnasium	Fire-Engagement Medical Cleaning/Welfare Program Catering/Welfare Program Medical Learning Module	Facility Medical Care (SEMS 6.1.7) MEDEVAC of Casualties (SEMS 6.7)	Emergency Response Manual (SEMS 10.1) Incident Reporting and Investigation (SEMS 11.0) Whistleblower Protection (SEMS 12.5)	4 - C - Has occurred in company	C4	0	C - Has occurred in company
2	Medical unit/trials - personnel having injury / illness at facility	3 - Major Harm	0 - Zero Effect	OWH					3 - C - Has occurred in company	C3	0	C - Has occurred in company
3	Medical unit/trials - personnel with undetermined/no known medical history	3 - Major Harm	0 - Zero Effect	OWH					3 - C - Has occurred in company	C3	0	C - Has occurred in company
29.02	Motion sickness	Top Event = Personnel exposed	Outcomes = Exposure limit exceeded	Top Event = Personnel exposed	Outcomes = Exposure limit exceeded							
1	Motion sickness - crew change by helicopter	1 - Sight Harm	0 - Zero Effect	OWH	Nutrition Medication				1 - D - Multiple occurrences per year	D1	0	D - Multiple occurrences per year
2	Motion sickness - crew change by boat	1 - Sight Harm	0 - Zero Effect	OWH					1 - D - Multiple occurrences per year	D1	0	D - Multiple occurrences per year
3	Motion sickness - vessel motion during tow	1 - Sight Harm	0 - Zero Effect	OWH					1 - D - Multiple occurrences per year	D1	0	D - Multiple occurrences per year
30	Noise	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded / human error related accident	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded / human error related accident							
30.01	High-level roles											
1	Macromedia - between Roger and crime operator - crew operations	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Decrease Objects At Height - Dropped or Slung Objects from Crane			5 - B - Has occurred in industry	B5	0	B - Has occurred in industry
2	Macromedia - between Roger and crime operator - crew	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dropped Objects at Height - Dropped or Slung Objects from Crane or Crew			5 - B - Has occurred in industry	B5	0	B - Has occurred in industry
3	Macromedia - between HCO and pilot - helicopter operations	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on External Contractors and Other Stakeholders - Large Scale Fire on the Facility			5 - A - Never occurred in industry	A5	0	A - Never occurred in industry
4	Macromedia - engine room	3 - Major Harm	0 - Zero Effect	OWH	Isolated Phone Booths	Job Safety Analysis (JSA) (SEMS 2.1.5) Job Safety Analysis (JSA) (SEMS 6.2.2) Workforce Competency Program (SEMS 7.1)	Facility Medical Care (SEMS 6.1.7) MEDEVAC of Casualties (SEMS 6.7)	Emergency Response Manual (SEMS 10.1) Incident Reporting and Investigation (SEMS 11.0) Whistleblower Protection (SEMS 12.5)	3 - B - Has occurred in industry	B3	0	B - Has occurred in industry
5	Macromedia - laundry/mechanical rooms	3 - Major Harm	0 - Zero Effect	OWH	New Alarm and Remote Light				3 - B - Has occurred in industry	B3	0	B - Has occurred in industry
6	Macromedia - common area	3 - Major Harm	0 - Zero Effect	OWH	Takeoff System				3 - A - Never occurred in industry	A3	0	A - Never occurred in industry
7	Macromedia - emergency generator room	3 - Major Harm	0 - Zero Effect	OWH	Water Supply				3 - A - Never occurred in industry	A3	0	A - Never occurred in industry
30.02	Intrusive noises	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded / human error related accident	Top Event = Personnel exposure	Outcomes = Exposure limit exceeded / human error related accident							
1	Intrusive noise - personnel within accommodation	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Human Performance - Human Error			5 - A - Never occurred in industry	A5	0	A - Never occurred in industry
31	Entrapment	Top Event = Escape impairment	Outcomes = Personnel trapped	Top Event = Escape impairment	Outcomes = Personnel trapped							
31.01	Fire explosion											
1	Personnel trapped fire and smoke - elevated places - crew	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Escape, Evacuation and Rescue Systems - Emergency Escape, Evacuation and Rescue			5 - B - Has occurred in industry	B5	0	B - Has occurred in industry
2	Personnel trapped fire and smoke - elevated places - aircraft	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Escape, Evacuation and Rescue Systems - Emergency Escape, Evacuation and Rescue			5 - B - Has occurred in industry	B5	0	B - Has occurred in industry
3	Personnel trapped fire and smoke - accommodation module	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Escape, Evacuation and Rescue Systems - Emergency Escape, Evacuation and Rescue			5 - B - Has occurred in industry	B5	0	B - Has occurred in industry
4	Personnel trapped fire and smoke - machinery spaces	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Escape, Evacuation and Rescue Systems - Emergency Escape, Evacuation and Rescue			5 - B - Has occurred in industry	B5	0	B - Has occurred in industry
31.02	Mechanical damage	Top Event = Escape impairment	Outcomes = Personnel trapped	Top Event = Escape impairment	Outcomes = Personnel trapped							
1	Personnel trapped mechanical damage - elevated places - crew	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Escape, Evacuation and Rescue Systems - Emergency Escape, Evacuation and Rescue			5 - B - Has occurred in industry	B5	0	B - Has occurred in industry
2	Personnel trapped mechanical damage - elevated places - aircraft	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Escape, Evacuation and Rescue Systems - Emergency Escape, Evacuation and Rescue			5 - B - Has occurred in industry	B5	0	B - Has occurred in industry
3	Personnel trapped mechanical damage - accommodation module	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Escape, Evacuation and Rescue Systems - Emergency Escape, Evacuation and Rescue			5 - B - Has occurred in industry	B5	0	B - Has occurred in industry
4	Personnel trapped mechanical damage - machinery spaces	5 - Multiple Failures	0 - Zero Effect	MH		Refer to M&E: Bottle Analysis - BT1201 - Dependence on Escape, Evacuation and Rescue Systems - Emergency Escape, Evacuation and Rescue			5 - B - Has occurred in industry	B5	0	B - Has occurred in industry

# Ocean Scepter Hazard Register

ID	Hazard Source and Hazardous Event	Worst Case Reasonable Consequence			Preventive Control Measure	Recovery Control Measures			Residual Risk			
		Health & Safety	Environment	Category		Administrative	Technical	Administrative	C	P	Health & Safety	C
5	Personnel injured (mechanical damage) - galley freeze / Miller	4 - Severe Injury	0 - Zero Effect	OWH	Rig Phones Freeze Alert Freeze Device Emergency Release	Fleet Medical Care (SEMS 5.17)	Facilities Emergency Response Program (SEMS 7.1) Emergency Response Manual (SEM 10.10) Incident Reporting and Investigation System (SEMS 11.2) Incident Reporting and Investigation System (SEMS 11.2.2)	4	B - Has occurred in industry	B4	0	B - Has occurred in industry
31.03	Diving	Top Event = Escape Impairment. Outcomes = Personnel tripped										
		No injuries or fatalities	No injuries	-								



Hazard	Top Event
Loss of Containment from Well Test Equipment	Emergency Escape, Evacuation and Rescue Systems
Large Scale Fire on the Facility	Medical Emergency on Facility
Accidental Ignition of Explosives	Extreme Metocean Conditions

## Common Causal or Event Escalation BowTie Models

Loss of Containment from Well Test Equipment	Emergency Escape, Evacuation and Rescue Systems
Large Scale Fire on the Facility	Medical Emergency on Facility
Accidental Ignition of Explosives	Extreme Metocean Conditions
Loss of Containment of Hydrogen Sulphide Gas	
Personnel Exposed to Unsafe Atmosphere	
Personnel Fall	
Dropped or Swinging Objects in Derrick or Cellar Deck	
Dropped or Swinging Objects from Crane	
Collision with Facility	
Loss of Elevated Mode Stability	
Loss of Floating Mode Stability	
Loss of Tow Control in Transit Mode	
Helicopter Unable to Complete Flight to Destination	
Loss of Control Over Helicopter	

Safety	Never occurred in industry	Has occurred in industry	Multiple occurrences per year in company	
			Has occurred in company	per year in company
arm				
arm	1			
arm		1		
fatality				
fatality	23	45		

## Aggregated Environmental Residual Risk Estimate Summary

ment	Never occurred in industry	Has occurred in industry	Multiple occurrences per year in company	
			C	D
fect				
ffect	3	1		
ffect		1		
arm				
ffect	1	2		
		6		
				15

## Hazard: BT.002 Hydrocarbons in Well Test Equipment / Loss of Containment from Well Test Equipment

Risk Type			
Carbon Release on Facility	People	Environment	Environment
Carbon Release on Facility	Environment	People	Environment
Fire and Explosion on Facility	People	Environment	Environment
Fire and Explosion on Facility	Environment	People	Environment
Gas Cloud on Facility	People	Environment	Environment
Gas Cloud on Facility	Environment	Environment	Environment

## **Hazard: BT.003 Other Flammable Materials / Large Scale Fire on the Facility**

Risk Type	Effects of Heat and Smoke	Failure - Loss of Elevated Mode Stability	People	People

**Hazard: BT.004 Explosive Materials / Accidental Ignition of Explosives**

R	Risk Type
ctiles	People

**Hazard: BT.005 Hydrogen Sulphide Gas (H<sub>2</sub>S) / Loss of Containment of Hydrogen Sulphide Gas**

R	Risk Type
ydrogen Sulphide Gas	People

**Hazard: BT.006 Unsafe Atmospheres in Enclosed Spaces / Personnel Exposed to Unsafe Atmosphere**

R	Risk Type
oisoned or Burned	People

**Hazard: BT.007 Personnel Working at Height / Personnel Fall**

R	Risk Type
urface / Casualty Stranded at Height	People
Man Over Board)	People

**Hazard: BT.008 Objects at Height (Drilling Operations) / Dropped or Swinging Objects in Derrick or Cellar Deck**

R	Risk Type
ped / Swinging Object	People
ction Infrastructure Struck by Dropped Object from MODU	People
ction Infrastructure Struck by Dropped Object from MODU	Environment
ture Struck by Dropped Object from MODU	People
ture Struck by Dropped Object from MODU	Environment

Infrastructure Struck by Dropped Object from MODU	People
Infrastructure Struck by Dropped Object from MODU	Environment
Structure Struck by Dropped Object from MODU	People
Structure Struck by Dropped Object from MODU	Environment

### Hazard: BT.010 Other Marine Vessels and Obstacles / Collision with Facility

Risk Type	R
Flooding, Sinking - Loss of Floating Mode Stability	People
Flooding, Sinking - Loss of Floating Mode Stability	Environment
Failure and Failure - Loss of Elevated Mode Stability	People
Failure and Failure - Loss of Elevated Mode Stability	Environment
Loss of Hydrocarbon Containment from Well	People
Loss of Hydrocarbon Containment from Well	Environment

### Hazard: BT.011 Elevated Operating Mode / Loss of Elevated Mode Stability

Risk Type	R
Failure, Collapse and Sinking	People
Loss of Hydrocarbon Containment from Well	People
Loss of Hydrocarbon Containment from Well	Environment

### Hazard: BT.012 Floating Operating Mode / Loss of Floating Mode Stability

Risk Type	R
Sinking, Sinking	People
Sinking, Sinking	Environment

### Hazard: BT.013 Transit Operating Mode / Loss of Tow Control in Transit Mode

Risk Type	R
Tow Vessel or Obstacles	People

Drowning and Hypothermia)

People

Hazard: BT.015 Helicopter Arrival and Departure / Loss of Control Over Helicopter	
R	Risk Type
Ocean near the Facility	People
Ocean near the Facility	Environment
Facility	People
Facility	Environment
Helideck	People
Helideck	Environment

Hazard: BT.016 Dependence on Escape, Evacuation and Rescue Systems / Emergency Escape, Evacuation and Rescue	
R	Risk Type
Evacuate to a Place of Safety During an Emergency	People

Hazard: BT.017 Dependence on Medical Services / Medical Emergency on Facility	
R	Risk Type
Medical Care	People

Hazard: BT.018 Dependence on Environmental Conditions / Extreme Metocean Conditions	
R	Risk Type
Well	People
Well	Environment
ht	People
ects from Crane	People
ability	People


Environment	
People	
Environment	
Environment	
People	

### Hazard: BT.019 Dependence on Equipment / Equipment Failure

Risk Type
Well
Well
ht
ects in Derrick or Cellar Deck
ects from Crane
ability
ability
ility
bility
ansit Mode
ansit Mode
facility
facility

### Hazard: BT.020 Dependence on Human Performance / Human Error

Risk Type
ainment from Well)
' Error (Accidental Ignition of Explosives)
or Swinging Objects)
apped or Swinging Objects)
ed or Swinging Objects)



People  
Environment

ator (Loss Of Hydrocarbon Containment From Well Test Equipment)  
ator (Loss Of Hydrocarbon Containment From Well Test Equipment)

## in Well Test Equipment // Loss of Containment from Well Test Equipment

ile Materials // Large Scale Fire on the Facility .....

rials // Accidental Ignition of Explosives .....

hride Gas (H<sub>2</sub>S) // Loss of Containment of Hydrogen Sulphide Gas .....

heres in Enclosed Spaces // Personnel Exposed to Unsafe Atmosphere .....

king at Height // Personnel Fall .....

ht (Drilling Operations) // Dropped or Swinging Objects in Derrick or Cellar Deck .....

ht (Crane Operations) // Dropped or Swinging Objects from Crane .....

essels and Obstacles // Collision with Facility .....

itting Mode // Loss of Elevated Mode Stability .....

ing Mode // Loss of Floating Mode Stability .....

ng Mode // Loss of Tow Control in Transit Mode .....

ansit // Helicopter Unable to Complete Flight to Destination .....

al and Departure // Loss of Control Over Helicopter .....

Escape, Evacuation and Rescue Systems // Emergency Escape, Evacuation and Rescue .....

Medical Services // Medical Emergency on Facility .....

Environmental Conditions // Extreme Metocean Conditions .....

Equipment // Equipment Failure .....

Human Performance // Human Error .....



